AMACON

LIVE WELL"

Location

## 

Eve - Tower: 1 - Unit: 3005 3005 - 3515 Kariya

 Closing Date
 0000

 Date
 10Feb09

Contact Name(s)

Contact Telephone# Company: Attention: Telephone: Fax: Rupali Dalvi and Sandeep Dalyi

Amacon Service Carlos Bravo (905) 848-2827

From: Warranty Services Department - Head Office

Please complete the following items:			
Deliciency Liste /			
Number /		Appointment  Date/Time	Notes
9892 / LYING/DINING ROOM- WINDOWS-ALUMINUM scratched, see tape		Date: 18th	
9893 VING/DINING ROOM- WALLS-mark on back wall facing windows, see tape			
9894 LIWING/DINING ROOM- WALLS: 1-marks, left wall, see tape	V		
9895 / VIVING/DINING ROOM- WALLS: 2-marks right wall, see tape			
9896 JUEST BEDROOM 1- ELECTRICAL/LIGHTING-outlet cover missing right wall, see tape			
9897 OUEST BEDROOM 1- WINDOWS-scratches on ALUMINUM, see tape			
9898 MASTER BEDROOM- WALLS-marks, left wall, see tape	V		
9899 MASTER BEDROOM- WALLS: 1-chips in baseboard, left wall, see tape	V		
9900 MASTER BEDROOM- WALLS: 2-j-mold around windows cracked, see tape			
9901 ASTER BEDROOM- WALLS: 3-crack at either end of window sill, see tape			
9902 MASTER BEDROOM- WALLS: 4-drywall dented in front of window, right wall, see tape			
9903 MASTER BEDROOM- WALLS: S-baseboards scratched, see tape	1	<del>  </del>	
9904 MASTER BEDROOM- FLOORING-CLEAN CARPET	7		
9906 MASTER BEDROOM- CLOSET-clean carpet	V		
9907 MASTER BEDROOM- CLOSET: 1-hole in back wall left closet, see tape			
9908 MAIN BATHROOM-TUB-silicone around showerhead, tap, faucet, see tape	7.		
9909 V SUITE BATHROOM- WALLS-crack along right side of vanity, see tape	7		
9910 VINSUITE BATHROOM- DOORS-excessive gaps top corners outside casing, see taoe	<b>V</b>		
9911 ACMSUITE BATHROOM-DOORS: 1-excessive gap inside top corners of casing, see tape	7		
9912 PNSUITE BATHROOM-DOORS: 2-gap to right of door by tile, see tape	1		
9913 PMSUTTE BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	~		
9914 YY SUITE BATHROOM-TUB: 1-mark on 6th tile from ceiling, rear end of tub, see tape	<b>I</b>		-
9917 CMSUITE BATHROOM-SINK-caulking top lip of sink, see tape	7		
9920 PASUITE BATHROOM- VANITY CABINETC: 2-silicone to right of mirror, see tape	1		
9922 VENSUITE BATHROOM-ELECTRICAL/LIGHTING-BULBS BURNED OUT	J,		
9925 KITCHEN- CABINETS: 2-marks on side panel to right of window over sink, see tape	$\overline{}$		
9935 KATCHEN- APPLIANCE-diSHWASHER not installed properly and kickplate missing	حد	CALL	WHIRLPOOL
9936 / KATCHEN- WINDOWS-excessive caulking right side of window over sink, see tape	V		
9937 KNCHEN- BACKSPLASH-grout on right end of window sill over sink, see tape			
9938 KINCHEN- WALLS-DRYWALL DENTED to left of wundow over sink, see tape	V		
9939 KIN OHEN- WALLS: 1-J-mold right side of window over sink cracked at wall, see tape	\\ \tag{7}		
9940 KYTCHEN- WALLS: 2-crack along left side of window, see tape		i	
9942 / I.AUNDRY CLOSET- WALLS-hole by water shut off, see tape	7	i	

Date Completed: FEBCUARY 11,09

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointmen you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

[Kallure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

 $\frac{\text{Back-Forms Meinu}}{\text{9892/9893/9894/9895/9896/9897/9898/9899/9900/9901/9902/9903/9904/9906/9907/9908/9909/9910/9911/9912/9913/9914/9917/9920/9922/9925/9935/9936/9937/9938/9939/9940/9942}{\text{Eve Ph 1 Lot 3005}}$