AMACON

Warranty Services Work Order Phone: (905) 848-2069 Fax:(905) 848-2827

LIVE WELL

Eve - Tower: 1 - Unit: 311

311 - 3515 Kariya 0000

Closing Date Date Contact Name(s) Contact Telephone#

Location

11Feb09 Victor Tchor

Company: Attention: Telephone:

Amacon Service Carlos Bravo

Fax: (905) 848-2827

Warranty Services Department - Head Office From:

Please	complete the following items:			
Deficiency Number	lssuc		Appointment Date/Time	Notes
10582	FOYER / ENTRY- WALLS-mark on wall to left of closet, see tape			
10585	POYER / ENTRY- DOORS-door scratched and point drips, see tape	V		Kome cote topano
10584	FOYER / ENTRY- CLOSET-access panel not flush, see tape	V		,
10589	INVING/DINING ROOM- WINDOWS-ALUMINUM dented to left of sliding, see tape	X		Kome cote topani Aluminam realine
10590	LIVING/DINING ROOM- WINDOWS: 1-caukling cracked and holes along bottom window edge,	/		
10591	LIVING/DINING ROOM- WINDOWS: 2-caulking cracked along balcony door threshold, see tape	4		
10000	LIVING/DINING ROOM- CEILING-gaps along edges at walls	×		stucco
18593	LIVING/DINING ROOM- CEILING: 1-scratch in front of bathroom			Stuko
10594	LIVING/DINING ROOM- CEILING: 2-scratch/dent to right of light canopy, see tape	X		Stuck 0
10595	VIVING/DINING ROOM- WALLS-finish around thermostat is rough, see tape			
10596	MVING/DINING ROOM- WALLS: 1-left wall is dirty and patchy, see tape			
10597 🗸	VIVING/DINING ROOM-WALLS: 2-DRYWALL DENTED to left of balcony door, see tape			
10598	ZIVING/DINING ROOM- WALLS: 3-J-mold cracked to left and right of window, see tape			
	ZIVING/DINING ROOM- WALLS: 4-J-mold cracked to right of balcony door, see tape			
10600	MASTER BEDROOM- WALLS-DRYWALL rough along left bulkhead, see tape			
	MASTER BEDROOM- WALLS: 1-baseboard chipped to right of window, see tape			
	MASTER BEDROOM- WALLS: 3-discoloration along bulkhead, right sude		4	Stucko
10603	MASTER BEDROOM- WALLS: 2-paint on window frame, top right corner			
10604	MASTER BEDROOM- CEILING-holes around speaker, see tape	X		Stucko
10605	MASTER BEDROOM- CEILING: 1-corner top right of window not finished properly	×		Stucko
10606 🗸	MASTER BEDROOM-ELECTRICAL/LIGHTING-telephone jack not flush, see tape][
	MASTER BEDROOM- WINDOWS-caulking cracked along bottom of windows, see tape	V		
10608	DEN- CEILING-ceiling along bulkhead not properly finished			Stucko
	MAIN BATHROOM- WALLS-wall inside vanity not finished, see tape		<u> </u>	
10610	MAIN BATHROOM- WALLS: 1-mark under light switch, sss tape	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
10611	MAIN BATHROOM- TUB-silicone around showerhead, faucet and tap, see tape	3		
	WITCHEN- WALLS-DRYWALL DENTED at bulkhead above microwave, see tape	1/1		
	LAUNDRY CLOSET- WALLS-cover for water shut off not secured, see tape			

Date Completed:	FEB.	12/09	ì
· · · · · ·			Г

Amacon Customer Care Signature: MENAN SONSK i

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

1D# 10582/10583/10584/10589/10590/10591/10592/10593/10594/10595/10596/10597/10598/10599/10600/10601/10602/10603/10604/10605/10606/10607/10608/10609/10611/10618/10619 Eve Ph 1 Lot 311