

Grahme Walsh

From: Jim Hill [jimh@allanwindows.com]
Sent: February-06-12 8:01 PM
To: Sandra Valencia; Grahme Walsh; Mark Fritz
Subject: Elle
Attachments: IMG00335-20120127-0925.jpg; IMG00331-20120127-0921.jpg;
IMG00332-20120127-0921.jpg; IMG00333-20120127-0922.jpg

Re Jan 27/12

209 Bdrm NE at corner of window bottom cold removed s/u stop drill hole pump foam spray till it came out under curb flashing outside. This detail outside balcony, curb, flashing, all end at m/f bypass.

3206 Vent keeper was hitting frame

Reset mandoor frame, keeper and dead bolt hole

1110 said lots of condensation everything was dry, heavy drapes, furniture against windows see photo's, this is 2nd time to check for same problem

2706 s/u is a heat break

Inspection Jan 27/2012

209

3206

1110 - see ATTACHED comments and pictures

Elle ^{upload}
to
pics

1110 Jan 20/2012
Bedroom
Heavy draps



1110 Elle - Jan 27 / 2012



2002/42440-0111-2012



Elle - Jan 27/2017

1110

