

## **Quality Control-WEB**



Vendor / Builder # Enrollment # 2271192

Purchaser Name: Legal Address: 1 Concord CityPlace Way, Suite

1606

Project: Concord Adex Developments Corp.

Plan #:

Lot / Phase #: 1606 / TOWER A

Inspector: Ali Ghazanchaie Municiaplity:

Inspection Date: May 16, 2025

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace

**Phone Res:** 

**Phone Bus:** 

**Closing Date:** 

- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER / ENTRY	
WALLS	 
Deficiency: TOUCH UP 2 MARKED SPOTS - BELOW RECEPTACLE UNDER ALARM KEY PAD / ACROSS LAUNDRY ROOM / RIGHT OF MAIN BATHROOM ENTRANCE	
Pictures: No Pictures for this deficiency	
CLOSET	 
Deficiency: TOP EDGE OF CLOSET DOOR CHIPPED	
Pictures: No Pictures for this deficiency	
DOORS	 
Deficiency: RIGHT SUITE ENTRY DOOR FRAME CHIPPED ABOVE LOCK	
Pictures: No Pictures for this deficiency	
CEILING	 
Deficiency: TOUCH UP IN FRONT OF LAUNDRY ROOM	
Pictures: No Pictures for this deficiency	
LAUNDRY CLOSET	
NOTE	
NOTE	 
Deficiency: REMOVE PAINT OFF FLOOR DRAIN	
Pictures: No Pictures for this deficiency	
DOORS	 
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures:	
DOORS Deficiency:	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency  MAIN BATHROOM	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency  MAIN BATHROOM  FLOORING  Deficiency:	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency  MAIN BATHROOM  FLOORING  Deficiency: T - CAP SCRATCHED / LOOSE  Pictures:	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency  MAIN BATHROOM  FLOORING  Deficiency: T - CAP SCRATCHED / LOOSE  Pictures: No Pictures for this deficiency	
DOORS  Deficiency: BOTTOM EDGE OF DOOR CHIPPED  Pictures: No Pictures for this deficiency  MAIN BATHROOM  FLOORING  Deficiency: T - CAP SCRATCHED / LOOSE  Pictures: No Pictures for this deficiency  CEILING  Deficiency:	

DEN			
DEN			
FLOORING			
Deficiency: GAP ALONG BASEBOARD UNDER PHONE JACK AREA			
Pictures: No Pictures for this deficiency			
WALLS			
<b>Deficiency:</b> TOUCH UP NORTH WALL AT MARKED SPOTS			
Pictures: No Pictures for this deficiency			
KITCHEN			
LOWER CABINETS			
Deficiency: BOTTOM OF FILLER PANEL LEFT OF FRIDGE CHIPPED	Deficiency: MULTIPLE STAINS ON KICK PLATE / LOOSE	Deficiency: BOTH SINK LOWER DOORS SO	RATCHED
Pictures: No Pictures for this deficiency	Pictures: No Pictures for this deficiency	Pictures: No Pictures for this deficiency	
UPPER CABINETS			
Deficiency: END UPPER DOOR RIGHT OF SINK SCRATCHED			
Pictures: No Pictures for this deficiency			
ELECTRICAL/LIGHTING			
Deficiency: UNDER MOUNT CABINET LIGHT NOT WORKING			
Pictures: No Pictures for this deficiency			
WALLS			
Deficiency: TOUCH UP LEFT OF FRIDGE AT CEILING			
Pictures: No Pictures for this deficiency			
APPLIANCE			
Deficiency: RIGHT BASE OF OVEN HANDLE SCRATCHED			
Pictures: No Pictures for this deficiency			
SINK			
Deficiency: SCRATCHED			
Pictures: No Pictures for this deficiency			

LIVING/DINING ROOM		
WALLS		
Deficiency: TOUCH UP ABOVE LIGHT SWITCH - PHONE JACK AND RECEPTACLE AREA		
Pictures: No Pictures for this deficiency		
WINDOWS		
Deficiency: SCREEN SLIDER NOT CATCHING LOCK PLATE		
Pictures: No Pictures for this deficiency		
MASTER BEDROOM		
MASTER BEDROOM  WALLS  Deficiency: TOUCH UP BOTH SIDES OF BREAKER PANEL / ABOVE LEFT BLIND		
WALLS  Deficiency: TOUCH UP BOTH SIDES OF BREAKER PANEL / ABOVE		
WALLS  Deficiency: TOUCH UP BOTH SIDES OF BREAKER PANEL / ABOVE LEFT BLIND  Pictures:		
WALLS Deficiency: OUCH UP BOTH SIDES OF BREAKER PANEL / ABOVE LEFT BLIND Pictures: lo Pictures for this deficiency		

	ECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER AS A REFERENCE FOR FUTURE WARRANTY REQUESTS
* Purchasers or owners who intend to des to the vendor/builder authorizing the design	signate someone to conduct the PDI in their place should ensure they provide written authority
to the vendor/builder authorizing the design	griate to sign this form on their benail.
	O.B unsold
Builder Representative	Purchaser
Designate's Name(please print)	Designate's Signature
I the homeowner, confirm that all repair w	ork listed will be completed
O.B unsold	

Date

Purchaser