

Soil Engineers Ltd.

CONSULTING ENGINEERS

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

TEL: (705) 684-4242 FAX: (705) 684-8522 GRAVENHURST NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 TEL: (905) 440-2040 FAX: (905) 725-1315 OSHAWA MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 TEL: (705) 721-7863 FAX: (705) 721-7864 BARRIE

Inspection No.

Lot 34 (Left & Right) and Lot 35 (Left & Right) Zenith Avenue

- The inspected footing subgrade is capable of sustaining a Maximum Allowable Soil Pressure of 150 kPa.
- Two 15-mm steel reinforcing bars have been placed continuously in the strip footings.
- placed continuously in the upper section of the foundation walls and must be inspected Two 15-mm steel reinforcing bars must be by Soil Engineers Ltd.
- column pads of the dwellings are in general conformance with the approved permit The layout, size of strip footings and drawing.

SOIL ENGINEER STOOM OF THE STOO ORNANO ្វ 100 July 100 a, Dennis] DL:dd

Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315

TEL: (905) 777-7956 FAX: (905) 542-2769 HAMILTON

REFERENCE NO. 1608-C052

DATE: October 24, 2016

PROJECT

Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive Residential Subdivision City of Vaughan

JOB DESCRIPTION:

Footing Subgrade/Steel Reinforcing Bar Inspection

DATE OF INSPECTION: October 14, 2016

INSPECTOR: Jalal Fahimi, C.E.T

DESIGNED SOIL PRESSURE:

SOIL PRESSURE FOR INSPECTED SUBGRADE: RECOMMENDED MAXIMUM ALLOWABLE 150 kPa

AS-BUILT ELEVATION:

As recorded by site superintendent

WATER CONDITION:

Moist

DESCRIPTION OF INSPECTED SUBGRADE: Compacted earth fill

METHOD OF INSPECTION:

Rod probe and visual

Approved for 150 kPa

<u>S</u>UBGRADE:

GIVEN TO:

Bruno

(05/91)The footings and foundation walls must be protected against frost action at all times. (05/91 1 kPa = 20.89 psf



Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864 MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315 NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522 PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315 HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 106

Lot 14 – Cranbrook Crescent Lot 35 (Right) – Zenith Avenue

- Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.

SOIL ENGINEERS LTD.

Dennis Lai, P.Eng. DL:vk



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

DATE: January 5, 2017

PROJECT:

Residential Subdivision
Gold Park Homes at Kleinburg Glen
Baron Street and Algoma Drive
Cit of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: November 9, 2016.

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE:

AS-BUILT ELEVATION:

WATER CONDITION:

DESCRIPTION OF INSPECTED SUBGRADE:

METHOD OF INSPECTION:

Visual

SUBGRADE:

GIVEN TO:

Bruno

1 kPa = 20.89 psf

The footings and foundation walls must be protected against frost action at all times.