



# Soil Engineers Ltd.

CONSULTING ENGINEERS

**GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE**

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

**BARRIE**  
TEL: (705) 721-7863  
FAX: (705) 721-7864

**MISSISSAUGA**  
TEL: (905) 542-7605  
FAX: (905) 542-2769

**OSHAWA**  
TEL: (905) 440-2040  
FAX: (905) 725-1315

**NEWMARKET**  
TEL: (905) 853-0647  
FAX: (416) 754-8516

**GRAVENHURST**  
TEL: (705) 684-4242  
FAX: (705) 684-8522

**PETERBOROUGH**  
TEL: (705) 748-0576  
FAX: (905) 725-1315

**HAMILTON**  
TEL: (905) 777-7956  
FAX: (905) 542-2769


## INSPECTED LOT:

Lot 65 – Roulette Crescent  
Building Permit No.: 16-146741

## Notes:

1. The inspected footing subgrade consisting of stiff to very stiff silty clay till is suitable for normal house footing construction.
2. Footing adjacent to the easement at Lot 88 was founded below the invert of the storm pipe.

## **SOIL ENGINEERS LTD.**



Benjamin Lee, P. Eng.  
BL/IH:nj

Original to: Fieldwalk Investments Inc.  
Attn: Ms. Jennelle Ramrattan

REFERENCE NO.: 1604-C169.25

DATE: November 4, 2016

## PROJECT:

Goldpark Homes at Mt. Pleasant  
Plan No. 43M-2005  
City of Brampton

## JOB DESCRIPTION:

Footing Subgrade Inspection

DATE OF INSPECTION: October 7, 2016

INSPECTOR: Ibrahim Hajjaj

DESIGN SOIL PRESSURE: -

RECOMMENDED MAXIMUM ALLOWABLE  
SOIL PRESSURE FOR INSPECTED SUBGRADE:  
150 kPa

## AS-BUILT ELEVATION:

As recorded by the Site Superintendent

WATER CONDITION: Moist

## DESCRIPTION OF INSPECTED SUBGRADE:

Stiff to Very Stiff Silty Clay Till

## METHOD OF INSPECTION:

Rod Probe and Visual

SUBGRADE: See Notes

GIVEN TO: Hand-written copy given on site

1 kPa = 20.89 psf

The footings and foundation walls must be protected  
against frost action at all times.

(05/91)