lake inti



PDI Page 1 of 1



Vendor/Builder# Purchaser Name :

34234

Wesley & Melinda Bobbie

Phone Res : Phone Bus : (705) 524-5654

Closing Date: Inspector:

2011-12-15 Bruno Tidd Euroliment# Legal Address:

Municiantity:

DLS[19] Pratt Hansen Group Project: Plao #: Lot / Phase #:

41104 / Building41

1748673

Inspection Date: 11 Dec 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
 Flooring (hardwood, viryl, ceramic tiles, carpeting)
 Interior finished and trim carpentry


- · Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door
- · Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions pennit

Also list here anything that can't be assessed because for example is dirty or inaccessible,

GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 3:00 P.M. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. SCREENS AND CRARKS MISSING FROM WINOWS. MIRAORS WERE INSTALLED IN BATHROOMS. SHOULD NOT HAVE BEEN NOTE: INSTALLED. HARDWOOD FLOOR DIRTY. MASTER ENSUITE BATH DOOR RUBS ON FRAME. **ELECTRICAL/LIGHTING** COVER PLATE MISSING ON CEILING. MASTER BEDROOM HARDWOOD HAS A LOT OF MOVEMENT NEXT TO WINDOW. FLOORING HARDWOOD MOVES THROUGHOUT THE ROOM VERY EMEVEN. BEDROOM #2 FLOORING HARDWOOD SCRATCHED WHERE MARKED NEAR WINDOW. WINDOWS CRACKED WINDOW ON LEFT SIDE. MAIN BATHROOM DOOR DOES NOT CLOSE PROPERLY. SHOWER ENCLOSURE DOOR NOT INSTALLED ON SHOWER ENCLOSURE. FÖYER/HALL CERAMIC GAP DETWEEN FLOOR AND TRIM NEXT TO CLOSET FLOORING ENTRY DOOR. GROOT REQUIRED. LIVING ROOM FLOORING HARDWOOD SCRATCHED IN AREAS WHERE MARKED. COVER PLATE FOR CABLE OFFICE NEXT TO FURNACE CLOSET BLECTRICAL/LIGHTING GARDEN/PATIO DOORS NOTE GLASS BROKEN ON LEFT PANEL EXTERIOR OF PATIO DOOR. KITCHEN CABINETS ALL DOORS MEED ADJUSTING, GAPS BETWEEN DOORS. CAULKING AT COUNTER AND WWALL OVER DISHWASHER COUNTERTOPS OPENING. RECEIVAD DEC 1.2.2011 7.1400-71100



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RIPOSSESSION IT WILL BE USED AS A REFERENCE FOR FIFTURE ** Purchasers or owners who intend to designate someone to conduct the authorizing the designate to sign this form on their behalf. Builder Representative	WARRANTY REQUESTS	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purchaser	Date

31001-PDIF-01,01