

PDI Page 1 of 1



Purchaser Name:

Brian Duval and Amanda Duval

Phone Res: Phone Bus: (705) 735-2697

Closing Date: Inspector:

2013-06-13 Bruno Tidd Enrollment# Legal Address: Project:

Municiaplity:

DES[19] Pratt Hansen Group

Plan #: Lot / Phase #:

43307 / Building43

Inspection Date: 3 Jun 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following: **OPERATING CONDITION**

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

- Hot water heater, if provided (not rental)
- · Exterior finished, driveways, walkways, decks and landscaping Also list here anything that can't be assessed because for example is dirty or inaccessible.
- Windows, interior and exterior doors including garage overhead doors, door locks
- · Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating systemHot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS INSPECTION START TIME INSPECTION STARTED AT 1:12 P.M. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. FRONT DOOR NEEDS PAINTING. ROUGH FINISH AROUND THE NUMBER 7. PURCHASER IS NOT PLEASED WITH CLEANING JOB. GLUE NOTE: ON COUNTERTOPS AND SUBSTANCE ON FLOORS NOT REMOVED. NEW TELEPHONE NUMBER 705-627-1324 MASTER ENSUITE BATH SCRATCHED COUNTERTOP TO LEFT OF SINK. COUNTERTOPS ELECTRICAL/LIGHTING FAN DOES NOT SEEM TO WORKING PROPERLY BEDROOM #2 PAINT SECOND COAT ON TRIM FOR CLOSET ENDS BASE TRIM. NOTE MAIN BATHROOM ROUGH WALL BEHIND TOILET APPEARS TO HAVE BEEN SANDED WALLS ROUGHLY AND PAINTED OVER. LIVING ROOM LAMINATE FLOOR HAS SEVERAL MARKS IN FLOOR. FLOORING HVAC DOOR CHIPPED AT BOTTOM RIGHT CORNER. TRIM COLD AIR RETURN COVER PLATE CROOKED. NOTE: GARDEN/PATIO DOORS HANDLE HAS CHIPS. NOTE: KITCHEN BACKSPLASH HAS SOME AREAS THAT HAS CHIPS WALLS LEFT OF PLUG TO RIGHT OF FRIDGE, GLASS PIECE IS PROTRUDING. CHIPPED PIECE OF GLASS NEXT TO PLUG TO LEFT OF STOVE. CORNER PIECE ON PENINSULA NOT ATTACHED. PLUG UNDER CABINETS PENISULA CROOKED AND HAS CHIPPED EDGES AROUND PLUG. CHECK VALANCE COVER LIGHT SHOWING THROUGH AT TOP OF VALANCE. KICKPLATE TO RIGHT OF FRIDGE NOT ATTACHED.

GLUE AND SCRATCHES ON COUNTERTOP.

SIDING UNDER DECKABOVE HAS DENT AND SCRATCH.

| THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RE POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V * Purchasers or owners who intend to designate someone to conduct the Fauthorizing the designate to sign this form on their behalf. Builder Representative | WARRANTY REGILIESTS 1 | |
|---|-----------------------|---|
| Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed | Designate's Signature | _ |
| | Purchaser Date | |

31001-PDIF-01.01

COUNTERTOPS EXTERIOR

NOTE:

