

Lot 118 (mwi)
SPROUTLE ST
2240



RECEIVED
AUG 10 2009
mwi - 118

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS). Please initial all changes and deletions. As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
<ul style="list-style-type: none"> Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, if provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	<ul style="list-style-type: none"> Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit

Comments Douglas Trumble (Dough)

Item #	Room/Location	Description
1	EXTERIOR.	GRADING, SOO, PAVED DRIVEWAY, MURKAN TOUCH-UPS, SUFFIT, FASCIA, GUTTER POUTS NOT COMPLETED.
2	INTERIOR	TELEPHONE, CABLE, VACUUM PATES NOT INSTALLED.
3	INTERIOR	CLEANING NOT COMPLETED
4	BEDROOM #2	CLOSET SLIDER NOT INSTALLED.
5	STAIRS	RAILING NOT INSTALLED.
6	BASEMENT.	DAMPNESS @ BASE OF EXTERIOR WALLS & PIPES.
7	FURNACE	CAN'T ACCESS FURNACE FILTER - P. RE IN WAY.
8	KITCHEN	BOTTOM DRAWER ON POTS & PANS CABINET RUBBING AGAINST FRIDGE SIDE PANEL.
9	KITCHEN	MALIC ON HANDLE OF KITCHEN SIDE DOOR OR ABOVE SIDE CABINET
10	KITCHEN	SCRATCH IN LEFT DOOR IN ABOVE SIDE CABINET
11	EXTERIOR	TEMP. RAILING @ PORCH & MISSING PILLAR.
12	WALKWAY	PAVING STONE CRACKED
13	PORCH BASE	MORTAR MISSING BETWEEN BRICKS
14	EXTERIOR	BLACK PLASTIC TO BE TRIMMED ON WEST WALL
15	EXTERIOR-Foundation	CUSTOMER CONCERNED ABOUT CRACK@ BASE OF MAIN DOOR FROM GARAGE & AT TOP IN FOUNDATION.
16	IN GARAGE	MAIN DOOR TO EXTERIOR - TRIM INCOMPLETE
17	GARAGE	GAS LINE BRACKETS NOT SERVED
18	GARAGE DOOR - CAULKING	NEEDED & TRIM BOARD VERY ROUGH.
19	EXTERIOR PAN	2 (TWO) SCREWS MISSING
20	BASEMENT	CUSTOMER CONCERNED ABOUT CRACK BY MAIN DRAIN
21	ATTIC / DRY	- PAINT NEEDED
22	ENSUITE	DOOR HITS TOWEL RACK NOT DOOR STOP.
23	MASTER BEDRM.	ANGLED WALL - JOINT TAPE VISIBLE.
24	MAIN BATH	Linen closet missing shelves
25	KITCHEN	UPPER LEFT DRAWER IN POTS & PAN DRAWER RUBBING COUNTERTOP
26	KITCHEN	CUSTOMER CONCERNED ABOUT PLATE PROTRUDING INTO DISHWASHER SPACE.
27	PATIO SLIDER	CAULKING - OVER CAULKED
28	TERMOSTAT	NO INSTRUCTION MANUAL & NOT SECURE TO WALL.