

Customer Care Field Report

Case Reference and Task No. 27a22a74					2022-02-09	
Completed ☒	Return Visit Required ☐	New Issues Reported ☐	Reschedule Required ☐	Parts Only Required ☐		
Technician Name Sun Head			Secondary Technician			
Owner Information						
First and Last Name Zancor			Primary Phone:		Secondary Phone:	
Address Lot 35			Lot Number:		City:	
Courtesy Call and Sign In/Out						
Time of Sign In at Trailer/Arrival at Site:			Time of Sign Out at Trailer/Departure from Site:			
Time of Courtesy Call:						
Work Performed						
Deficiency Number	Wdw Fail Code	Door Fail Code	Description			Photos Yes / No
1			Adjust front door			☐ ☐
2						☐ ☐
3						☐ ☐
4						☐ ☐
5						☐ ☐
6						☐ ☐
7						☐ ☐
Additional Reports/Forms				Tech Observations / Notes		
Form Name		Yes / No	Form Name		Yes / No	
Stress Crack Report:		☐ ☐	Installation Report:		☐ ☐	
Other Form/Report:		☐ ☐	Air/Water Intrusion Report:		☐ ☐	
Parts and Labour Required for Next Visit:						
Room Location	Description (size, colour, thickness, bar pattern, handing, etc.)					
Job Status						
Return Crew Size Required:		Hours Needed:		Equipment Required:		
Signature: (Person provided site access)			Complete ☒ Incomplete ☐		Date: 2022-02-09	

Numéro de dossier *CIT* #:

27a22a74

Date:

2022-02-09

Propriétaire *Homeowner*:

Lot 35



Waiver (accessibility to JW product)

Date: 2022-02-09
JELD-WEN Claim: 27a22a74
Customer Name: Zancor
Service Address: Lot 35
Room Location:

In order to perform the warranty repair to the JELD-WEN product installed in the location noted above, appropriate access to the window / door is required.

JELD-WEN is not responsible to remove window coverings nor to move furniture or homeowner belongings in order to make the product accessible. However, at your request and in order to proceed with the service call today, JELD-WEN will:

- ☐ Remove window coverings
- ☐ Move household items
- ☐ Make the product accessible by _____

By signing below, you assume all responsibility and your signature below absolves JELD-WEN and its representatives of any claims resulting of the aforementioned accommodations and indicates that you (the homeowner) requests a JW field representative perform the action noted above.

Thank you,
JELD-WEN Customer Care

2022-02-09

Customer Signature

Date

**Propriétaire
Homeowner:**

[illegible]

--

Numéro de dossier Ci 27a22a74

Date: 2022-02-09

Propriétaire Homeowner: Zancor

Type	# Production PR#	# ligne Line#	failure code	description	Qté Qty

Note spécial / Special Note

--	--	--

Rapport Photo/ PICTURE REPORT

Numéro de dossier *CIT #:*

27a22a74

Date:

2022-02-09

Propriétaire *Homeowner:*

Zancor

Rapport Photo/ PICTURE REPORT

Numéro de dossier *CIT #*: 27a22a74

Date: 2022-02-09

Propriétaire *Homeowner*: Zancor



Service Case Autopsy Report Glass Stress Cracks

Reminder to only use 1 form, for every 1 window investigated

Case # 27a22a74

Date of Visit: 2022-02-09

Tech Name Sun Head

Type of Window: _____

G #:


Dual or Tri Pane? _____

Glass Size :


glass OD? _____

Using the pictures below:

- 1) Draw the stress crack on the IGU
- 2) Draw the placement of all shims
- 3) Draw the point of contact of the vinyl to the glass
- 4) Draw hinge placement if a casement window



Ex: diagram with shim, hinge, crack, chip











Please provide some additional information on the window
(Circle the answer that applies)

1) Did the glass seem too tight?	
2) Was there damage to edge of the glass where crack started?	
3) Is there a "bow" in the sash?	
4) Is the grey HB Fuller sealant touching the vinyl?	
5) Is the glass set in crooked with an appearance of an angle?	
6) Is the sash vinyl touching the glass?	
7) Are the IGU lites offset or out of square?	
8) Is there evidence of damage caused by transportation?	

RAPPORT D'INSTALLATION

Install report

 #1 #2 intérieur / Inside extérieur / Outside	 A B C intérieur / Inside extérieur / Outside	 A B C intérieur / Inside extérieur / Outside	 A B
Mesure de coin à coin (équerre) Corner to corner measurement (squareness)	Mesure horizontale (largeur) Horizontal measurements (width)	Mesure verticale (hauteur) Vertical measurements (height)	Aplomb Plumbness
 volet/cadre Sash / Frame intérieur / Inside extérieur / Outside	 volet/cadre Sash / Frame intérieur / Inside extérieur / Outside	 cadre Frame	 volet Sash
Niveau (2 jambages, tête, seuil) cocher les boîtes selon le côté (inscrire mesure) level (2 jambs, head, sill); check boxes as needed (write down measurements)	Courbes des jambages (de côté) cocher les boîtes selon le côté (inscrire mesure) Bowed jambs (sideway); check boxes as needed (write down measurements)	Courbes des jambages Bowed jambs	Courbes des jambages Bowed jambs

Notes :

Appel de service /
CIT # : 27a22a74

Tech: Sun Head

Date: 2022-02-09

Order #: 27a22a74	Site Name: Zancor	Completed by: Sun Head	Date: 2022-02-09
Section I - FALL HAZARD ASSESSMENT CHECKLIST			
The homeowner or designated individual over 18 must be on site during service activities			
1. Can the technician enter the area without restriction and perform work? (If NO contact manager)	☐ Yes	☐ No	
2. Will work from a height greater than 6 feet be required?	☐ Yes	☐ No	
a – Will a ladder be used? (if YES complete Section II)	☐ Yes	☐ No	
b - Will a manlift or scaffolding be required to reach the work area? (if YES complete section III)	☐ Yes	☐ No	
c - Will work be performed off of a roof or other structure*? (if YES complete section IV)	☐ Yes	☐ No	
3. Have slipping and tripping hazards been removed or controlled? (if No complete section V)	☐ Yes	☐ No	
4. Are there specific parking instructions? If yes detail in comments section.	☐ Yes	☐ No	
5. Is the structure built in 1978 or earlier (Lead?) if YES see section V	☐ Yes	☐ No	
6. Structure built before 1980? If Yes, has asbestos survey been completed?	☐ Yes	☐ No	
7. Are materials/ product able to be safely handled by one employee? (if NO see section V)	☐ Yes	☐ No	
8. Does the worksite contain any other recognized safety and/or health hazards, i.e. pets, adverse site conditions, overhead powerlines, etc. ? (if YES complete section V)	☐ Yes	☐ No	
Section II – Ladder Usage Assessment Information			
Initials	Hazard	Remarks/Recommendations	
	Potential fall distance:		
	Area underneath ladder is stable or can be stabilized (check for utility lines)	☐ Yes ☐ No	
	Ladder can be anchored to structure	☐ Yes ☐ No	If "NO" Contact Field Manager
	Location of power lines (Distance to work		
Section III – Manlift/ Scaffolding Usage Information: * Use of Manlift must be approved by Field Manager			
Initials	Condition/ Hazards	Remarks/Recommendations	
	Training is complete (See section VI)	☐ Yes ☐ No	
	Height of work area off ground level:	☐ Yes ☐ No	
	Use of Fall protection (Harness and Lanyard)	☐ Yes ☐ No	
	Location of Power lines (Distance to work		
	Management Approval	☐ Yes ☐ No	
Section IV - Working from Heights/ Roof Assessment Information * Must be approved by Field Manager			
Initials	Condition/ Hazards	Remarks/Recommendations	
	Pitch and type of roof:		
	Potential Fall Distance		
	Type of Fall Protection Needed		
	Management Approval	☐ ☐	
Section V - Additional Recognized Safety Hazards:			
Initials	Condition/ Hazards	Remarks/Recommendations	
	Does the Customer have pets?	☐ Yes ☐ No	
	Lead – painted surfaces flaking, cracked or	☐ Yes ☐ No	Contact Operations Manager
	Site Conditions for product delivery		
	Material / Product Handling Issues		
Section VI - Training requirements (NOTE: If aerial/ man-lifts will be utilized, training must be conducted by the equipment provider. The operator shall utilize and sign the CCWD Training Documentation form and keep on site for the term of the project):			
Initials	Required Training	Completed	
	1. Certified Lift Operator	☐ Yes ☐ No	
	2. Certified scaffolding erector (Have been trained in the use of scaffolding)	☐ Yes ☐ No	
	3. Ladder Safety	☐ Yes ☐ No	

Rapport Photo/ PICTURE REPORT

Numéro de dossier *CIT* #: 27a22a74

Date: 2022-02-09

Propriétaire Homeowner:

Section VII – Site/ Job Specific information

- Scope of work description (Attach Elevation, sketch, or Photo's if applicable):

☐ Approved

AUTHORIZATION

I certify that I have conducted a Worksite Hazard Assessment of the above designated location and have detailed the findings of the assessment on this form.

* Further detailed on attachment: ☐ Yes ☐ No

**** NOTE: The initial assessment was conducted off site. It is the responsibility of the field service technician to ensure, once on site this document is accurate and any changes or additions have been made so the project can be conducted in a safe manner. If work cannot be done in a safe manner the project will not commence and the field service technician shall contact their supervisor to report the unsafe conditions and discuss corrective actions.**

Name: Sun Head

Signature:

Title:

Date: 2022-02-09

Time:

ASSESSMENT FORM RETENTION INFORMATION

ATTACHMENTS

Permanent Retention File:

Location:

☐

*Yes

☐

No

Date Filed: 2022-02-09

Filed By: Sun Head

*See Following Pages

Site Specific Emergency Contact Information:

Type of Agency	Name of Agency	Phone Number
Ugent Care/ Medical Services		
Ambulance		
Fire		
Police		
Gas / Utilities		
Poison Control Center		
Misc		

Submit

Reset