## Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 1

31Mar22	31Mar22	3IMar22	31Mar22	31Mar22	31Mar22	31Mar22	Date Reported
PDI	PDI	PDI	PDI	PDI	PDI	PDI	Type
7	, 0	v	4	ίν	2	-	Number
EXTERIOR- NOTE:-GARAGE DOORS NOT INSTALLED PTEM (1882)	EXTERIOR- NOTE:-GARAGE SLAB NOT COMPLETE	EXTERIOREXTERIOR PAINTING NOT COMPLETE	MASTER ENSUITE BATH- ELECTRICAL/LIGHTING-LIGHT FIXIURES ABOVE SINK TO BE REMOVED AS PER UPGRADES. ROUGH IN ONLY IN BOTH WASHROOMS	MASTER ENSUITE BATH- VANITY CABINETS-SMALL CHIP INSIDE LOWER DRAWER AT VANITY	FOYER/HALL- STAIRS-DENTS ON FIRST TREAD AT STAIRS TO MAIN FLOOR	FOYER/HALL- NOTE:~EXPOSED NAIL AT RISER BELOW NOSING AT STAIRS TO BASEMENT	Deficiency Description
Abbey Overhead Doors Inc. 147057	Toronto Concrete & Drain 147058	Perfect Touch Painting 147056	Mykon Electric North Ltd 147055	New Image Kitchens 147054	Stairfab 147053	Stairfab 147052	Trade Add Assigned Trade
Add	Add	Add	Add	Add	Add	Add	Add Trade
No Appoint.	NoAppoint.	NoAppoint.	NoAppoint,	NoAppoint.	NoAppoint.	Z	Add Appointment Trade Date
		X	<	<		<	Item Completed
S	2		E.	Se Se	9	88	Initial

王
5
Η
ō
9
≦
6
-
53
œ
100
$\rightarrow$
5
53

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Zancor Service Technician: