Customer Care Field Report rapport de service Case Reference No/ No de dossier.: 13a22a28 Date: 2022-06-06 Work Requested Completed /travaux **Work Requested NOT** See Internal Comments On The Second Page/voir CCR Name/ nom du conseiller: Completed/ travaux demandés complétés commentaires pour usage internes sur la deuxième MLOCSIN demandée non complétés Technician Name/nom du technicien: Secondary Technician/ nom du deuxième technicien: Sun Head Owner Information/information du client First and last Name/ nom du client: Primary Phone/ téléphone primaire: Secondary Phone/ téléphone secondaire: Zancor City/ Ville: Address: Lot 10 Courtesy Call and Sign In/Out/ appel de courtoisie et arriver, départ du site Time of Sign In at Trailer/heure d'arrivé sur le site: Time of Sign Out at Trailer/heure de Time of Courtesy Call/ heure de l'appel de courtoisie: départ du site: Work Requested/travaux demandés Photos Deficiency #/# Door Fail window Fail Description Yes / No de la déficience Code Code oui/non Work Performed /travaux exécutés Replace front door sweep Skin damaged frame front window Garage man door done by site **Additional Forms/rapports additionnels** Form Name/ nom du rapport No oui/non Comments/commentaires installation report/rapport d'installation Air/Water Intrusion Report/rapport infiltration air/eau Stress Crack Report/rappor de bris thermique Other Form Report /autre rapport Additional Work and Parts Needed For Not Completed Work Requested/ pièces et travaux additionnels pour compléter les travaux requis Room Location/ appartement Description (size,color,thickness,bar pattern,handling,etc./couleur, grandeur,etc...) team Status Return Crew Size Required/ nombre Hours Equipment Required/ équipement requis: Incomplete Complete de techniciens requis pour le retour Needed/ temps requis: Signature: (Person Who Provided Access) Date:

2022-06-06

605001239 Rev. 10/13

commentaires/comments



Waiver (accessibility to JW product)

	Date:	2022-06-06						
	JELD-WEN Claim:	13a22a28 						
	Customer name:	Zancor						
	Service Address:	Lot 10						
	Room Location:							
In order to perform	•	WEN product installed in the lother window/door is required.	ocation noted above,					
homeowner belongings i	JELD-WEN is not responsible to remove window coverings, alarm sensors nor to move furniture or homeowner belongings in order to make the product accessible. However, at your request and in order to proceed with the service call today, JELD-WEN will:							
Remove window	coverings							
Remove alarm se	nsors							
Move household	items							
Make the produc	t accessible by:							
By signing below, you assume all responsibility and your signature below absolves JELD-WEN and its representatives of any claims resulting of the aforementioned accommodations and indicates that you (the homeowner) requests a JW field representative perform the action noted above.								
	Т	hank you						
	JELD-WEI	N Customer Care						
			2022-06-06					
Customer Signa	ature		Date					

enêtres/windows	5							Retour - I	Inventaire	I Return - Inv	entory		Pièces se	ulement / Pa	arts only	
numéro de cas												opriétaire				
Cit Case #:						I	DATE:				Но	meowner:				
							sealed ı	units								
					failure	verre	verre				l.			patron du		
		1	Ligne #	failure description	code de	réel real	visible	Largeur	Hauteur	haut. Sec.	Larg. Sec.	type de carrelage	couleur du carrelage		unit type de	qté th
Style	Туре	PR#	Lighe #	du défaut		galss	glass	Width	Height	Height	Width	Grill Type	Grill Colour	pattern	thermo	S/U Qty
,									J	<u> </u>		- 71		<u>'</u>		,
															-	
			<u> </u>													
			 											 		
						,	window	parts								
					failure	Г		parac								
				failure	code											
01.1	_	55"	Ligne #		de											., .
Style	Туре	PR#	Line#	du défaut	défaut					d	escripti	on				qté qty
		ļ	ļ													
Added Note`s:						1										

	F	Porte /	Doors				Retour - Inventa	aire / Return - Inventory	Pièces seulement / Parts	only
Numéro de dossier C	13a22a28			Da	ite: 2022-0	6-06	Propriétaire Homeo	wner: Zancor		70
				_						
Туре	# Production PR#	# ligne Line#	failure code				des	cription		Qté Qty
										+
										-++
										-+-
										-H
										\perp
Note spécial / Spec	ial Note							.V		
			0							

Rapport Photo/ PICTURE REPORT

Numéro de dossier CIT #:	13a22a28 —————————————————————————————————	Date: 2022-06-06	Propriétaire Homeowner: Zancor

Rapport Photo/ PICTURE REPORT

Numéro de dossier CIT #:	13a22a28 —————————————————————————————————	Date: 2022-06-06	Propriétaire Homeowner: Zancor




Service Case Autopsy Report Glass Stress Cracks

Reminder to only use 1 form, for every 1 window investigated

Case #	13a22a28	Date of Visit:	2022-06-06
		Tech Name	Sun Head
Type of Window:		G #:	
Dual or Tri Pane?		Glass Size :	
		glass OD?	

Using the pictures below:

- 1) Draw the stress crack on the IGU
- 2) Draw the placement of all shims
- 3) Draw the point of contact of the vinyl to the glass
- 4) Draw hinge placement if a casement window



Please provide some additional information on the window (Circle the answer that applies)


1) Did the glass seem too tight?	
2) Was there damage to edge of the glass where crack started?	
3) Is there a "bow" in the sash?	
4) Is the grey HB Fuller sealant touching the vinyl?	
5) Is the glass set in crooked with an appearance of an angle?	
6) Is the sash vinyl touching the glass?	
7) Are the IGU lites offset or out of square?	
8) Is there evidence of damage caused by transportation?	



90, rue Industrielle Saint-Apollinaire (Québec) Canada GOS 2EO 418 881-3974 Tél 418 881-2514 Fax

RAPPORT D'INSTALLATION

Install report





JELD-WEN Customer Support Worksite Hazard Assessment – Form A

Order #:	13a22a28	Site Name:		Co	ompleted by: Sun Head	022-06-06			
	S	ection I - FALL HAZAI	RD ASSI	SSMEN	T CHECKLIST				
	-				on site during service activities				
1. Can th	e technician enter the are					T	Yes		No
2. Will work from a height greater than 6 feet be required?						ŢΕ	Yes		No
a – Will a	ladder be used? (if YES co	omplete Section II)					Yes		No
b - Will a	manlift or scaffolding be r	required to reach the w	ork area	? (if YES	complete section III)		Yes		No
c - Will w	ork be performed off of a	roof or other structure	*? (if YE	S comple	ete section IV)		Yes		No
3. Have sl	ipping and tripping hazard	ls been removed or con	trolled?	(if No co	mplete section V)		Yes		No
	ere specific parking instruc					<u>↓</u>	Yes		No
	tructure built in 1978 or e	'				⊥ <u>L</u>	Yes	┷	No
	re built before 1980? If Ye					<u>↓</u>	Yes	ᄔ	No
	terials/ product able to be					ᅶ	Yes	ᄔ	No
	•	•		ealth haz	ards, i.e. pets, adverse site	lг	☐ Yes	$I \vdash$	l No
	s, overhead powerlines, et		ection V)				_	<u> </u>	-
	I – Ladder Usage Assess	sment Information							
Initials	Hazard				Remarks/Recommendations				
	Potential fall distance:			ı					
	Area underneath ladder		□Yes	Пио					
	be stabilized (check for u				If "NO" Court of Field Manager				
	Ladder can be anchored		Yes	INO	If "NO" Contact Field Manager				
C	Location of power lines (* * * * * * * * * * * * * * * * * * * *						
		g Usage Information:	" Use	oj iviani	lift must be approved by Field Mo	<u>ana</u>	ger		
Initials	Condition/ Hazards		Пу	П.	Remarks/Recommendations				
	Training is complete (See		Yes	∐No					
	Height of work area off		Yes	No					
	Use of Fall protection (H		Yes	∐No					
	Location of Power lines (Distance to work							
	Management Approval	1. / 5. 6.4	Yes		<u> </u>				
		hts/ Roof Assessmen	it Inforr	nation '	* Must be approved by Field Man	age	er		
Initials	Condition/ Hazards		I		Remarks/Recommendations				
	Pitch and type of roof:								
	Potential Fall Distance								
	Type of Fall Protection N	leeded							
	Management Approval								
Section \	V - Additional Recognize	ed Safety Hazards:							
Initials	Condition/ Hazards				Remarks/Recommendations				
	Does the Customer have	•	Yes	∐No					
	Lead – painted surfaces	flaking, cracked or	Yes	□No	Contact Operations Manager				
	Site Conditions for produ	•							
	Material / Product Hand								
Section \	VI - Training requirement	nts (NOTE: If aerial/ n	nan-lifts	will be	utilized, training must be conduct	ed i	by the		
equipme	nt provider. The operat	or shall utilize and sig	gn the C	CWD Tr	aining Documentation form and k	eep	on site	? for	the
term of t	the project):								
Initials	Required Training					Со	mplete	d	
	1. Certified Lift Operator	•					Yes	I .	No
	2. Certified scaffolding e	rector (Have been train	ed in th	e use of	scaffolding)		Yes		No
	3. Ladder Safety		_				Yes		No

	Rapport Photo/ P	PICTURE REPORT			
Numéro de dossier CIT #:	Date: 2022-06-06	Propriétaire Homeowner:	Lot 10		
	-				

Section VII – Site/ Job Specific in	ntormation					
Scope of work description (Attac		oto's if applicable)	:			
Approved	<u>AUTHORIZ</u>	<u>ATION</u>				
I certify that I have conducted a Wor the assessment on this form. ** NOTE: The initial assessment was a this document is accurate and any characteristics.	conducted off site. It is the r anges or additions have bee e project will not commenc	* Further detail esponsibility of the n made so the proje	led on attachm field service te ect can be cond	ent:	No No note on site anner. If wor	
report the unsafe conditions and discu	ss corrective actions.	Signature:				
Name: Sun Head		Signature.				
				r <u></u> .		
Title:		Date: 2022-06-06		Time:		
ASSESSMENT FOI	RM RETENTION INFORMATION	<u>ON</u>		<u>ATTACHMENTS</u>		
Permanent Retention File:	Location:			*Yes	☐ No	
Date Filed: 2022-06-06	Filed By:Sun Hea	d		*See Following P	ages	
Site Specific Emergency Contact	: Information:					
Type of Agency	Name of Ag	ency		Phone Number		
Ugent Care/ Medical Services						
Ambulance						
Fire						
Police						
Gas / Utilities						
Poison Control Center						
Misc						

Safety Form A - PB

Submit

Reset