

Zancor Homes (Parkview) Ltd. Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

**Work Order** 

Closing Date: Address: 27May22

Location: Today's Date: Contact(s):

Now Towns In Brooklin - Phase: 1 - Lot: Unit 63 (Block 10) 25Aug22
Mark, Anson Faria - Cell: (647) 291-7489 - (markfaria20@gmail.com) Carollynn, Gimeno San Jose - (carollynn.sj@gmail.com) markfaria20@gmail.com

Email:

Zancor - Brooklin Warranty Service

Company:
Attention:
Telephone:
Fax:

Please
Complete
the f
allowing
items:

149106		149087		149086		149085	DAI
30-Day		30-Day		30-Day		30-Day	Type Issue
Exterior- General- item 27- balcony- floor- 2nd floor terrace wood	powder room and basement is installed and slanted- svc to measure	Other- General- item 8- landing- wood flooring between	scratched/ peeled off when carpet was installed	Other- General- item #7- wall- bedroom on right side hallway - door frame wall	the door frame and wall scratched, peeled off when carpet was installed	Other- General- item #6- (storage) linen closet on left wall by	Issue
1 all		0	11/1	,	11/2 <		
26Aug22 /am		26Aug22 /am		26Aug22 /am		26Aug22 /am	Appt. Date/Time
	120Ar	KEBOOK FI					Notes
	1	7					

149112	149111	149108	149107	
30-Day	30-Day	30-Day	30-Day	
Exterior- General- item 33- 2nd floor back terrace above exterior sliding doors caulking unfilled areas- svc touch up small area of caulking above door	Exterior- General- item 32- 3rd floor balcony brick/mortar filling at the corner to the right of the balcony has unfilled hole files and nor weep holes	Exterior- General- item 29- caulking/sealant- 2nd floor front balcony above exterior door and side window frame caulking large unfilled areas and mulin	Exterior- General- item 28- balcony- 2nd floor front balcony - right second plank largae crack along wood- normal not warranted	plank decking cracked c3 bends easily when stepped on- Unable to find, svc to inspect
KIT	(1)		( )	(h)
26Aug22	26Aug22 /am	26Aug22 /am	26Aug22 /am	

Date Completed: X

Date Completed: #44 4

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature:
Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

## Outstanding Deficiencies Now Towns In Brooklin - Phase: 1 - Lot: Unit 63 (Block 10)

splintered/cracked  Exterior- General- item 24- porch roofing- dropping and without metal trim- missing
Exterior- General- item 23- balcony- floor- 3rd floor primary/bedroom balcony wood flooring missing nails and wood
Main Bathroom- General- item 20- sink- faucet plug not holding plugged position
Great Room- General- item 19- floor- large long scratch on floor in the middle of the family room- photo send on key pick up
Stairs- General- item 17- stair/step gap on stairs and post at mid way landing of between 1st and 2nd floor as well as between 2nd and 3rd floor
Other- General- item 15- stairs- trimbetween 2nd floor landing and 3rd floor underside- stair trim not the same as trim rest of stair as identified in pdi
4- wood floor gap wood short below
Living Room- General- item #9- window facing the front of the house frame/weather stripping inside chipped
Other- General- item 8- landing- wood flooring between powder room and basement is installed and slanted- svc to measure
Other- General- item #7- wall- bedroom right side hallway - door frame wall scratched/ peeled off when carpet was installed
eneral- item #6- (storage) linen left wall by the door frame and wall l. peeled off when carpet was
Main Bathroom- General- item #4- countertop- main bathroom countertop edge on left side lifting from surface creating gap susceptible to water damage no issue svc to inspect
Main Bathroom- General- Item #3- primary bathroom laminate countertop edge on left side lifting from surface creating gap susceptible to water damages- no issue svc re inspect
Bedroom 2- General- Item #2- sliding door- primary bedroom sliding door left mullin replaced with a dented/cracked mullin
Main Bathroom- General- Item #1- shower-cracked grout in tile with large gaps on floor, along the edges And corners where the floor needs the tiled floor and surrounding tile areas silicone caulking lifted as grout beneath are cracked or have holes/gaps
FOYER/HALL- STAIRS~ADJUST OUTSIDE TRIM LEFT OF STRINGER AT 7TH TREAD AT STAIRS FROM MAIN FLOOR TO 1ST LANDING TO 2ND FLOOR (SLANTED)
BEDROOM #2- FLOORING~CARPET NOT INSTALLED
WINDOWS~LEFT

Homeowner Signature.

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction. 25 12022

Date: 0 25/2000 Zancor Service Technician: