



**Zancor Homes (Parkview) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 25Aug22

**Address:**

**Location:** Now Towns In Brooklin - Phase: 1 - Lot: Unit 56 (Block 9)

**Today's Date:** 23Aug22

**Contact(s):**

**Email:**

**Company:** Medi Group

**Attention:**

**Telephone:** (416) 741-2737

**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
149630	PDI	EXTERIOR- BRICKS-MOTAR REQUIRED ABOVE LENTIL AT MAIN FLOOR BALCONY			

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_  
The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:** Oct. 24/22

**Trade &/or Service Tech.**

**Signature:** [Signature]

**Print Name:** \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

44 - Oct. 24/22

**MEDI GROUP**

BLK 1- UNIT 1

**NORTHSIDE:**

- Replace window sill at garage side where window is close to jogged wall revealing styrofoam inside sill

BLK 1- UNIT 4

**REAR:**

- Repair 3 courses of stove below steel I-BEAM reveals masonry not level at right side & add mortar under steel I-BEAM L/S

BLK 9- UNIT 52

**REAR:**

- Add mortar under steel I-BEAM at L/S

BLK 9- UNIT 54

- Add mortar under steel I-BEAM at R/S (NO INDICATION OF WHERE)

BLK 9- UNIT 55

**FRONT:**

- Pressure wash required for stone and bricks

**REAR:**

- Add mortar under steel I-BEAM at left side

BLK 9- UNIT 56

**REAR:**

- Add mortar under steel I-BEAM at R/S

**\*NOTE: ALL UNITS MUST BE PRESSURE WASHED**



# MEDI GROUP Service

WO Number : **W-084200**WO Date : **20-Oct-2022**Issued To : **ROBERT ULJASZ**Builder : **Zancor****ZAN11**Lot No : **B9-56**Project : **ZANCOR-BROOKLIN TOWNS-3-21**

Model :

Directions : Brooklin /Whitby  
Intersection of Thickson Road and  
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : **Tahoe**

Main Stone :

Accent Brick :

Accent Stone : **Champagne (Chamfer Walling)**

INIT	Item	Work Description	PO	Builder Ref #
✓	1	ADD MORTAR UNDER STEEL I-BEAM AT R/S		ALLAUG0922
✓	2	FRONT COLUMN REMOVE 1 COURSE OF STONE - SEE PHOTO		S-065541
✓	3	COLUMN REQUIRES REPAIRING FROM POSSIBLY BEING STRUCKED - SEE PHOTO		08M101541
✓	4	MORTAR REQUIRED ABOVE LINTIL AT MAIN FLOOR BALCONY - SEE PHOTO		S-065545
				08M101541
				S-065545
				56AUG2322
				S-065740

21 Oct/22

\_\_\_\_\_  
Homeowner Signature\_\_\_\_\_  
Date Completed\_\_\_\_\_  
Site Super Signature\_\_\_\_\_  
Date Completed

Special Notes :

COMPLETED OCT 24 2022


74

24-Oct. 24/20



#3

Blk#9 Units#56 & 57 column requires repairing from possibly being struck:



Oct. 24/22  
-M.



Blk#9 Units#56 & 57 rears remove 1 course from each columns: