

SO - Oct. 24/22
PM

MEDI GROUP

BLK 2- UNIT 9

NORTH SIDE:

- Repair chipped bricks at natural gas steel pipping

BLK 2- UNIT 10

REAR:

- Add mortar at left side for steel I-BEAM

BLK 2- UNIT 11

FRONT:

- Remove residue on stone located on both sides of the front door

BLK 2- UNIT 12

FRONT:

- Remove residue on stone at L/S of front door
- Add mortar at L/S corner at vertical soffit reveals a "void" inside car port

SO - Oct. 24/22
24

MEDI GROUP

BLK 4- UNIT 21

FRONT:

- Replace brick at R/S corner below porch slab

***NOTE: ALL UNITS MUST BE PRESSURE WASHED**

SO - Oct. 24/22
Z1

MEDI GROUP

BLK 10- UNIT 58

- Power wash mud off brick/stone L/S
- Chipped brick by downwipe L/S
- 2 chipped bricks by bell pedestal
- Remove 1 x 4 below stone by metres
- Mortar where steel meets stone @ garage
- Clean stone/brick @ garage

BLK 10- UNIT 60

- Clean mortar splashes @ column
- Mortar splashes on stone above window

BLK 10- UNIT 62

- Clean marks of precast headers over all front windows
- Clean off marks from stone @ garage

BLK 10- UNIT 63

- Chipped sill @ front window ground floor
- Clean all pencil marks precast garage heaters throughout
- Fill mortar @ empty void L/S garage
- Mortar cracked R/S of garage
- Power wash stone / brick @ garage wall R/S
- Remove pencil off front masonry columns

BLK 10- UNIT 64

- Mortar gap where stone meets aluminium - R/S of front door
- Power wash white marks off stone - side of unit
- Mortar cracked @ power by terrace

SO - Oct. 24/22
74

MEDI GROUP

BLK 1- UNIT 1

NORTHSIDE:

- Replace window sill at garage side where window is close to jogged wall revealing styrofoam inside sill

BLK 1- UNIT 4

REAR:

- Repair 3 courses of stone below steel I-BEAM reveals masonry not level at right side & add mortar under steel I-BEAM L/S

BLK 9- UNIT 52

REAR:

- Add mortar under steel I-BEAM at L/S

BLK 9- UNIT 54

- Add mortar under steel I-BEAM at R/S (NO INDICATION OF WHERE)

BLK 9- UNIT 55

FRONT:

- Pressure wash required for stone and bricks

REAR:

- Add mortar under steel I-BEAM at left side

BLK 9- UNIT 56

REAR:

- Add mortar under steel I-BEAM at R/S

***NOTE: ALL UNITS MUST BE PRESSURE WASHED**



MEDI GROUP Service

WO Number : **W-084198**

WO Date : **20-Oct-2022**

Issued To : **ROBERT ULJASZ**

Builder : **Zancor**

ZAN11

Lot No : **B2-12**

Project : **ZANCOR-BROOKLIN TOWNS-3-21**

Model :

Directions : **Brooklin /Whitby**

Intersection of Thickson Road and
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : **Tahoe**

Main Stone :

Accent Brick :

Accent Stone : **Champagne (Chamfer Walling)**

INIT

Item

Work Description

PO

Builder Ref #

1

**ADD MORTAR AT L/S CORNER AT VERTICAL SOFFIT
REVEALS A "VOID" INSIDE CAR PORT**

ALLAUG0922

S-065541

21 Oct/22

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED OCT 24 2022