

Oct. 24/28
241

MEDI GROUP

BLK 1- UNIT 1

NORTHSIDE:

- Replace window sill at garage side where window is close to jogged wall revealing styrofoam inside sill

BLK 1- UNIT 4

REAR:

- Repair 3 courses of stove below steel I-BEAM reveals masonry not level at right side & add mortar under steel I-BEAM L/S

BLK 9- UNIT 52

REAR:

- Add mortar under steel I-BEAM at L/S

BLK 9- UNIT 54

- #1 - Add mortar under steel I-BEAM at R/S (NO INDICATION OF WHERE)

BLK 9- UNIT 55

FRONT:

- Pressure wash required for stone and bricks

REAR:

- Add mortar under steel I-BEAM at left side

BLK 9- UNIT 56

REAR:

- Add mortar under steel I-BEAM at R/S

***NOTE: ALL UNITS MUST BE PRESSURE WASHED**

Oct. 24/22

Del.



Blk#9 Units#54 & 55 front column remove 1 course of stone:



MEDI GROUP Service

WO Number : **W-084202**WO Date : **20-Oct-2022**Issued To : **ROBERT ULJASZ**

Builder : Zancor

ZAN11

Lot No : B9-54

Project : ZANCOR-BROOKLIN TOWNS-3-21

Model :

Directions : Brooklin /Whitby

Intersection of Thickson Road and
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : Tahoe

Main Stone :

Accent Brick :

Accent Stone : Champagne (Chamfer Walling)

INIT	Item	Work Description	PO	Builder Ref #
✓	1	ADD MORTAR UNDER STEEL I-BEAM AT R/S (NO INDICATION OF WHERE)		ALLAUG0922
✓	2	FRONT COLUMN REMOVE 1 COURSE OF STONE - SEE PHOTO		S-065541
				08M101541
				S-065545

21 Oct/22

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED OCT 24 2022