76

Quality Control-WEB



Vendor / Builder #

Purchaser Name: Helena Broad

Phone Res:

Closing Date:

2022-06-02

Phone Bus:

7057180434

Inspector:

Gisella Fiore

Enrollment #

Project:

Legal Address:

Zancor Homes (Wasaga) Ltd.

Plan #:

Lot / Phase #:

152/1

Municiaplity:

Inspection Date: Jan 24, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace

- Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit


KITCHEN

CABINETS

Deficiency:

H.O REQUESTING TO HAVE ELECTRICAL PLUG OUT
BACKSIDE OF IS LANDING FACING BREAKFAST AREAIF NOT POSSIBLE INFRONT OF DISHWASHER 2) CHIP
FILLED RIGHT GABLE NOT ACCEPTED

Pictures:















Deficiency:
ADJUST PLUG ON BREAKFAST WALL AS PER
HOMEOWNER NOT STRAIGHT 2) ADJUST LEFT OUTLET
AT BACKSPLASH WALL

ctures:







ADD-SHELF RED D @ ISLAND

WINDOWS

BEDROOM #2

Deficiency: SCRATCH ON LEFT FIXED GLASS





UPPER HALL

NOTE:

Deficiency:
H.O REQUESTING PAINT TO BE COMPLETED AT UPPER
LOFT CEILING ABOVE BREAKFAST AREA







Deficiency: FILL GAP AT RAILING AT CORNER BELOW RAILINGS WHERE NOSING MEETS RAILING

Pictures:





Deficiency:

H.O REQUESTING FILL GAPS AT RISER AND TREAD AT 4,5,8 STEP TO 2ND FLOOR FROM 1ST LANDING TO 2ND FLOOR 2) FILL GAP AT 1, 2, 6 RISERS AND TREAD AT STAIRS FROM 1ST LANDING TO MAIN FLOOR 3) CRACK ON TREAD BELOW NOSING AT STAIRS FROM 1ST LANDING TO MAIN FLOOR 4, DET ON 2ND TREAD FROM LANDING TO MAIN FLOOR FROM LAUNDRY 5) CRACK ON 4TH TREAD AT STAIRS FROM BASEMENT LANDING TO 1ST LANDING TO 2ND FLOOR







FOYER/HALL

STAIRS

Deficiency:

VARNISH REQUIRED 2 TREAD AT STAIRS FROM 1ST
LANDING TO 2ND FLOOR DUE TO DRIP MARK - BY
PICKET 2) DRIP MARK ON 2ND TREAD AT STAIRS FROM
LAUNDRY TOO MAIN FLOOR BY PICKET VARNISH
REQUIRED











FLOORING

Deficiency: CRACK ON TILE RIGHT OF CRAWL SPACE DOOR AT BASEMENT LANDING



DINING ROOM

TRIM

Deficiency:
H.O REQUESTING TO INSPECT RIGHT AND LEFT
WINDOW BOW IN WALL RIGHT AND LEFT OF FIREPLACE

Pictures:







LAUNDRY ROOM

CABINETS

Deficiency: CRACK ON SIDE SPLASH RIGHT SIDE AT LAUNDRY SINK

Pictures:





EXTERIOR

NOTE:

Pictures:

No Pictures for this deficiency





rjomeowner Signature:

The Homeowner acknowledges and accepts that all initialed work has been completed in a workman like manner to their satisfaction.



The above items were received on this Aday of Annuary, 2023	_N/A_ Other	_N/A_ Recycling and Green Bins	Homeowner Manual (given at PDI)	House and Garage Door Keys	Lot # Site/Phase: Shoreline Point	The items listed below were released to the homeowner(s) of		HOMES	
---	-------------	--------------------------------	---------------------------------	----------------------------	-----------------------------------	---	--	-------	--

Purchaser

Purchaser