Outstanding Deficiencies Caledon Club - Phase: 1 - Lot: 141A

20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	<u>Date</u> Reported
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	Type
had _b	13	hort N	Same Same	10	V	00	7	6	Si .	4	دي	ы	, mad	Number
Main Hall- General-ITEM #14- doors the Zancor: main entrance door is very loose and it can be easily opened-WORKING GOOD 156350 Add 12May23	Basement- General- Item #13- floor- visible big crack on the floor that needs to be filled in the room on the left- N/A NOT WIDER THEN 4MM	Basement- General- item #12- unfinished area- drywall insulation has many bugs it needs to be replaced asap before the cover entire house- REMOVE BUGS AT INSULATION	Main Bathroom- General-Item #11 toilet- the toilet stool is shaky/loose needs to be rightened-SVC TO CAULK BASE	Basement- General- Item #10- some drawers are not smooth and some different color stains, need to be checked-SEND PHOTO UNABLE TO FIND	Dining Room- General- Item #9- ceiling- paint dent on the ceiling near the dining and stairs to the basement paint is different then rest of the house- CELING TOUCHED UP WITH WALL PAINT	Main Bathroom- General- Item #8- very low water flow from low bathrooms shower heads	Main Bathroom- General- Item #7- no water in master bedroom water tub-COMPLETE	Master Bedroom- General- Item #6- carpet is a bit bumpy near the washroom entrance (in master bedroom	Kitchen- General- item #5- cabinets kitchen cabinets 1-2 are not aligned properly	Main Bathroom- General- Item #4- electrical- pot lights have come outside from ceilings in two bathrooms- SECURE NOT FLUSH	Laundry Room- General- Item #3- plumbing fixture- dryer vent is on a wrong wall so I cant push the dryer machine close to the wall which gives very les space to use machine- N/A	Laundry Room- General- Item #2- mudroom - door from garage to home is not aligned it keeps some gap so air comes inside	Exterior- General- Item #1- driveway collects a lot of water makes unable to walk and creates risk of mosquitos, please improve driveway alignment	Deficiency Description
Zancor - Caledon 156350	Zancor - Caledon 156349	Zancor - Caledon 156348	Zancor - Caledon 156347	Zancor - Caledon 156346	Zancor Caledon 156345	Lon Plumbing & Heating 156344	Zancor - Caledon 156343	Zancor - Caledon 156341	New Image Kitchens 156340	Dart Electric 156339	Zancor - Caledon 156338	Newmar 156337	C Valley Paying 156336	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
12May23	12May23	12May23	12May23	12May23	12May23	12May23	12May23	12May23	12May23	12May23	12May23	94May23	12May23	Add Appointment
1	1	7	7	1	7	7	7		2		7	7		Item Completed
80.	80	90	3	3.0	30	3,0	BD	3.0	BP	>	QB	80	Participation of the Control of the	Initial

	***************************************	12May23	Add	VIA Trim and Doors Inc. 156355	Basement- General- Item #19- bedroom closest door cannot be closed easily it nots aligned properly	19	30-Day	20Apr23
		12May23	Add	VIA Trim and Doors Inc. 156354	Basement- General- Itrm #18- bathroom door leading to the room an be clsose easily and its not aligned	000 000	30-Day	20Apr23
9	1	12May23	Add	Zancor - Caledon 156353	Basement-General-ITEM #17- there are a bunch of cables and we are not sure why there are if they are any safety risk-SVC TO CONFIRM WITH H.O WHAT CABLES ARE FOR	17	30-Day	20Apr23
B.D	7	12May23	Add	Zancor - Caledon 156352	Basement- General- Item #16- concrete- visible enlarge cracks on the basements floor - MONTIOR	16	30-Day	20Apr23
60		04May23	Add	Newmar 156351	door is not installed correctly it is very loose and can be easily opened from the outside- ADJUST SCREEN DOOR NOT ON STRAIGHT	Us.	30-Day	20Apr23

The Homeowner Signature: Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

A NCOR Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Glosing Date: 23Feb23
Address:
Location: Caledon Clu
Today's Date: 03May23
Contact(s): Vishal Govinc

Caledon Club - Phase: 1 - Lot: 146A
03May23
Vishal Govindbhai Patel - Work: (647) 403-5199 - (vishal.patel9@live.com)
Bhurnika Patel - Cell: (647) 274-3556 - (bhurnika.patel@live.ca)
vishal.patel9@live.com

Email:

Company: Zancor -Caledon Attention: Telephone: Fax:

Please Complete the following items:

		rior .		
156274	156273	156272	156267	DAI
30-Day	30-Даў	30-Day	30-Day	Type
Master Ensuite- General- Item #4- corner joint in ceiling developing a crack(H.O TO REPORT AT YEAR END	Main Bathroom- General- Item #3- Trim- Master bath: counter top marble trim to call joint seal peeling off	Main Bathroom- General- Item #2- Trim- Master bath: shower bottom marble frame to wall & floor joint needs re-finishing & touch up	Master Ensuite- General- Item #1- trim- shower marble frame wall entire joint needs re-finishing	Issue
ANT-	کھ	7,9	35	
09May23 /am	09May23 /am	09May23 /am	09May23	Appt. Date/Time
Xen EN				Notes

KREGOK

156284	156283	156282	156281	156280	156279	156278	156277	156275	metable municipal management
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	-
Main Bathroom- General- Item #13- wall- bed 1 bath: tile to	Main Bathroom- General- Item #12- bathroom -wall bed 1 bath: tile to ceiling tile to wall joint	Main Bathroom- General- Item #11- wall- bed 1: bath: to ceiling corner joint is unfinished	Bedroom 2- General- Item #10- wall- bed 1bath- tile to ceiling 'corner joint is unfinished	Bedroom 2- General- Item #9- master bed: window wood frame is developing a long crack	Bedroom 2- General- Item #8- windows- master bed: window corner joint is developing a crack	Bedroom 2- General- item #8- windows- master bed: window corner joint is developing a crack	Bedroom 2- General- Item #7- windows- master bed:window corner joint is developing a crack	Main Bathroom- General- Item #5- windows- master bath: window corner joint is developing a crack	SETTLEMENT)
78	8	8	8		8	8	B	25	
09May23 /am	09May23 /am	09May23 /am	09May23 /am	09May23 /am	09May23 /am	09May23 /am	09May23 /am	09May23	
	The control of the co			SPAIR END					- Constant

	09May23 /am	agegypp promodents holis	Laundry Room- General- Item #31-	30-Day	156313
	09May23	750	Kitchen- General- Item #30- kitchen floor- floor to wall joints need fill upP- BELOW SLIDING DOOR	30-Дау	156311
SAM ENO	09May23 /am		Main Hall- General- Item #22- hallway ceiling- ceiling to joint developing a crack	30-Day	156295
	09May23 /am	72	Main Bathroom- General- Item #21- doors- main door- door frame joint is developing a crack	30-Day	156294
	09May23 /am	<u> </u>	Main Bathroom- General- item #19- wall- bed 2 bath tile joint to wall frame joint is unfinished	30-Day	156292
	09May23	70	Master Bedroom- General- Item #18- windows- bed 2: window frame joint is developing a crack	30-Day	156291
She Sur	09May23 /am		Master Bedroom- General- Item #17- bedroom ceiling- bed 2: the ceiling corner joint is developing a crack	30-Day	156290
Be BN	09May23 /am		Bedroom 3- General- Item #15- ceiling- bed 1: ceiling corner joint is developing a crack Report at Year end Tarion	30-Day	156286
	09May23 /am	525	Main Bathroom- General- Item # 14- floor- bed 1- bath : floor to tile to wall joint unfinished	30-Day	156285
	e mico ma VIII		wall joint is unfinished		

1		G. Tarana		***************************************
	09May23 /am	Exterior- General- Item #39- window drain pipe is full of gravel and mud- Seasonal wwill be removed at orading stage	30-Day	156332
	09May23 /am	Exterior- General- Item #38-returing wall- foundation crack found on right side of property close to gas pipe- water test	30-Day	156331
	09May23 /am	Exterior- General- item #35- gas pipe clamp is not properly secured	30-Day	156325
	09May23 /am	Basement- General- Item #34- electrical panel access to the electrical panel is not ssafe furnace& heater is to close - talk to anthony	30-Day	156321
	09May23 /am	Basement- General- Item #33- unfinished area- long crack is developing close to stairs- N/W H.O TO MONITOR NOT WIDE ENOUGH	30-Day	156318
	09May23 /am	Stairs- General- ITEM #32- unfinished area around	30-Day	156315
SP PHILES	(C))	ceiling- laundry room ceiling 3 nail pops- Report at Year end Tarion		

(i)
(D)
Σ/
9
3
73
70
(D)
Date Completed
Ω.
11
100
- 62
1
142
~
1
1
1
11 /
· V
108
L(I)

Date Completed:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.
Signature CC

Print Name: Louren

page 4 / 6