* 33B Zancor Caledon * VENT RIGHT SIDE CROOKED + NO CAULK NA MO • CLEAN MORTAR FROM WEEPERS RV. • WINDOW WELLS IN REAR FU. BRICK REPAIR BY GASLINE PENETRATION • CLEAN MORTAR LEFT SIDE RV. • NO ADDRESS PLAQUE ZAW. · CANTINA VENTS TO BE INSTALLED ZAW (1-) Shelf 350-1000 y-) 1886k-07 LAnnetry (arborite) MASTER ENSUITE: • GROUT SHOWER CEILING LEFT SIDE A • GROUT VERTICAL SHOWER TILE LINE RIGHT SIDE AU • SMALL CHIPS LOWER GABLE RIGHT SIDE MZ • LEFT SINK STOPPER HARD TO USE IP.

RIGHT SINK WATER BUILD UP WHEN LEFT ON IP.

• SILICONE REQUIRED 2AW.

MASTER BED:

· SECURE ATTIC HATCH ZAN/

MAIN BATH:

• SILICONE NEEDED /

BED #3:

BOLT CRACK @ ENTRANCE VT.

FOYER:

- HEAT REGISTER CUT TOO CLOSE TO WALL NA.
- DAMAGE TO DOOR FRAME ABOVE OPERATION N W
 DOOR FRONT DOOR

POWDER ROOM:

• WATER BUILDS UP IN SINK SLOW DRAINAGE IP.

DINING:

• FIX INSTALLATION OF LIGHTING FIXTURE $b \subset$

LAUNDRY:

- CHIP @ COUNTER TOPS SIDE NA
- LEFT SIDE OF STAIR HAS UNFINISHED AREA BS

KITCHEN:

• REMOVE PENCIL MARKS INSIDE CABINET RIGHT OF

STOVE

- INSTALL SHELF IN CABINET LOWER RIGHT OF STOVE
- FRIDGE CABINET FAR LEFT UPPER FROM
- ALIGN ALL CABINETS N+
- RED STAIN ON DRYWALL RIGHT OF FRIDGE ZAW

BASEMENT:

- DENTS IN SIDE DOOR PT
- PAINT STAIRS GREY PT.
- REPAIR WRAP INSULATION BY CANTINA DOOR ZAW
- REMOVE NAILS FROM CANTINA ZAW
- ONLY ONE CANTINA VENT ONE COVERED RL
- SEAL INSULATION BY BASEMENT BY WINDOW

Chris Di Genova Innisfil – Cove - Office Administrator (647) 679-0469