Rindry hereles Deficiency Check List - User: Christopher DiGenova

Chip in House

Outstanding Deficiencies

Belle Aire Shores - Phase: 3 - Lot: 90W

<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	06Jun23	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	06Jun23	<u>06Jun23</u>	<u>06Jun23</u>	Date Reported
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	<u>Type</u>
19	18	17	16	15	14	13	12	=	10	9	∞	7	6	S	4	υ,	2	-	Number
DINING ROOM- FLOORING~CHIP ON 3RD, 14TH, 15TH HARDWOOD PLANK FROM WINDOW	DINING ROOM-FLOORING~CHIP ON 1ST, 3RD, 6TH HARDWOOD PLANK FROM MAIN HALL TO DINNING	UPPER HALL- FLOORING~CHIP ON 2ND HARDWOOD PLANK FROM NOISING AT UPPER HALL	UPPER HALL- RAILING~STAIN REQUIRED AT JULIETTE BALCONY BOTH SIDES	BEDROOM #2- FLOORING~TUCK CARPET BUBBLING IN MIDDLE OF FLOOR	MASTER BEDROOM- FLOORING~TUCK CARPET BUBBLING MIDDLE OF FLOOR	FAMILY ROOM- WALLS~BUBBLE AT DRYWALL AT FIREPLACE AND CEILING AND LEFT SIDE WHERE CORNER MEETS, CAN SEE FROM JULIETTE RAILING	SHARED ENSUITE: VANITY CABINETS-CHIP BELOW LEFT SINK ON DOOR CORNER CHIPS ON RIGHT FILLER PIECE	LAUNDRY ROOM- FLOORING~FLOOR DRAIN MISSING IN LAUNDRY ROOM FLOOR	LAUNDRY ROOM- FLOORING~SCRATCH ON 3RD HARDWOOD PLANK AT LANDING FROM MAIN FLOOR TO BSMT	LIBRARY/DEN- FLOORING~CHIP ON 6TH HARDWOOD PLANK FROM BACK WALL AND 4TH HARDWOOD PLANK FROM ARCHWAY AT ENTRANCE TO LIVING INSPECT 8TH HARDWOOD PLANK FROM ENTRANCE TO LIVING ROOM DISCOLOURED FROM ARCHWAY	EXTERIOR- NOTE:~SECURE, TRIM BY SOFFIT ABOVE LIGHT FIXTURE WAVY AT FRONT PORCH	Exterior- General- NOTE:~SOFFIT MISSING LEFT and right OF COLUMN AT FRONT PORCH	EXTERIOR- NOTE:~CRACK ON RIGHT GARAGE DOOR WINDOW	Exterior- General- NOTE:~ADJUST freezeboard ABOVE GARAGE DOOR AT EAVES. PLYWOOD SHOWING	Exterior- General- NOTE:~INSPECT CAULKING AT WINDOW ABOVE GARAGE SEPARATING FROM MULIN	Exterior- General- NOTE:~GAS LINE IN INCORRECT AREA AS PER EXTRA SHOULD BE ON LEFT SIDE OF DECK	Exterior- General- NOTE:~HOLE IN EXTERIOR MULIN TRIM AT FRONT DOOR RIGHT SIDE	Exterior- General- NOTE:~CHIP ON STONE RIGHT OF WINDOW LEFT THE FRONT DOOR	Deficiency Description
First Canadian Hardwood 157855	First Canadian Hardwood 157854	First Canadian Hardwood 157853	Perfect Touch Painting 157852	Quality Rugs Canada LTD. 157851	Quality Rugs Canada LTD. 157850	Foremont Drywall 157849	New Image Kitchens 157848	Icon Plumbing & Heating 157847	First Canadian Hardwood 157846	First Canadian Hardwood 157845	Promark Aluminum LTD. 157844	Promark Aluminum LTD. 157968	Abbey Overhead Doors Inc. 157843	Promark Aluminum Control 157967	CJ Caulking 157969	Zancor Construction/Labour Innisfil 157966	<u>Newmar</u> 157899	River Valley Masonry Group LTD 157898	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Appointment <u>Date</u>
\	7	<	<	<	7	×	11		<				7		7	<	_	\	Item Completed
			5	4	4			Œ	S			C sources	25		~	Di	J	63	Initial

10	10	lo lo	-	T 10	10	10	ю	10	10	10	0	10	10	10	10	10	0	IC		Ic	IC	10	
<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>6Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	06Jun23	06Jun23	06Jun23	<u>6Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	<u>06Jun23</u>	06Jun23	06Jun23	06Jun23	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI
43	42	41	40	39	<i>∞</i>	37	36	35	34	33	32	32	30	29	28	27	26	25	24	23	22	21	20
KITCHEN- CABINETS-FILL NAIL HOLES THROUGHOUT AND TOUCH UP EDGES AT CROWN MOLDING	KITCHEN- CABINETS~ADJUST CORNER PIE CABINET AND INSPECT BLACK MARKS ON TOP AND CHIP INSIDE BOTTOM GABLE	KITCHEN- CABINETS~BLACK MARKS ON EDGE OF DUMBY DOOR ISLAND FACING FAMILY ROOM	KITCHEN- CABINETS~CHIPS ON UPPER SHELF LEFT LEFT ABOVE DISHWASHER CUT OUT	KITCHEN- CABINETS~REMOVE RED PEN MARK ON UPPER SHELF ABOVE CORNER PIE CABINET	KITCHEN- WINDOWS-CHIP AT MULIN THRESHOLD AT FLOOR LINE AT FIXED SIDE SLIDING DOOR	KITCHEN- ELECTRICAL/LIGHTING~VALANCE LIGHTING NOT INSTALLED AS PER EXTRA STRIP LED	KITCHEN- SINK/FAUCET/PLUMBING~WATER LINE FOR FRIDGE NOT INSTALLED	FOYER/HALL- CLOSET~LEFT LINEN CLOSET DOOR NOT PAINTED	FOYER/HALL- STAIRS~TRIM NOT INSTALLED BY NOISING AT STAIRS TO BSMT	- STAIRS- C NEWEL BSMT	TO BSMT	NG	FOYER/HALL- STAIRS~CHIP ON MAIN POST AT LANDING TO BSMT	FOYER/HALL- STAIRS~CHIPS ON OUTSIDE STRINGER AT STAIRS TO 2ND FLOOR CAN SEE FROM MAIN FLOOR			IM TRINGER	-	FOYER/HALL- STAIRS~STAIN REQUIRED BY NEWEL POST AT BSMT LANDING	FOYER/HALL- STAIRS~BRUSH MARKS ON 6TH TREAD AT STAIRS FROM BSMT TO MAIN FLOOR	NAIL HOLES AT HARDWOOD PLANK BY NOISING AT STAIRS TO BSMT AND THROUGHOUT HOME	OOD PLANK	
New Image Kitchens 157879	New Image Kitchens 157878	New Image Kitchens 157877	New Image Kitchens 157876	New Image Kitchens 157875	<u>Newmar</u> 157874	Dart Electric 157873	Icon Plumbing & Heating 157872	Perfect Touch Painting 157871	WYECROFT TRIM 157870	Perfect Touch Painting 157869	Bolton Railings Inc. 157868	Bolton Railing <u>s Inc.</u> 157867	Bolton Railings Inc. 157866	Bolton Railings Inc. 157865	Bolton Railings Inc. 157864	Bolton Railing <u>s Inc.</u> 157863	WYECROFT TRIM 157862	Bolton Railings Inc. 157861	Perfect Touch Painting 157860	Perfect Touch Painting 157859	First Canadian Hardwood 157858	First Canadian Hardwood 157857	<u>Newmar</u> 157856
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	<u>Add</u>	Add	<u>Add</u>	Add	Add	Add	Add	<u>Add</u>	Add	Add	Add	Add	Add	Add
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.
1111	11	1111	1/11	11	<	<	<	<	<	<	<	. <	<		<	<	<	<	<	\	<	_	<
					95	8	T	C	T	8	4	7	4	J	6.	33	Z	J.	4	T			2

						7	· v				1	
<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	<u>06Jun23</u>	<u>06Jun23</u>	06Jun23	'9/23, 2:30 PM
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	_ ≤
56	55	54	53	52	51	49	48	47	46	45	44	
MASTER ENSUITE BATH- FAUCETS/PLUMBING~SINKS MISSING	MASTER ENSUITE BATH- VANITY CABINETS-CHIP ON MIDDLE BANK OF DRAWER	MASTER ENSUITE BATH- VANITY CABINETS~SCRATCH ON INSIDE LEFT CABINET AND FACE OF RIGHT DOOR	MASTER ENSUITE BATH- SHOWER ENCLOSURE~INSPECT BLACK MARK ON TILE BELOW JAMB INSIDE SHOWER	LIVING ROOM- WINDOWS~CRACK FIXED GLASS WINDOW	LIVING ROOM- WALLS~OVERCUT AT RIGHT POT-LIGHT AT CEILING RIGHT OF FIREPLACE	BASEMENT- NOTE:~ADJUST BASEMENT DOOR AND HANDLE TO BSMT	KITCHEN- FLOORING~CHIP AT 6 AND 12TH AND 15TH PLANK FROM FRIDGE.	KITCHEN- CABINETS~CHIP ON UPPER RIGHT AND LEFT VALANCE OF HOOD FAN	KITCHEN- CABINETS~BUBBLE ON HOOD FAN PANEL	KITCHEN- CABINETS-CHIP AT KICKPLATE RIGHT AND LEFT OF MICROWAVE CUT OUT AT ISLAND	KITCHEN- CABINETS~SCRATCH ON UPPER LEFT CABINET RIGHT OF HOOD FAN	Deficiency Ch
Icon Plumbing & Heating 157892	New Image Kitchens 157891	New Image Kitchens 157890	AV Classic 157889	<u>Newmar</u> 157888	Foremont Drywall 157887	WYECROFT TRIM 157885	First Canadian Hardwood 157884	New Image Kitchens 157883	New Image Kitchens 157882	New Image Kitchens 157881	<u>New Image</u> <u>Kitchens</u> 157880	Deficiency Check List - User: Christopher DiGenova
Add	Add	Add	Add	Add	Add	Add	Add	<u>Add</u>	<u>Add</u>	<u>Add</u>	Add	opher D
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	iGenova
<	11/1	11/1		1	<	1		1111	111	1/11	11/1	
45			A			4						

Zancor Service Technician:	Date:	The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.	Homeowner Signature:
1		all like	, I