Enrollment:

Purchaser Name: 222225

Jacqueline Jackson

**Phone Res:** 

Phone Bus: (647) 281-4266

Closing Date: Inspector: Gisella Fiore February 06, 2025

ANCO

HOMES Z

Vendor / Builder: Project Zancor Homes (Wasaga River) Ltd

Lot / Phase:

65/2

Address: Plan: 50 Rosanne Circle

Municiaplity:

Page 1 of 2

December 17, 2024

Inspection Date:

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum,

## DAMAGED, INCOMPLETE OR MISSING

check the following:

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

## RANGEHOOD CABINETS KITCHEN FRONT DOORS FLOORING FOYER/HALL **FLOORING** LAUNDRY ROOM FLOORING NOTE: VANITY CABINETS **FLOORING BEDROOM 4 ENSUITE BEDROOM #4** VANÎTY CABINETS BEDROOM 3 ENSUITE **UPPER HALL** MASTER ENSUITE BATH SCRATCH AT SHOWER SILVER TRIM LEFT OF GLASS DOOP FILL GROUT AT BACKSPLASH RIGHT OF HOODFAN AT CEILING FRONT LEFT DOOR BOWED AT FLOORLINE MISSING GROUT AT TILE BASEBOARD BELOW TRIM MISSING GROUT AT TOP OF FACUET IN TUB. AND ABOVE AT CEILING ROUGH EDGE AT ISLAND COUNTERTOP FACING BREAKFAST AREA CHIP AT PULL OUT DRAWER LEFT OF GARBAGE DRAWER AT ISLAND. SCRATCHED DAMAGED AT 13,14 15. PLANK FROM FOYER INFRONT OF DINNING ROOM REMOVE PAINT OFF CARPET AT ENTRANCE TO BATH. REMOVE VARNISH OFF 2ND PLANK RIGHT OF LONG RAILING INFRONT OF MASTER. AND AT STAIRS TO MAIN FROM 2ND FLOOR. LARGE GAP BETWEEN NOSING AND OUTSIDE STRINGER AT LANDING TO 2ND DAMAGED NOSING AT 2ND LANDING TO 2ND FLOOR. REDO CHIP AT BACK PANEL BELOW CABINET SCRATCH IN BOTTOM LEFT CABINET BELOW SINK GROUT LEFT OF TOE STOP DISCOLOURED. MISSING DRAWER BELOW SINK 2ND DRAWER CENTRE 2 8 8

Homeowner Signature The Homeowner acknowledges and accepts that all initialed work has been completed in , orkman like manner to their satisfaction.

Enrollment:

Purchaser Name: ???????

Jacqueline Jackson

Phone Res:

Phone Bus: (647) 281-4266

Closing Date: inspector: Gisella Fiore February 06, 2025

> HOMES ANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 65/2

Plan:

Address: 50 Rosanne Circle

Municiaplity:

Inspection Date: December 17, 2024

KITCHEN

SECURE LIGHT AT ISLAND AND POT LIGHT RIGHT OF SINK NOT FLUSH. SINK AT SURVERY FACUET TO BE SECURED. MOVING

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.
\*Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the

vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

255555

Purchaser's Name (print)

Designate's Name (print)

Designate's Signature

Purchaser's Signature

Jacqueline Jackson

Purchaser's Name (print)

Gisella Flore

inspector's Name (print)

Purchaser's Signature

Inspector's Signature