ZANCOR HOMES

Zancor Oakville Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Alicia

Closing Date:	**08Nov23**
Address:	**2450 Old Bronte Road, Suite 707**
	Oakville, Ontario
Location:	**The Branch Condos - Phase: 1 - Lot: 707**
Today's Date:	20Oct23
Contact(s):	Jessica Garabetian - Cell: (647) 964-2226 - (jessvahegara@gmail.com)
Email:	jessvahegara@gmail.com

Company:	**New Image Kitchens**
Attention:	
Telephone:	(416) 739-0007
Fax:	(416) 739-7031

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
165497	PDI	MASTER ENSUITE BATH- VANITY CABINETS~SHELF NOT INSTALLED			*Done*
165498	PDI	MASTER ENSUITE BATH- VANITY CABINETS~HANDLES NOT INSTALLED AT BANK OF DRAWERS			⋆ need 4 pcs of Handle in master Ensuite *Done*
165499	PDI	MASTER ENSUITE BATH- VANITY CABINETS~CHIPS AT BOTTOM GABLE BELOW SINK			*Done*
165507	PDI	POWDER ROOM- NOTE:~KICKPLATE NOT FLUSH AND CUT SHORT			⋆ need Kick Plate Timber grey 82cm X 12cm *Done*
165508	PDI	Powder Room- General- NOTE:~VANITY NOT INSTALLED THE STRAIGHT -ADJUST			*Done*

		GABLES ON INTERIOR			DONE
165516	PDI	KITCHEN-NOTE:~MOVABLE ISLAND NOT INSTALLED			* not Part of contract~ check file DONE
165517	PDI	KITCHEN-CABINETS~SECURE SHELF AT UPPER CABINET AND SHELF MISSING BELOW			* need shelf Done 41.5cm x 27.5cm (FIL)
165518	PDI	KITCHEN-CABINETS~SCRATCH ON UPPER CABINET ABOVE MICROWAVE			Done
165519	PDI	KITCHEN- CABINETS ~HOMEOWNER REQUESTING TO HAVE KICKPLATE MADE FOR DW PANNEL			* Dishwasher has not Kick Plate. Done * Make 1 Plate 12x24"
165520	PDI	KITCHEN-CABINETS~PAINT ON FREEZER PANNEL AND ON CABINETS THROUGHOUT			Done
165521	PDI	KITCHEN-CABINETS~HANDLES NOT INSTALLED AT BANK OF DRAWERS			* need 4 Pcs Handle in Kitchen Done

Date Completed: _____

Date Completed: 6/NOV/2023

Homeowner Signature: N/a

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature: Inder

Print Name: _____

3/April/2024   Inder

Please schedule your Service Department to complete work on the above Lot. Should no