



### Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 2310</u> <u>2310 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>29Jan09</u>
<b>Contact Name(s)</b>	<u>Josip Rudar and Rozi Rudar</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

#### Please complete the following items:


Deficiency Number	Issue	Appointment Date/Time	Notes
5976	FOYER / ENTRY- WALLS-stiple on wall above entrance to bathroom upper right corner	✓	
5977	FOYER / ENTRY- WALLS: 1-drywall dented right wall adjacent to closet where taped	✓	
5978	FOYER / ENTRY- DOORS-mark on frame lower right side entrance where taped	✓	
5980	LIVING/DINING ROOM- FLOORING-REPAIR seam in baseboard below telephone	✓	
5987	MASTER BEDROOM- WALLS: 1-drywall seam/tape visible on bulkhead from underside to ceiling where taped	✓	
5989	MASTER BEDROOM- DOORS-Outside door casing not straight	✓	
5990	MASTER BEDROOM- DOORS: 1-touch up seams of casings	✓	
5991	MASTER BEDROOM- DOORS: 2-scratches on face of door where taped	✓	
5992	MASTER BEDROOM- FLOORING-repair baseboard seam where taped	✓	
5995	MASTER BEDROOM- CLOSET-closet door stained/marked where taped	✓	
5996	MASTER BEDROOM- CLOSET: 1-marks/bubbles in frame and casing where taped	✓	
5997	MAIN BATHROOM- WALLS-drywall rough around light switch	✓	
5998	MAIN BATHROOM- DOORS-upper corners of casing needs paint interior and exterior	✓	
5999	MAIN BATHROOM- DOORS: 1-interior frames rough	✓	
6001	MAIN BATHROOM- COUNTERTOPS-corner piece delaminating where taped	✓	

6002	MAIN BATHROOM- COUNTERTOPS: 1-pencil mark on backsplash behind tap		✓	
6005	MAIN BATHROOM- VANITY CABINETS-excessive gap at vanity doors		✓	
6007	MAIN BATHROOM- VANITY CABINETS: 1-doors not aligned		✓	
6009	KITCHEN- CABINETS-adjust cabinet over microwave doors rubbing		✓	
6011	KITCHEN- CABINETS: 1-adjust doors cabinet right of microwave rubbing		✓	
6018	KITCHEN- CABINETS: 7-EXCESSIVE GAP top of upper cabinet 3rd from fridge		✓	
6020	KITCHEN- COUNTERTOPS: 1-excessive gap underside of countertop facing living room		✓	
6022	LAUNDRY CLOSET- DOORS-top corners of casing needs paint		✓	
6023	LAUNDRY CLOSET- DOORS: 1-bubble on door below handle where taped		✓	

Date Completed:

Jun 30/09/56

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back -](#)  
[Forms](#)  
[Menu](#)

ID#

5976/5977/5978/5980/5987/5989/5990/5991/5992/5995/5996/5997/5998/5999/6001/6002/6005/6007/6009/6011/6018/6020/6022/6023  
 Eve Ph 1 Lot 2310