


February 19, 2009

Gaurav & Baitit Mehta 3515 Kariya Drive 312 MISSISSAUGA ON L5B 0C1

Enrolment # H1512224 Case # 2356184



## **Tarion Warranty Corporation**

Customer Centre
5150 Yonge Street, Concourse Level
Toronto, Ontario M2N 6L8
Toil-Free: 1-877-982-7466

Copy to:

Amacon Development (Hurontario) Corp. 2 Harbour St. TORONTO Ontario M5J 3B1

Vendor/Builder # 33372 Lot: Pt. 16, Plan: , Block:

Mississauga, City

# Confirmation of Receipt of your 30-Day Form

This notice is to inform you that we received your 30-Day Form and are accepting it based on the Date of Possession, January 19, 2009, of record for your home. Please note that this is the only 30-Day Form we can accept for your home, as outlined in the *Homeowner Information Package*.

All items noted on your 30-Day Form that are part of your unit and are covered by warranty under the Ontario New Home Warranties Plan Act ("statutory warranty") should be repaired or otherwise corrected by your builder by June 19, 2009, except as noted below\*. If any of these items have not been corrected by this date, you may contact us between June 20, 2009 and July 20, 2009 to request a conciliation inspection of your home to assess the situation. If you do not contact us during this time period to request a conciliation inspection, we will consider all items listed on your 30-Day Form resolved and the matter closed. (You may resubmit the item(s) at a later date if the warranty covering those item(s) is still in effect.)


Because it can take several months for the natural materials in your home to dry and settle, new items may emerge over time. Your next opportunity to report to us any items that are covered by the statutory warranty occurs during the last 30 days before the first anniversary of possession of your home. During that period, you may report any such items by submitting the Year-End Form to us and sending a copy to your builder. (See your *Homeowner Information Package* for more details.)

The repair timelines listed above do not apply to items included in your condominium project's common elements because such items are not covered by your unit's statutory warranty. You should report these items in writing to the condominium corporation's Board of Directors. (For a complete description of your unit's boundaries, refer to Schedule "C" of the declaration of your condominium, which should be included with your Disclosure Statement.)

\* Please note there are specific situations - such as emergencies and completion of your new home's landscaping - in which this timeline does not apply. Please refer to the *Homeowner Information Package* for more information about the Statutory Warranty Process and exceptions to it.

You may wish to visit our website to consult the *Construction Performance Guidelines*. The Guidelines describe many of the most commonly reported warranty items and indicate which are covered by warranty under the *Ontario New Home Warranties Plan Act*.





30-Day Form

## TO NOTIFY TARION OF OUTSTANDING WASBLARDY ITEMS, COMPLETE AND SUBBIT THIS FORM BEFORE THE BEG OF THE PERSENCED PAYS OF POSSESSION OF YOUR HOME.

#### YOU MAY SURBIT ONLY CIRE 30-DAY FORM.

Statem Dis Peru in Dis Torico Compres Contro Expert in 5150 Yorga Silver Concorate Level, Toronto Oriento ANNOTED in resident his coal or courses on to broke 1.877.286.9716. Such your elegandings belonging floring by

one kienšijosiom informaton (Sereto)	yesa Tamiacaia el Cercinido	nasa Pooceason to consider	r 1903 (DCS)   Professional Company (Company (Co
	3372 3388888 11 - 11 - 12 - 13	1512224	
dvic Address jaxressiv yourross sicca s		CL CASE PARTS	
3515 KARIYA DRIVE Sinesi Noryonies Sinesi Martina		•	312 k-Sele (Tripplicade)
MISSISSAUGA	1.5B 0C1 ()	Pt. 16	PONDOS
Contact information of Homeovaner(s):		Acedini	boYvšisoki Nimbo
GAURAY MEHTA		BALJIT MEHTA	
garaggerragingana	i i i i i i i i i i i i i i i i i i i	especials basins d'agricultis	
\$ 905 \$403 0595 ENT 26	50 Em 1999 E	905 - 7896 me Phicos Number, III.	0866
स्कारकी हुआएक एकेटकरूल	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	905 <sup>1</sup> 896 hythani Nober () - Th	0866
( ) — — — — — — — — — — — — — — — — — —	The Control of the Co	) — Svasker in in I in Inc	era (j. 20ja in 1)
GORDMEIITA ÄYAHOO.CA	er, er, e	ORDMEHT AGY AHO	•
Checulare would provide our demorphism - appointed nomecomen.		Chang più poa f yan are : Legespend frankasana	Paris Siding
and Address for Correspondence to			cooracceronica correccionamento su meio
and the state of t	A STATE OF THE STA	A CONTRACTOR OF THE CONTRACTOR	
Speed Mariner Street beginn			Crysk-Sine # . II andioaka

TAPN-2007-04.00

Page for 3

PAGE: 003 OF 004

FROM: 9058960866; Gord Mehta

#### Outstanding herrs

List of outstanding from consisted by the statutory scarcing in the tobic below. If you require more space, please make copies of this page, number there and allach men to this Substenz Wassanty Form

ikam si	Roomillocation	Description	
4	Living dinning	room hardwood floor is damaged with deep scratches and one place it is heavily damaged. Also in one place the plank of wood floor is cracked. The complaint was put in first day but we were told to use the 30 day form.	
3	Living dinning	The floor is moving in couple of places and not glaced mailed to the floor properly;	   
2	Kitchen	On the refrigerator there is a scratch.	
1	Front entrance	Front door steel place is not properly put in. The steel plate is loose and bent in couple of places	
5	Living dinning	Crack in the drywall in the following places: wall, kitchen and front door. Behind the fridge there is also wall damage.	
6	Bathrooms (Both)	Toilet does not flush all the way. The float closes too fast. Less than 25% of the tank empties before the float closes.	
7	Bathrooms Kitchen	Hot water, at the highest setting the water is Luke warm. We seem to run out of even the warm water on weekends	•
8 9	Spare bedroom Master Bathroom	Circuit breaker not labelled Bathroom door does not lock properly	: :! -:::
10	Front entrance	Front entrance and kitchen floor tiles have marks which we could not be cleaned	ŧ

The little specified on the Shearan Warrany Conniccentile a complete list of all known warrany leans when her -oldstanding and have not been resolved by my Builder in dise.

Ekternecements Signostade (diagréficiole)

CARRAMENT PRESENTATE

2009 1.02 -18 (Date of Signature (YYY)YAWWOO)

Phone the first of their time state Barks a suprementable is substitutioned account to grave their elegand engine have the comment. analyzakiem te virangesi nerbetus, in mit in saanyeks har eserintar virak. Pekareta da as mey papankes yini ereninty teyta.

TARM-1907-04.01

PAGE: 004 OF 004

FROM: 9058960866; Gord Mehta

## Outstanding lienes

List, all putationshing items, covered by the statutory scame ay in the table below. If you require more enacte, please make copies of this page, number them. and alloch here to this Statutory Warranty Form

The kitchen a specified on the Stephen Collection of the panel door and forgot to replace the Tarion sticker.  The kitchen The kitchen cabinet next to the stove is missing a cabinet panel.  Very cold air coming from the microwave exhaust vent  The filling around counter top is coming apart from the wall and counter top Tub Faucet and shower head are loose. Shower head pipes are moving  Back side of the bathroom door there is chuck (blob) of paint stuck there.  Guest Bathroom  Cuest bathroom shower there is pin holes in the shower grout.  Tarion sticker missing on electrical panel. During the PDI inspection we mentioned that there was a scrarch on the electrical panel sor Amaeon must have replaced the panel door and forgot to replace the Tarion sticker.  The herita specified on this Stephen Witnesmy from exceptible a company for distinct was a server of all known waysony game which are exceptible and all known waysony game which are	itarn f	Room&ccaban	Description
Master Bathroom Tub Faucet and shower head are loose. Shower head pipes are moving  13 Master Bathroom Back side of the bathroom door there is chuck (blob) of paint stuck there.  14 Guest Bathroom Guest bathroom shower there is pin holes in the shower grout.  15 Spare Bedroom Tarion sticker missing on electrical panel. During the PDI inspection we mentioned that there was a scratch on the electrical panel sor hand sor have replaced the panel door and forgot to replace the Tarion sticker.  16 The large appealant on the Stephen Western Commission and Forgot to replace the Tarion sticker.	11	Kitchen	The kitchen cabinet next to the stove is missing a cahinet panel.
Tub Faucet and shower head are loose. Shower head pipes are moving    15   Master Bathroom   Back side of the bathroom door there is chuck (blob) of paint stuck there.	12	Kitchen	Very cold air coming from the microwave exhaust vent
Master Bathroom   Back side of the bathroom door there is chuck (blob) of paint stuck there.	13	Master Bathroom	The filling around counter top is coming apart from the wall and counter top
Guest Bathroom  Tarion sticker missing on electrical panel. During the PDI inspection we mentioned that there was a scratch on the electrical panel sor Amazon must have replaced the panel door and forgot to replace the Tarion sticker.  The large specified on this Statuter Western Committee in a congress for all broken waterny large which use	14	Master Bathmom	Tub Faucet and shower head are loose. Shower head pipes are moving
Tarion sticker missing on electrical panel. During the PDI inspection we mentioned that there was a scratch on the electrical panel so Amazon must have replaced the panel door and forgot to replace the Tarion sticker.  The terms specified on the Station Warson Commonstate a complete by disk tooks warson, sans which are	15	Master Bathmom	Back side of the bathroom door there is chuck (blob) of paint stuck there.
mentioned that there was a scratch on the electrical panel so funacon must have replaced the panel door and forgot to replace the Tarion sticker.    The terms specified on the Stephen Western Commonstable is company for the Stephen Western are	16	Guest Bathroom	Guest bathroom shower there is pin holes in the shower grout.
The terms specified on the Steplan Western Commonwhile a company La of all works werenny have which the	17	Spare Bedroom	mentioned that there was a scratch on the electrical panel so. Amacon must
		•	
	***************************************		
	***************************************		
		-	
			! _
	******* **		<u> </u>
The the granum 1220 wither	æ.··	YER Lofai.	Christian 1720 outre
#conscions & Styristics   Homeodyne in Squared (Capitalists)   - 2009	200	09 / 02 / 1	

Photos was tempor a medi office your Burths a suprementations or outdoor bodies because to your lower change egylen basesses from the contemp. anticipation of the contribute for the contribute of the contribut

TARR-3907-94.02

Paga 3 of 3