

RECEIVED FEB 2 3 2009

February 19, 2009

Nenad & Sonja Smakdzija 530 Driftcurrent Drive Suit# 11 MISSISSAUGA Ontario L4Z 4G2

Enrolment # H1512251 Case # 2356205

3515 Kariya Drive, #706, MISSISSAUGA, L5B0C1

Tarion Warranty Corporation

Customer Centre
5150 Yonge Street, Concourse Level
Toronto, Ontario M2N 6L8
Toll-Free: 1-877-982-7466
www.tarion.com

Copy to:

Amacon Development (Hurontario) Corp. 2 Harbour St. TORONTO Ontario M5J 3B1

Vendor/Builder # 33372 Lot: Pt. 16, Plan: , Block:

Mississauga, City

Confirmation of Receipt of your 30-Day Form

This notice is to inform you that we received your 30-Day Form and are accepting it based on the Date of Possession, January 19, 2009, of record for your home. Please note that this is the only 30-Day Form we can accept for your home, as outlined in the *Homeowner Information Package*.

All items noted on your 30-Day Form that are part of your unit and are covered by warranty under the Ontario New Home Warranties Plan Act ("statutory warranty") should be repaired or otherwise corrected by your builder by June 19, 2009, except as noted below*. If any of these items have not been corrected by this date, you may contact us between June 20, 2009 and July 20, 2009 to request a conciliation inspection of your home to assess the situation. If you do not contact us during this time period to request a conciliation inspection, we will consider all items listed on your 30-Day Form resolved and the matter closed. (You may resubmit the item(s) at a later date if the warranty covering those item(s) is still in effect.)

Because it can take several months for the natural materials in your home to dry and settle, new items may emerge over time. Your next opportunity to report to us any items that are covered by the statutory warranty occurs during the last 30 days before the first anniversary of possession of your home. During that period, you may report any such items by submitting the Year-End Form to us and sending a copy to your builder. (See your *Homeowner Information Package* for more details.)

The repair timelines listed above do not apply to items included in your condominium project's common elements because such items are not covered by your unit's statutory warranty. You should report these items in writing to the condominium corporation's Board of Directors. (For a complete description of your unit's boundaries, refer to Schedule "C" of the declaration of your condominium, which should be included with your Disclosure Statement.)

* Please note there are specific situations - such as emergencies and completion of your new home's landscaping - in which this timeline does not apply. Please refer to the *Homeowner Information Package* for more information about the Statutory Warranty Process and exceptions to it.

You may wish to visit our website to consult the *Construction Performance Guidelines*. The Guidelines describe many of the most commonly reported warranty items and indicate which are covered by warranty under the *Ontario New Home Warranties Plan Act*.

PASE: 001 OF 004

FROM: 2058487827

30-Day Form

TO NOTIFY TARION OF OUTSTANDING WARRANTY ITEMS, COMPLETE AND SUBMIT THIS FORM BEFORE THE END OF THE FIRST 30 DAYS OF POSSESSION OF YOUR HOME.

YOU MAY SUBMIT ONLY ONE 30-DAY FORM.

TO NOTIFY TARION OF OUTSTANDING WARRANTY ITEMS, COMPLETE AND SUBMIT THIS FORM BEFORE THE END OF THE FIRST 30 DAYS OF POSSESSION OF YOUR HOME.					
YOU MAY SUBMIT ONLY ONE 30-DAY FORM.					
Submit this Form to the Tariori Customer Centre, located at 5150 Yonge Street. Concourse Level, Toronto, Ontario M2N 6L8, in person, by mail or coulter, or by fex to 1-877-664-9710. See your Homeowner Information Package for details about submitting this Form. Send a copy of the completed Form to your Builder and keep a copy for yourself.					
Home Identification Information (Refer to your Certificate of Completion and Possession to complete this box.)					
2009 / 01 / 19 3337 Delete Possession (1974/MADD) Television (1984)	N. 1782 (1982)				
Circic Address extress dear consumer exercity					
35/5 KARIYA DEWE	FOG				
MSSISSAUGA (CSTOCK)	EUE				
Cayfover Contact information of Homeconner(s)	Froed Subalivision Name				
DENAD SHANDSIMA	AFISTAMAR ASHOE				
(%5) 755 - 0700 /46-816-1888	(505) 755 - 070G /416-826-18				
(905) 755 - 5706	(Sos) 7515 - 0746				
EPONO Phone Number	Everage Thore Number				
() — — — — — — — — — — — — — — — — — —	TEXAMORE				
shenade rogers com	snehad & rogers, com				
Check histor (1964 bie 1788 ie 1870 mi 1996 Brei Hiotheomor	Chock his bow from alle not the original legisleted from entries				
Mailing Address for Correspondence to Homeowner (If different from Civic Address shove)					
Para Bana o e e dago do do do dos destados de la compansión de la compansión de la compansión de la compansión	and the second of the second o				

		CONTRACTOR SERVICE		
				t l
\$550 \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	タクープロヨダダメンフラ	_	설립함	
			ing Company of the Nation	and a State of
Sired Number Street			in the second of	Samo Sitatean
A continue of a s	100 mm	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	. (20) 图题	sobroane;
MSS(SSAUGA	### OO!	William Parker		
	national and the second of	Committee of the commit	2 - 12 5 - 14 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Carlor	THE REPORT OF THE PARTY OF THE	Rose Code	COMMUNICATION OF A 1997 OF 199	Andrew Control of the Control

Page 1 of

1) TENTRY DOOR - OUTSIDE FOOL OF WOOD STAINS, ALSO STAINS ON HETAL PARTS

LIVING DINING ROOM

- O FLOORYNG BIG HOLSY SKEAG WING. AREA IN THE FLOOR
 ESPECIALY ON THE BEGINING AREA ABTACENT TO TAILS IN ENTRY!

 AND FEW ANOTHER PLACES

 NOT PROPER INSTALATION OF FRORING

 O CLOS IN MASERIAND I SECOND IN THE FLOOR

 OF CLOS IN MASERIAND I SECOND IN THE FLOOR

 OF CLOS IN MASERIAND I SECOND IN THE PAIN COIL HAIT
 - 2 GAPS IN BASEBOARD LEFT WALL BELOW FAN COLLUNIT AND NEXT IS CLOSE TO BUTSINE WALL
- B @ELECTRICAL NO POWER AT OUTLETS
- → MARK MOOVE FAN COIL WALL PRODUCTOR FOR HACTER BEDRUCK

 → HARK MOOVE FAN COIL WALL PRODUCTOR

 → HARK MOOVE FAN COIL WALL PRODUCTOR

 → HARK MOOVE FAN COIL WALL PRODUCTOR

 → HARK MOOVE FAN COIL WALL

 → HARK MOOVE

 → HARK M
- B DILL FILLTERS ID FAN COIL WHITE DIRTY AND FULL OF DUST

TOEST BEDROOM

(WALL IS OPOSITE OF ENTRACE DOOR TO ROOM)

HASTER DEDROOM

O D WALS - DIRT HARKS ON THE WALL NEXT TO BATHROOM

THAIN BATHROOM

O MESTING STLLICONE AROUND SPOUT AND SHOWER HEAD AND TEMPERAL CONTROL

- 9 MISSING SILLICOUE PREDUND SPOUT PUD SHOWER HEAD CONTROL PUD TEMPERATURE CONTROL
- (D BED DEMAGE GRADEH ON THE COUTER TOP
 - I HOT WATER NOT ENOUGH HOT
- 12- WATER PRESURE IN POPLET HRE STALL

KITCHEN

- B- KITCHEN CABINET (BETWEEN MICROWAVE & HASTER WEDROOM DON HAS BOOKS THAT NOT FEETING PROPERLY 8 NOT IN THE SAME LEW
- 14 ALSO FEW ANOTHER DUDRES NOT IN LEWISL (LINDER SINK) AND ANOTHE
- 15- DIG PURPLE STAIN ON THE TAILS FLOOR IN FRANCE
- 16 REFRIGERBYOR DOOR SHOULD OPEN ON OPOSITE SIDE
- 17 ONE NOTH IN LIGHT FICTURE IN KITCHEN WOT WORKING
- 18 ALL WINDOWS IN CONDO ARE VERY DIRTY
 ALSO FEW THINGS FROM PDI
 ARK NOT FINISHED