

Scan to Pres
Done

Can't to mail

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5H 1A1

TEL: 416-383-9069 FAX: 416-383-9065 905-232-4637 (Fax to Amaccon)
(416) 383-4636 CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-943-2823 FAX: 905-943-2827

NAME: Gifford Boothe SUITE: 705

DEVELOPMENT NAME: 15th Ave ADDRESS: 3515 Kariya Dr M5H 1A1

REST: 416-9066449 BUS: CELL:

FAX: EMAIL:

DATE OF REQUEST: August 25/2009

SERVICE REQUEST:

1. Second Request: 2 weeks ago
2. Main Washroom shower pipe keep turning
3. upside down, and when water is on
4. the silver part pull forward and
5. sprayed wetting, cannot use shower for
6. 2 weeks now. "Second Request" to the
7. Office

8. Sign G. Boothe

9. August 25/09

10.

I authorized to enter Suite in my absence
G. Boothe

EVE
705
Scan to PASS

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: Gifford Boothe SUITE # 705

DEVELOPMENT NAME: Amelcon ADDRESS: 3515 Kariya Dr.

RES. TEL: 416 906-6449 BUS. TEL: _____ CELL: _____

FAX: _____ EMAIL: _____

DATE OF REQUEST: 2ND Request 1st Request 3 week ago
10 / April 2009

SERVICE REQUEST:

1. Lazy Suzan door need screw in door off
2. master ~~long~~ small wood missing
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. I orth, suite access

G Boothe

eve 705
Scan to Pass

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

Fax - 900 232 1357

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

DONR

TEL: 905-848-2069 FAX: 905-848-2827

NAME: BASSANT GORIN

SUITE # 705

DEVELOPMENT NAME: ELLE

ADDRESS: 3515 Kariya Dr.

RES. TEL: 905-915-2488 BUS. TEL: 647-283-2267 CELL: 416-346-8319

FAX: 905-790-9266 EMAIL: Randget.gorin@yashoo.ca

DATE OF REQUEST: May 23 - 2009

SERVICE REQUEST:

1. Floor to be repaired wood Joint Moved leading
2. a 1/2" gap in the floor. separating
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____