

We
Sales file
1806
A SANO TO PASS
system.

2007-06-10

10:00

905-896-2947

ISLAND INKJET S01

P 1/2

Pg 1

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 1A1

TEL: 905-896-2947 FAX: 905-896-2948
905-232-4837 (Fax to AMACON)

CUSTOMER CARE

ATTENTION: CUSTOMER CARE 3515 KARIYA DR.

TEL: 905-896-2947 FAX: 905-896-2948

NAME: JACK LEUNG

DATE: 1806

DEVELOPMENT NAME: EVE

ADDRESS: 3515 KARIYA DR

RETEL: 647-338-0378

REUSTEL:

CELL:

FAX:

EMAIL: JLEUNG@SANO.CA

DATE OF REQUEST: 30 July 2009

SERVICE REQUEST:

- 1. TOUCH UP ON WALL
- 2. AIR-CON VERY NOISY IN BOTH MASTER BEDROOM AND LIVING ROOM / WHEN AIR-CON IS ON THE WHOLE UNIT HAS A DISTURBING SMELL E.G. GARBAGE, FISHY SMELL, SMOKE, CIGARETTE SMOKE, A UNFRESH SMELL
- 3. VANITY CABINET BOARD MISSING (IN COMPLETE)
- 4. TWO BATHROOM TOILET BOWL FLUSHING MECHANISM NOT WORKING WELL
- 5. HARDING FLOOR HAS SQUEAKING SOUND AND STICKING
- 6. KITCHEN FLOOR TILE INSTALLED POORLY AND UNBALANCE AND COLOUR DIFFER FROM ONE TO ANOTHER

PG (2)

AMACON DEVELOPMENT**AMACON SERVICE REQUEST FORM**

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5H 1K1

TEL: 416-332-8888 FAX: 416-332-8888

905-232-4637 (Fax to Amaccon)

ATTENTION CUSTOMER CARE: 3515 KARNIA DR.

CUSTOMER CARE

TEL: 905-948-2869 FAX: 905-948-2877

NAME: JACK LEUNG

DEVELOPMENT NAME: EVE

SLATE #

1806

RES. TEL: 416-338-0378

ADDRESS:

3515 KARNIA DR.

FAX:

EMAIL:

JLEUNG@SHAW.CA

DATE OF REQUEST:

30 July 2009

SERVICE REQUEST:

- 1. THERE ARE NO LIGHT SWITCH IN MASTER BEDROOM
- 2. REFRIGERATOR DOORS ARE NOT LOGICAL
- 3. VENT IN MASTER BEDROOM VERY NOISY AND NOT WORKING WELL
- 4. BATH TUB FAUCET IN MAIN BATHROOM VERY TOP LOOSE (FEEL LIKE FALLING APART)
- 5. CRACK RUN DOWN FROM CEILING TO MASTER BDRM
- 6. GRILL DEFLECTOR NOT ROTATIONAL
- 10. SEVERAL DEFLECT ON FOOTBOARDS THRU OUT THE UNIT

606
1806
Scantlas
DOWR

AMACON SERVICE REQUEST FORM
PLEASE MAIL, FAX OR SUBMIT ON-LINE
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE
2 HARBOUR STREET, TORONTO, ON M5J 3B1
TEL: 416-369-9069 FAX: 416-369-9068
www.amacon.com

NAME: DOMAGALSKA, EWA Suite #:- 1806

DEVELOPMENT NAME: AMACON

ADDRESS: 3515 Kariya Dr.

RES. TEL: 647-262-9082 BUS. TEL: _____

CELL: _____ FAX: _____

DATE OF REQUEST: Feb 5/09

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. The main bathroom door
does NOT close / nor lock

2. _____

3. _____

4. _____

1806

Newowner
Ref: 1**AMACON DEVELOPMENT****AMACON SERVICE REQUEST FORM**

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9069
OR (905) 882-4636905-232-4637 (FAX NO AMACON)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2327

NAME: JACK LEUNG

SUITE # 1806

DEVELOPMENT NAME: EVE

ADDRESS: 3515 KARIYA DR

RES. TEL: 647-338-0378

BUS. TEL:

CELL:

FAX:

EMAIL: JLEUNG@SHAW.CA

DATE OF REQUEST:

30 July 2009

SERVICE REQUEST:

1. TOUCH UP ON WALL

2. AIR-CON VERY NOISY IN BOTH MASTER BEDROOM
AND LIVING ROOM / WHEN AIR-CON IS ON, THE4. WHOLE UNIT HAS A DISTURBING SMELL E.G. GARBAGE,
FISHY SMELL, SMOKE, A CIGARETTE VERY

5. VANITY CABINET BOARD MISSING (IN COMPLETE)

7. TWO BATHROOM TOILET BOWL FLUSHING MECHANISM

8. NOT WORKING WELL

9. HARDING FLOOR HAS SREAKING SOUND AND STICKING

10. KITCHEN FLOOR TILE INSTALLED POORLY AND
UNBALANCE AND COLOUR DIFFER FROM ONE TO ANOTHER

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9069
(905) 982-4636

905-232-4637 (FAX NO AMACON)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: JACK LEUNG

SUITE # 1806

DEVELOPMENT NAME: EVE

ADDRESS: 3515 KARIYA DR

RES. TEL: 416-338-0378

BUS. TEL:

CELL:

FAX:

EMAIL: JLEUNG@SHAW.CA

DATE OF REQUEST: 30 July 2009

SERVICE REQUEST:

1. THERE ARE NO LIGHT SWITCH IN MASTER BEDROOM
2. REFRIGERATOR DOORS ARE NOT LOGICAL
3. VENT IN MASTER BEDROOM VERY NOISY AND NOT WORKING WELL
4. BATHTUB FAUCET IN MAIN BATHROOM VERY LOSE (FEEL LIKE FALLING APART)
5. DASH WASHER HAS NO INSULATION (STEAMY & HOT)
6. CRACK RUN DOWN FROM CEILING TO MASTER BDR
7. GRILL DEFLECTOR NOT ROTATIONAL
8. SEVERAL DEFLECT ON FOOTBOARD THRU OUT THE UNIT