

RECEIVED

SEP 22 2010

He failed



EV 2005

UPLOAD to AWS

lost of creativity

01/17/2011

AMACON DEVELOPMENT

AMAZON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMARON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 3B1

TEL: 416-368-9068 FAX: 416-368-9065

12-00000-4636

905-232-4637 (Fax to AmeriCon)
CUSTOMER CARE

CUSTOMER CHAIR

ATTENTION CUSTOMER CARE: 800-5 KARTYA DE

TEL: 905-845-2569 FAX: 905-845-2527

NAME Ariya Naweed

SUITE 2005

DEVELOPMENT NAME: Eve

ADDRESS: 3515, Kariya Drive

RETE: 905 232 2499. RETE:

QUESTIONS

CS-1

FAX: _____ E-Mail: _____

DATE OF REQUEST: Sep 15, 2010

SERVICE REQUEST:

1. Wall board cracking.
2. Wall socket loose / wall socket broken.
3. ~~Vacuum~~ Vacuum under the floor plank. Floor riser
4. Bathroom tub tap dripping.
- 5.
- 6.
- 7.
- 8.
- 9.
- 10.

TH. m. coming off wall in Dining Rm.
Living en receptacle receptacle Loose
Bed Room F 1 broken