

Friday, September 14, 2012

Natalia Baricevic & Nick Josef Baricevic  
1250 White Oaks Blvd  
Oakville Ontario L6H 2C2

**Re: The Residences At Parkside Village #605**

---

Dear Natalia Baricevic & Nick Josef Baricevic,

As per your scheduled PDI, **Thursday September 13<sup>th</sup>, 2012 at 1:30pm**; you had encountered an issue with your exhaust fan and posted the question whether the hole should be sealed or insulated. In regards to that question, the exhaust fan is not required to be insulated or sealed as the exhaust piping is sealed at the joints\connections and is within a bulkhead that is directly connected to the exterior.

If you have any further questions and or concerns please feel free to contact us

Sincerely,

Amacon Customer Care



**A M A C O N**

L I V E   W E L L

**Warranty Services  
Work Order**

Phone: (905) 232-4636 Fax:(905) 232-4637

<b>Location</b>	<u>The Residences At Parkside Village - Tower: 1 - Unit: 605</u> <u>1250 WHITE OAKS BLVD</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>14Sept12</u>
<b>Contact Name(s)</b>	<u>NATALIA BARICEVIC and NICK JOSEF BARICEVIC</u>
<b>Contact Telephone#</b>	<u>Res: (905) 337-8771</u>
<b>Company:</b>	<u>Amacon Customer Care Head Office</u>
<b>Attention:</b>	<u>Grahme Walsh</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>4 (16-) 369--906</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:					
Deficiency Number	Issue		Repair Deadline	Appointment Date/Time	Notes
27844	KITCHEN- NOTE-CLIENT WOULD LIKE TO KNOW IF THE HOLE WHERE THE EXHAUST FAN IN KITCHEN EXITS SHOULD BE SEALED OR INSULATED.		16Sep12		Issued a letter in response to their question 9/14/12

Date Completed:

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back - Forms Menu](#)

ID# 27844 The Residences At Parkside Village Ph 1 Lot 605

## Chantal Andrade

---

**From:** Grahme Walsh  
**Sent:** September-14-12 10:33 AM  
**To:** Chantal Andrade  
**Subject:** Parkside - Letter

<a href="#">13Sept12</a>	605	1	The Residences At Parkside Village	PDI 27844	KITCHEN-NOTE-CLIENT WOULD LIKE TO KNOW IF THE HOLE WHERE THE EXHAUST FAN IN KITCHEN EXITS SHOULD BE SEALED OR INSULATED.	NATALIA BARICEVIC NICK JOSEF BARICEVIC	1250 WHITE OAKS BLVD	(905) 337-8771	<a href="#">NoAppoint.</a>	1
--------------------------	-----	---	------------------------------------	-----------	--	--	----------------------	----------------	----------------------------	---

Please produce a letter for the homeowner in 605,

The exhaust fan does not required to be insulated or sealed as the exhaust piping is sealed at the joints/connections and is within a bulhead that is directly connected to the exterior

**GRAHME WALSH**  
Manager, Construction Contracts/ Customer Care



L I V E   W E L L

37 Bay Street, Suite 400,  
Toronto, ON, M5J 3B2  
Tel. 416.369.9069  
Fax. 416.369.9068  
Email. [gwalsh@amacon.com](mailto:gwalsh@amacon.com)  
Web. [www.amacon.com](http://www.amacon.com)

This e-mail is intended only for the named recipient(s) and may contain information that is privileged, confidential and/or exempt from disclosure under applicable law. No waiver of privilege, confidence or otherwise is intended by virtue of communication via the internet. Any unauthorized use, dissemination or copying is strictly prohibited. If you have received this e-mail in error, or are not named as a recipient, please immediately notify the sender and destroy all copies of this e-mail. Please be aware that internet communications are subject to the risk of data corruption and other transmission errors. For information of extraordinary sensitivity, we recommend that our clients use encryption software when they communicate with us by e-mail.