

Monday, November 19th, 2012

4065 Brickstone Mews
Mississauga Ontario L5B 0G3

Dear Annette Marcaro,

Re: Residences at Parkside Village #206, regarding the submitted 30 Day Form

In regards to your submitted 30 day form, the deficiencies from your list have been grouped into the following categories:

A. ITEMS TO BE RECTIFIED

Arrangements will be made for the items in this category to be repaired.

B. ITEMS TO BE INVESTIGATED

Items in this category require further investigation by an Amacon Customer Care Representative. Once these items have been investigated; Amacon will advise if the items will be repaired or if they will not be remedied pursuant to the warranty and the rationale for such a decision.

C. ITEMS TO BE REVIEWED ON PRE-DELIVERY INSPECTION

*As Amacon is not responsible for regular wear and tear, certain items will **only** be rectified if they were **noted on your original Pre-Delivery Inspection** (i.e. scratches, etc.).*

D. ITEMS THAT WILL NOT BE RECTIFIED

Certain items will not be rectified because they:

- ♦ *Are not warrantable*
- ♦ *Meet or exceed the Industry Standards allowable*
- ♦ *Were caused by a homeowner's failure to follow maintenance procedures, or to mitigate any damage.*

E. ITEMS TO BE DIRECTED TO THE CONDOMINIUM CORPORATION

*Exterior areas, such as your balcony, are considered common property. This means that you have the exclusive right to use this area, but it is still considered to be common property. As common property is the property of all owners at **Residences at Parkside Village** we must receive requests in this regard from the Condominium Corporation as they act on behalf of all owners. Please be assured that the Condominium Corporation will contact us regarding any necessary items.*

***Please note that cracks in drywall will only be repaired if they are due to settlement. Drywall deficiencies to be repaired will be left sanded and ready to paint. Amacon does not repaint.**

A. ITEMS TO BE RECTIFIED

ITEM	LOCATION	DESCRIPTION
1	Bedroom Door	Bottom left corner of right mirror door is chipped
3	Hallway	Grout missing from tile at entrance door.

E. ITEMS TO BE DIRECTED TO THE CONDOMINIUM CORPORATION

ITEM	LOCATION	DESCRIPTION
2	Hall way	Outside facia of door entering unit is scuffed.

Should you have any further questions or concerns please refer to the **Residences at Parkside Village** homeowner's manual that was provided, or contact the undersigned.

Sincerely,

Amazon Customer Care

November 19th, 2012

Re: Residences #206 30 Day #1

Issue: Bedroom- bottom left corner of right mirror door is chipped.

Response: This item will be rectified out of courtesy for you the homeowner, as this item was never listed on the PDI:



November 19th, 2012

Re: Residences #206 30 Day #2

Issue: Door - Outside fascia of door entering unit is scuffed.

Response: Please inform your Property Management of this issue.

November 19th, 2012

Re: Residences #206 30 Day #3

Issue: Hallway - Grout missing from tile at entrance door.

Response: This item will be rectified.