

**Outstanding Deficiencies
For Frendel Kitchens Limited
For Heathwood Homes (Huron) Limited**

Print Session: 2917 - Printed: 11Jul22

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
05Jan22	286C-20	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~ONE CHIP ON SINK CABINET ON FLOOR CLOSE TO SINK SUPPORT TRIM.	131118	07Jun22	187	
14Feb22	190E-30	1	Heathwood Homes (Huron) Limited	1 Year	MASTER ENSUITE- CABINETRY~ITEM # 3 KICKPLATE NOT ALIGNED WITH VANITY SIDE PANEL, CABINET DOOR PANEL ON RIGHT NOT LEVELLED. TO BE ADJUSTED.	134307	11May22	147	
16Mar22	242	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BUILT IN OVEN- THE END GABLE IS DAMAGED, AT THE BACK AND BOTTOM	137076	Cancelled	117	
25Mar22	285B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE ANGLE CABINET- DOORS ARE GAPPED	138055	25May22	108	
25Mar22	285B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, LEFT OF SINK- HINGE CREAKING WHEN OPENED	138056	25May22	108	
25Mar22	285B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND, LEFT CORNER TRIM- GLUE IS VISIBLE ON EDGE	138057	25May22	108	
25Mar22	285B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- RIGHT AND LEFT SIDES, PANELS CHIPPED AT THE FLOOR	138058	25May22	108	
06Apr22	217	2	Heathwood Homes (Huron) Limited	PDI	MAIN BATHROOM- CABINETRY~COUNTERTOP SIDE SPLASH - RETURN EDGE PIECES HAS SHARP EDGE	139082	18May22	96	
06Apr22	218	2	Heathwood Homes (Huron) Limited	PDI	ENSUITE 4- CABINETRY~SINK CABINET BROKEN, BACK BOTTOM CORNER, AS TAGGED	139018	25May22	96	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND, BACK SIDE- PANEL IS CHIPPED ALONG BOTTOM, SCRATCHES NEAR LEFT SIDE, AS TAGGED.	139271	30May22	91	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND, RIGHT SIDE- VERTICAL CRACK AT CENTRE, AS TAGGED.	139270	30May22	91	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~SERVERY UPPER- ADJUST GAP BETWEEN DOORS, AS TAGGED.	139268	30May22	91	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~SINK CABINET- FRONT EDGE OF CABINET FLOOR IS CHIPPED, LEFT SIDE	139288	30May22	91	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	SERVERY- CABINETRY~UPPER AND LOWER DOORS GAPPED/ NOT LEVEL, PLEASE ADJUST.	139265	30May22	91	
11Apr22	221	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER, RIGHT OF HOODFAN- SCRATCHES IN SURFACE, AS TAGGED.	139269	30May22	91	
14Apr22	224	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BASE CABINET, RIGHT OF FRIDGE- SHELF IS CHIPPED, BACK LEFT.	139743	30May22	88	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
14Apr22	224	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~COUNTERTOP-LEFT LAMINATE SPLASH IS TOO LONG, SHARP EDGE	139759	30May22	88	
14Apr22	224	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- BOTH CORNER TRIM PIECES HAVE WHITE GLUE AT EDGES	139742	30May22	88	
14Apr22	224	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~TOE KICK IS CUT TOO SHORT, LEFT SIDE	139758	30May22	88	
14Apr22	224	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER, RIGHT OF SINK- DAMAGED AT BACK	139741	30May22	88	
19Apr22	284C-14	2	Heathwood Homes (Huron) Limited	30-Day	MAIN BATHROOM- Cabinets - Kitchen & Bathroom- CABINETRY~ITEM # 2 CHIP ON COUNTERTOP ON LEFT SIDE FACE FRAME/ EASED EDGE	139899	NoAppoint.	83	
19Apr22	284C-14	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~ITEM # 4 ISLAND BOTH SIDE GABLES HAS ROUGH EDGES AT THE BOTTOM	139896	NoAppoint.	83	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BACK OF ISLAND- CHIPPING ON TOP AT COUNTERTOP, AND BASE AT FLOOR, AS TAGGED	140125	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, LEFT OF COOKTOP- SCRATCHES ON LEFT DOOR, AS TAGGED	140128	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, RIGHT OF ENTRY- DAMAGED BELOW COUNTERTOP, AS TAGGED	140122	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~INSIDE DISHWASHER OPENING- SIDE OF SINK CABINET DAMAGED, AT THE BACK	140123	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- CORNER SUPPORTS HAVE GAP, UNFINISHED AT TOP AT COUNTERTOP, BOTH SIDES	140124	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- VISIBLE NAIL HOLES ON BOTH BACK EDGE TRIM PIECES	140126	18May22	80	
22Apr22	213	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~TOE KICK TO BE INSTALLED- STOVE/OVEN SIDE OF KITCHEN, AS TAGGED	140127	18May22	80	
28Apr22	205	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- #1- Upper cabinet box, right gable on left side of sink dented	140511	29Jun22	75	
28Apr22	205	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- #2- Door right of corner upper chipped	140515	29Jun22	75	
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BANK OF DRAWERS - 3RD DRAWER TOO STIFF	140748	30May22	73	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~CABINET UNDER RIGHT SIDE SINK- ONE SCREW HOLE SHOWING ON CABINET FLOOR CLOSE TO BACK PANEL	140769	30May22	73	
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~EXTRA GAP BETWEEN LAZY SUSAN CABINET DOOR PANELS	140747	30May22	73	
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND SINK CABINET- FACE FRAME TO BE INSTALLED ON LEFT SIDE OF SINK CABINET, AND NAILS STICKING OUT AT THE BOTTOM ON ISLAND BACK PANEL	140746	30May22	73	
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	BASEMENT BATHROOM- CABINETRY~SINK CABINET RIGHT SIDE PANEL GETS STUCK ON COUNTERTOP	140735	30May22	73	
29Apr22	222	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~SINK CABINET- SMALL CHIP IN THE MIDDLE OF CABINET FLOOR NEAR FRONT	140745	30May22	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, RIGHT OF STOVE- CHIPPED AT FRONT CORNER, AS TAGGED	140534	Cancelled	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~CORNER TRIM, RIGHT SIDE- PAINT CHIPPED OFF, BOTTOM AND TOP, AS TAGGED	140537	Cancelled	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- LEFT BACK, PANEL IS CRACKED, AS TAGGED	140538	Cancelled	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- LEFT CORNER TRIM- NAIL HOLE NEAR MIDDLE, AS TAGGED	140539	Cancelled	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- LEFT OF DISHWASHER- EDGE IS GOUGED, AS TAGGED	140536	Cancelled	73	
29Apr22	223	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, RIGHT OF STOVE- CHIP ON BOTTOM EDGE, RIGHT SIDE, AS TAGGED	140535	Cancelled	73	
03May22	286B-10	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ALL UPPER AND LOWER DOORS ARE GAPPED OR UNEVEN, REQUIRE ADJUSTMENT	141139	NoAppoint.	69	
03May22	286B-10	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- BACK PANEL IS CHIPPED AT FLOOR, NEAR RIGHT CORNER	141135	NoAppoint.	69	
03May22	286B-10	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- CORNER EDGE IS UNFINISHED, LEFT OF DISHWASHER	141134	NoAppoint.	69	
03May22	286B-10	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- DISHWASHER CABINET- UNFINISHED PIECE INSTALLED AT TOP.	141137	NoAppoint.	69	
09May22	271	2	Heathwood Homes (Huron) Limited	30-Day	MAIN BATHROOM- Cabinets - Kitchen & Bathroom- Item #13- Grey Stain on counter top near sink	141428	NoAppoint.	63	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BANK OF DRAWERS- CHIPS ON DRAWERS FLOOR CLOSE TO FRONT PANEL	141521	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BASE CABINET LEFT SIDE OF STOVE, CHIP ON BACK PANEL	141520	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~CHIPS ON BACK PANEL OF LAZY SUSAN CABINET	141522	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- CHIPPED ALONG FLOOR BOTH SIDES AND THE BACK	141518	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- CHIPS ON BACK PANEL NEAR GRANITE	141517	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~MULTIPLE CHIPS AROUND PLUMBING SUPPLY, AND CLOSE TO BACK PANEL	141532	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~NAIL HOLES SHOWING ON KICKPLATE AT SINK CABINET	141519	07Jun22	63	
09May22	286B-13	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~SINK CABINET- CHIPS ON CABINET FLOOR CLOSE TO BACK PANEL	141527	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BASE ANGLE CABINET- INTERIOR, BACK PANEL BROKEN	141458	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~COUNTERTOP, RIGHT AND LEFT SPLASH- SHARP EDGE ON SIDE, CORNER SHARP AND LAMINATE ISN'T GLUED	141466	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND, LEFT OF DISHWASHER, UNFINISHED EDGES AT CORNER	141457	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- BACK LEFT CORNER BEAD IS BROKEN	141455	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- LEFT SIDE, CHIPPED ALONG BOTTOM EDGE	141456	07Jun22	63	
09May22	286B-14	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- RIGHT OF SINK- EDGE IS UNFINISHED <i>H/O out of country until August 2022</i>	141454	07Jun22	63	
12May22	224	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BACK OF ISLAND- WHITE GLUE SHOWING AT CORNER TRIM ON LEFT AND RIGHT SIDES, AS TAGGED.	141819	30May22	60	
12May22	224	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, RIGHT OF SINK- CRACKED AT THE BACK, AT WALL, AS TAGGED	141818	30May22	60	
17May22	286B-10	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE ANGLE CABINET- STAPLES STICKING OUT, BACK OF CABINET FLOOR, AS TAGGED	142213	NoAppoint.	55	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
17May22	286B-10	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BOTTOM DRAWER- RUBBING, NOT CLOSING PROPERLY, AS TAGGED	142215	NoAppoint.	55	
17May22	286B-10	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- CHIP AT FLOOR, ON RIGHT SIDE, AS TAGGED	142212	NoAppoint.	55	
17May22	286B-10	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, AT BREAKFAST AREA- SIDE OF CABINET IS CHIPPED, AT THE WALL, AS TAGGED.	142216	NoAppoint.	55	
17May22	286B-10	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, LEFT OF CORNER- LEFT DOOR HINGE CATCHING, AS TAGGED. GAP BETWEEN DOORS TOO LARGE, TO BE ADJUSTED, AS TAGGED.	142214	NoAppoint.	55	
25May22	286B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, RIGHT OF STOVE- INSTALL SHELF	143030	07Jun22	47	
25May22	286B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- BACK PANEL IS CHIPPED ALONG THE FLOOR, AS TAGGED	143029	07Jun22	47	
25May22	286B-13	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER ANGLE CABINET- GAP ON DOOR, PLEASE ADJUST, AS TAGGED	143031	07Jun22	47	
25May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	MAIN BATHROOM- CABINETRY~COUNTERTOP- BOTH LEFT AND RIGHT SIDE SPLASH - SHARP EDGES SIDE AND NOT GLUED PROPERLY	143068	07Jun22	47	
25May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND - RIGHT SIDE OF SINK OPENING- MOLDING NOT INSTALLED TO ISLAND	143055	07Jun22	47	
25May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND BACK PANEL, RIGHT SIDE MOLDING IS LOOSE AT THE BOTTOM	143054	07Jun22	47	
25May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND SIDE GABLE FACING BREAKFAST AREA, HAS CHIPS AT BOTTOM	143057	07Jun22	47	
25May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- LEFT SIDE OF DISHWASHER- MESSY FINISH AT THE CORNER ON FACE FRAME	143056	07Jun22	47	
26May22	286B-14	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~UPPER ANGLE CABINET - EDGE TAPE HAS ROUGH EDGES AT THE BOTTOM	143084	07Jun22	47	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~3 TAGS - MIDDLE CABINET- CHIP ON LEFT SIDE, CABINET FLOOR CLOSE TO BACK AND FRONT EDGE	143299	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND - SMALL CABINET RIGHT SIDE OF BANK OF DRAWERS- CHIPPED AT THE BOTTOM CORNER	143267	NoAppoint.	45	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND BACK GABLE FACING GREAT ROOM - CHIPS ON TOP NEAR COUNTERTOP	143271	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND RIGHT SIDE GABLE ON OUTLET SIDE - PANEL CHIPPED AT THE FLOOR	143269	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- MULTIPLE NAIL HOLES SHOWING ON ALL CORNER TRIMS	143270	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- RIGHT AND LEFT SIDE OF DISHWASHER - CHIPPED ALONG CORNERS	143268	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~ONE CHIP ON DRAWER FLOOR CLOSE TO FRONT	143298	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~POTS AND PANS DRAWER LEFT SIDE OF STOVE- CHIP ON SECOND AND THIRD DRAWERS CLOSE TO FRONT	143266	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~POTS AND PANS DRAWERS RIGHT SIDE OF STOVE- CHIPS ON ALL DRAWERS FLOOR CLOSE TO FRONT	143265	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~SINK CABINET ON RIGHT HAND SIDE- CHIP AT FRONT EDGE AND AT CABINET FLOOR CLOSE TO BACK	143284	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~SINK CABINET ON RIGHT SIDE- THREE CHIPS ON CABINET FRONT EDGE	143297	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER BOX LEFT SIDE OF HOOD FAN, CHIP ON EXTERIOR SIDE	143263	NoAppoint.	45	
27May22	225	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER BOX RIGHT SIDE OF HOOD FAN, CHIP ON EXTERIOR SIDE	143264	NoAppoint.	45	
30May22	227	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BOTTOM DRAWER, LEFT OF MICROWAVE- CHIPPING AT FRONT EDGE	143351	29Jun22	42	
30May22	227	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~DRAWER BELOW MICROWAVE- 2 CHIPS IN LEFT FRONT CORNER	143350	29Jun22	42	
30May22	227	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~LEFT SINK CABINET- LARGE GAP BETWEEN DOORS	143389	29Jun22	42	
30May22	227	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~RIGHT DOOR IS TOO HIGH, HITTING UNDERSIDE OF STONE COUNTERTOP	143364	29Jun22	42	
30May22	227	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER CABINET, AT BREAKFAST AREA- CHIP ON SIDE, AT FRONT OF CABINET.	143352	29Jun22	42	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ RIGHT OF WALL OVEN- UPPER DOORS GAPPED, REQUIRE ADJUSTMENT.	143519	29Jun22	41	
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	SERVERY- CABINETRY~LEFT BASE CABINET- DOORS ARE GAPPED	143524	29Jun22	41	
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-RECYCLING PULL OUT, RIGHT OF DISHWASHER- TOO TIGHT, REQUIRES ADJUSTMENT	143520	29Jun22	41	
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~RIGHT OF FRIDGE- UPPER DOORS GAPPED, REQUIRE ADJUSTMENT	143517	29Jun22	41	
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~RIGHT OF HOODFAN- UPPER DOORS GAPPED, REQUIRE ADJUSTMENT	143518	29Jun22	41	
31May22	301	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-WALL OVEN- CHIP ON OUTSIDE EDGE, LEFT SIDE OF FRONT FACE	143521	29Jun22	41	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-BANK OF DRAWERS- CHIP ON 1ST, 2ND AND 3RD DRAWER FLOOR CLOSE FRONT AND SECOND DRAWER ON RIGHT SIDE	144214	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-BASE CABINET - RIGHT SIDE OF BANK OF DRAWERS - SECOND CABINET - CHIP ON ADJUSTABLE SHELF FRONT EDGE	144213	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-CROWN MOLDING- MULTIPLE NAIL HOLES SHOWING IN DIFFERENT AREAS AS TAGGED	144207	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-LAZY SUSAN CABINET- SECOND SHELF- CHIPS ON FRONT EDGE ON RIGHT HAND SIDE	144209	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-PANTRY MIDDLE CABINET- MISSING ONE PLASTIC SHELF BRACKET ON RIGHT HAND SIDE	144215	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~POTS AND PANS DRAWER RIGHT SIDE OF STOVE- CHIPS ON 1ST, AND 2ND DRAWERS FLOOR CLOSE TO FRONT	144212	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-POTS AND PANS DRAWERS LEFT SIDE OF STOVE- CHIPS ON EACH DRAWER FLOOR AS TAGGED	144210	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~POTS AND PANS SECOND DRAWER- CHIP ON FLOOR CLOSE TO FRONT	144211	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER BOX - RIGHT SIDE OF HOOD FAN- RIGHT SIDE PANEL CHIPPED AT THE BOTTOM NEAR SOFT DOOR BUMPER	144208	29Jun22	34	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER BOXES ON BOTH SIDES OF HOOD FAN ON EXTERIOR SIDE HAS ROUGH EDGES/ NOT ENOUGH PAINT AT THE BOTTOM	144206	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~VANITY - CABINET ATTACHED TO SHOWER WALL- CHIP ON FLOOR CLOSE TO BACK PANEL	144243	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~VANITY DRAWERS- CHIP ON SECOND AND THIRD DRAWER FLOOR CLOSE TO FRONT	144244	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	ENSUITE 2- CABINETRY~VANITY- CHIPS ON BOTH DRAWERS FLOOR CLOSE TO FRONT PANEL	144239	29Jun22	34	
07Jun22	304	2	Heathwood Homes (Huron) Limited	Quality Control	ENSUITE 2- CABINETRY~VANITY- SINK CABINET- CHIP ON FLOOR CLOSE TO BACK PANEL	144238	29Jun22	34	
08Jun22	242	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- #3- Repeated from PDI - oven cabinet end gable damaged at wall and at floor - Parts already on order with Frendel	144301	NoAppoint.	33	
08Jun22	303	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BANK OF DRAWERS REQUIRE ADJUSTMENTS, UNEVEN GAPS BETWEEN THEM.TOP DRAWER HITTING GRANITE.	144410	06Jul22	33	
08Jun22	303	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~BOTTOM VANITY DRAWER- CHIPPED IN FRONT RIGHT CORNER.	144415	06Jul22	33	
08Jun22	303	2	Heathwood Homes (Huron) Limited	Quality Control	SERVERY- CABINETRY~RIGHT CABINET NEEDS ADJUSTMENT, HITTING BOTTOM OF COUNTERTOP	144405	06Jul22	33	
08Jun22	303	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~SUPPORT AT BACK OF COOKTOP IS BROKEN, COUNTERTOP INSTALLED...	144464	06Jul22	33	
08Jun22	303	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~TOE KICK NOT INSTALLED	144411	06Jul22	33	
10Jun22	247	2	Heathwood Homes (Huron) Limited	1 Year	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~ITEM # 9 DRAWER AT THE BOTTOM OF BUILT IN MICROWAVE & OVEN - CHIP IN THE MIDDLE ON DRAWER FLOOR	144506	NoAppoint.	31	
10Jun22	284C-15	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~ITEM # 2 BANK OF DRAWERS ON RIGHT SIDE OF FRIDGE - EXTRA GAP BETWEEN COUNTERTOP AND CABINET (AS PER HEATHWOOD TECH INSPECTION TRADE REQUIRED)	144482	NoAppoint.	61	
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~BOTH VANITIES- NAILS, VISIBLE NAILS HOLES IN TOEKICK.	144520	06Jul22	31	
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~DRAWER AT WALL OVEN NOT ALIGNED PROPERLY.	144542	06Jul22	31	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND, RIGHT GABLE- SCRATCH NEAR BOTTOM CORNER	144540	06Jul22	31	
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~LEFT VANITY, BASE CABINET, BESIDE WINDOW- CHIP ON FLOOR, FRONT LEFT CORNER.	144519	06Jul22	31	
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~TOP DRAWER AND WASTE RECEPTICLE CABINET DOORS HIT TOGETHER, TO ADJUST	144543	06Jul22	31	
10Jun22	305	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER DOORS, RIGHT OF WALL OVEN- DOORS NOT LEVEL	144541	06Jul22	31	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- SMALL CABINET RIGHT SIDE OF DRAWERS- TWO CHIPS - ONE AT THE BOTTOM CORNER, 2ND ABOVE UPPER HINGE	144675	NoAppoint.	28	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~KITCHEN ISLAND - MULTIPLE NAIL HOLES SHOWING ON MOLDING ON ALL CORNERS	144676	NoAppoint.	28	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY KICKPLATE - VISIBLE LINE ON RIGHT HAND SIDE	144705	NoAppoint.	28	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	SHARED BATHROOM- CABINETRY~VANITY LEFT SIDE SPLASH- RETURN EDGE PIECE HAS SHARP EDGE	144698	NoAppoint.	28	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY- RIGHT SIDE SINK CABINET- EXTRA GAP BETWEEN COUNTERTOP AND CABINET FACE FRAME	144706	NoAppoint.	28	
13Jun22	225	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY- SINK CABINET NEAR SHOWER- FACE FRAME BROKEN, AND FACE FRAME NOT ATTACHED TO COUNTERTOP PROPERLY	144707	NoAppoint.	28	
13Jun22	257	2	Heathwood Homes (Huron) Limited	1 Year	KITCHEN- Cabinets - Kitchen & Bathroom- Item #9 Gap between both fridge gables and floor	144600	NoAppoint.	28	
14Jun22	220	2	Heathwood Homes (Huron) Limited	30-Day	KITCHEN- Cabinets - Kitchen & Bathroom- Item #9 Top two drawers at island are hard to close, to be adjusted	144740	NoAppoint.	27	
14Jun22	274	2	Heathwood Homes (Huron) Limited	Interval	KITCHEN- Cabinets - Kitchen & Bathroom- Edge of lower outer gable cracked	144739	29Jun22	27	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~ADJUST GAP BETWEEN DOORS, BELOW LEFT SINK	144776	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BASE CABINET, AT BREAKFAST AREA- GLUE VISABLE ALONG FRONT EDGE TAPE	144800	29Jun22	26	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~DRAWER BELOW MICROWAVE- 2 CHIPS IN LEFT FRONT CORNER	144803	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~FILLER STRIP ABOVE FRIDGE- UNFINISHED EDGE, REQUIRES EDGE TAPE	144799	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~INSIDE BOTTOM DRAWER, LEFT OF MICROWAVE- CHIPPING ALONG FRONT EDGE	144802	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	SHARED BATHROOM- CABINETRY~RIGHT CABINET DOOR IS HITTING UNDERSIDE OF COUNTERTOP	144774	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	BASEMENT BATHROOM- CABINETRY~RIGHT DOOR IS HITTING UNDERSIDE OF COUNTERTOP	144781	29Jun22	26	
15Jun22	227	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET AT BREAKFAST AREA- CHIP ON EXTERIOR FRONT LEFT CORNER. ADJUST GAP ON LEFT DOOR.	144801	29Jun22	26	
15Jun22	270	2	Heathwood Homes (Huron) Limited	Interval	KITCHEN- Cabinets - Kitchen & Bathroom- Gap between back island gable and floor and no aligned	144767	NoAppoint.	26	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~SHARED BATHROOM ATTACHED TO BED #3 & 4 - VANITY SIDE SPLASH ON LEFT SIDE OF SINK HAS CHIP AT FRONT EDGE	144886	29Jun22	25	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~SHARED BATHROOM ATTACHED TO BED#2 - VANITY- CABINET LEFT SIDE OF SINK- TWO CHIPS AT FRONT EDGE, AND ON CABINET FLOOR CLOSE TO BACK	144888	29Jun22	25	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~SHARED BATHROOM ATTACHED TO BED#2- VANITY- CABINET RIGHT SIDE OF SINK- CHIPPED AT FRONT EDGE	144887	29Jun22	25	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER BOX LEFT SIDE OF HOOD FAN- EXTERIOR SIDE PANEL CHIPPED AT THE BOTTOM	144878	29Jun22	25	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~VANITY- CABINET IN MIDDLE - CHIP ON CABINET FLOOR CLOSE TO BACK	144897	29Jun22	25	
16Jun22	309	2	Heathwood Homes (Huron) Limited	Quality Control	MASTER ENSUITE- CABINETRY~VANITY- SINK CABINET NEAR SHOWER- CHIP ON CABINET FLOOR CLOSE TO BACK PANEL	144896	29Jun22	25	
17Jun22	310	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ALIGN/ ADJUST ALL DOORS, DRAWERS. INSTALL MISSING DOOR BUMPERS, 3 IN PANTRY, 1 IN SERVERY, AS TAGGED	145089	29Jun22	24	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
17Jun22	310	2	Heathwood Homes (Huron) Limited	Quality Control	SHARED BATHROOM- CABINETRY~RIGHT DRAWER- CHIP ON FLOOR, IN FRONT CORNER	145067	29Jun22	24	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	SERVERY- CABINETRY~BASE RIGHT DOOR- SMALL CUT IN FINISH, TOP EDGE OF DOOR	145151	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~LEFT OF DISHWASHER- CHIPS ON FINISHED EDGE	145157	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~LIGHT VALANCE, LEFT OF STOVE- DENTS BELOW GLASS DOOR, CRACKED AT WALL	145156	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~MICROWAVE CABINET, TOP LEFT OF FRAME- VERTICAL CRACK VISIBLE	145153	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, AT RIGHT WALL- CHIP INSIDE CABINET, ON RIGHT SIDE, AT FRONT.	145154	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET, LEFT OF STOVE- EXTRA SCREW VISIBLE, INSIDE CABINET, RIGHT BOTTOM SIDE AT FRONT	145155	29Jun22	21	
20Jun22	302	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~VISIBLE NAIL HOLES ON TOEKICK, INCLUDING PANTRY, ISLAND AND SERVERY	145158	29Jun22	21	
21Jun22	301	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~LEFT OF SINK- END CAP NOT SECURED TO CABINET	145217	29Jun22	20	
21Jun22	301	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PULL OUT DRAWER FOR WASTE RECEPTICLE IS TOO TIGHT, TO BE ADJUSTED. ADJUST ALL CABINET DOORS, GAPPING AT FRONT. BASE CABINET, BESIDE FRIDGE- BOTH DOORS CANNOT OPEN, HITTING UNDERSIDE OF COUNTERTOP	145219	29Jun22	20	
21Jun22	301	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~WALL OVEN- CHIP ON OUTSIDE EDGE, LEFT SIDE OF FRONT FACE	145218	29Jun22	20	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	LAUNDRY ROOM- CABINETRY~CABINET ON LEFT SIDE- SCREW HOLES SHOWING ON BACK PANELS	145345	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND BACK PANEL FACING GREAT ROOM- 5 TAGS- 3 TAGS FOR CHIPS AND 2 FOR LOW PAINT	145309	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND DISHWASHER OPENING- CHIPS AT THE BOTTOM OF SIDE PANELS	145306	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND LEFT SIDE GABLE CHIPPED AT THE BOTTOM	145305	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND SIDE GABLE FACING BREAKFAST AREA- CHIPPED AT THE BOTTOM	145300	NoAppoint.	19	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND- WASTE DRAWER MISSING KNOB, AND DRAWER ABOVE WASTE CABINET RUBS TO COUNTERTOP	145307	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~KICKPLATE AT THE BOTTOM OF BUILT IN MICROWAVE OVEN HAS ROUGH EDGES AT BOTH ENDS	145302	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~KICKPLATES - MULTIPLE NAIL HOLES SHOWING THROUGHOUT	145308	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~LEFT SIDE VANITY - CHIP ON FIRST DRAWER FLOOR CLOSE TO FRONT EDGE AND DRAWER ON THE RIGHT RUBS ON COUNTERTOP	145361	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PANTRY CABINETS- LOWER CABINETS LEFT SIDE OF POTS AND PANS DRAWERS- SCRATCH ON BOTH PANELS AND DOOR FRAME	145301	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PURCHASER CONCERNED ABOUT EXTRA GAP BETWEEN UPPER CABINETS DOOR PANELS (TO BE INSPECTED BY TRADE)	145304	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~RIGHT SIDE VANITY- RIGHT DRAWER RUBS ON COUNTERTOP AND CHIP ON THE BOTTOM CABINET FLOOR CLOSE TO FRONT	145360	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	BASEMENT BATHROOM- CABINETRY~VANITY RIGHT SIDE PANEL RUBS ON COUNTERTOP	145274	NoAppoint.	19	
22Jun22	228	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~VISIBLE NAIL HOLES SHOWING ON CROWN MOLDING THROUGHOUT	145303	NoAppoint.	19	
23Jun22	311	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- CORNER LEFT OF DISHWASHER- CHIPPED AT SIDE AND BOTTOM.	145404	06Jul22	18	
24Jun22	206	2	Heathwood Homes (Huron) Limited	6 Month	KITCHEN- Cabinets - Kitchen & Bathroom- Item #4 Cabinet base at sink to be replaced	145475	NoAppoint.	17	
24Jun22	286C-21	2	Heathwood Homes (Huron) Limited	6 Month	KITCHEN- Cabinets - Kitchen & Bathroom- Island kickplate is over cut	145466	NoAppoint.	17	
28Jun22	284C-16	2	Heathwood Homes (Huron) Limited	1 Year	MASTER ENSUITE- CABINETRY~ITEM # 6 CHIP ON COUNTERTOP NEAR EDGE ON LEFT HAND SIDE	145620	NoAppoint.	13	
28Jun22	304	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~DRAWER AT THE BOTTOM OF STOVE RUBS AND NOT CLOSING SMOOTHLY	145581	NoAppoint.	13	
28Jun22	304	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY- SINK CABINET RIGHT SIDE OF SHOWER ENTRANCE - BOTH SIDE PANELS CHIPPED ON TOP	145610	NoAppoint.	13	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
29Jun22	303	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- OTHER-DEFECTIVE DOOR IN SERVERY RIGHT DOOR AT TOP LEFT CABINET	145659	NoAppoint.	12	
29Jun22	303	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- OTHER-SCUFF ON DRAWER BELOW FUTURE MICROWAVE OVEN. SCUFF ON SHELF EDGING IN TOP CABINETS RIGHT OF HOOD FAN	145660	NoAppoint.	12	
29Jun22	303	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- OTHER-TOUCH UP PAINT ON FRONT GABLE OF ISLAND FACING GREAT ROOM	145662	NoAppoint.	12	
29Jun22	305	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY-BANK OF DRAWERS- 4TH DRAWER RUBS TO DRAWER ABOVE	145716	NoAppoint.	12	
29Jun22	305	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY-BASE CABINET- RIGHT SIDE OF BUILT IN MICROWAVE OVEN- LEFT SIDE PANEL RUBS ON BUILT IN MICROWAVE OVEN SIDE PANEL	145715	NoAppoint.	12	
29Jun22	305	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY-ISLAND- DRAWER ABOVE WASTE DRAWER RUBS TO COUNTERTOP	145717	NoAppoint.	12	
29Jun22	305	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY-VANITY ON RIGHT SIDE OF ENTRY- SINK CABINET- CHIPPED AT THE BOTTOM CLOSE TO BACK PANEL	145757	NoAppoint.	12	
29Jun22	305	2	Heathwood Homes (Huron) Limited	PDI	BASEMENT BATHROOM- CABINETRY-VANITY- TWO NAILS STICKING OUT FROM KICKPLATE	145695	NoAppoint.	12	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-BASE CABINET LEFT SIDE OF LAZY SUSAN- SHELF NOT INSTALLED MISSING AT THE TIME OF QA	145829	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-CABINET ABOVE FRIDGE- LEFT SIDE TRIM MISSING FACE FRAME AT THE BOTTOM	145830	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	BASEMENT BATHROOM- CABINETRY-EXTRA GAP BETWEEN SIDE SPLASH AND DRYWALL ON LEFT HAND SIDE	145812	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-ISLAND LEFT SIDE OF DISHWASHER OPENING- LEFT SIDE MOLDING DELIVERED NOT INSTALLED	145826	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-POTS AND PANS DRAWERS- CHIP ON FIRST AND SECOND DRAWER FLOOR CLOSE TO FRONT	145827	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-TRIM ON LEFT SIDE OF STOVE OPENING HAS MULTIPLE CHIPS AT FRONT EDGE	145828	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY-UPPER ANGLE CABINET- CHIP AND MESSY FINISH ON FACE FRAMES ON BOTH SIDES OF CABINET	145834	NoAppoint.	11	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER ANGLE CABINET- CHIPS ON BACK PANEL AS TAGGED	145833	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER ANGLE CABINET- TOP SHELF- OVERCUT ON RIGHT SIDE	145832	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER CABINET- RIGHT SIDE OF FRIDGE- CHIPPED ON BACK PANEL	145831	NoAppoint.	11	
30Jun22	278	2	Heathwood Homes (Huron) Limited	Quality Control	BASEMENT BATHROOM- CABINETRY~VANITY- RIGHT SIDE PANEL GETS STUCK TO COUNTERTOP	145811	NoAppoint.	11	
04Jul22	279	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BANK OF DRAWERS- 4TH DRAWERS RUBS ON DRAWER ABOVE	145999	NoAppoint.	7	
04Jul22	279	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BASE CABINET LEFT SIDE OF STOVE- CHIP ON ADJUSTABLE SHELF ON LEFT HAND SIDE	146001	NoAppoint.	7	
04Jul22	279	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~DRAWERS AT THE BOTTOM OF STOVE RUBS ON DRAWER ABOVE	146000	NoAppoint.	7	
05Jul22	248	2	Heathwood Homes (Huron) Limited	1 Year	KITCHEN- Cabinets - Kitchen & Bathroom- Item # 30 Island - loose trim/extra gap between molding and island at the bottom facing great room, and chipped paint in one area.	146077	NoAppoint.	12	
05Jul22	302	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- Cabinets - Kitchen & Bathroom- CABINETRY~PANTRY BESIDE FRIDGE- HANDLES DELIVERED, NOT INSTALLED	146154	14Jul22	40	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	SERVERY- CABINETRY~BASE CABINETS- CHIPS ON BOTH CABINET FLOORS, NEAR FRONT EDGE	146289	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~BUILT IN MICROWAVE OVEN- LEFT SIDE PANEL CHIPPED AT THE BOTTOM	146297	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~ISLAND LEFT SIDE OF DISHWASHER OPENING CHIPPED ALONG EDGE	146295	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PANTRY BASE CABINET RIGHT SIDE PANEL NOT CLOSING SMOOTHLY	146302	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PANTRY- VISIBLE NAIL HOLES SHOWING ON KICKPLATE	146301	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~PURCHASER CONCERNED ABOUT CROWN MOLDING NOT THE SAME COLOUR AS CABINETS (FRENDEL TO VERIFY COLOUR)	146294	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~UPPER CABINET LEFT SIDE OF FRIDGE- SCREW HOLE SHOWING ON BACK PANEL	146296	14Jul22	5	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY LEFT SIDE OF ENTRY- CABINET RIGHT SIDE OF SINK- SCREW HOLE SHOWING ON CABINET FLOOR NEAR FRONT ON LEFT HAND SIDE	146343	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY LEFT SIDE OF ENTRY- PURCHASER CONCERNED ABOUT EXTRA GAP BETWEEN VANITY DRAWERS AND BASE CABINETS	146342	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	MASTER ENSUITE- CABINETRY~VANITY LEFT SIDE OF ENTRY- SINK CABINET- SCREW HOLE SHOWING ON CABINET FLOOR ON RIGHT SIDE PANEL NEAR NEAR BOTTOM HINGE	146344	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- CABINETRY~WASTE CABINET NOT CLOSING SMOOTHLY AND RUBS, AND DRAWER ABOVE WASTE CABINET STUCK TO COUNTERTOP	146299	14Jul22	5	
06Jul22	306	2	Heathwood Homes (Huron) Limited	PDI	KITCHEN- HARDWOOD~PAINT SPLATTER ON HARDWOOD BOARDS IN FRONT OF DISHWASHER OPENING	146291	14Jul22	5	
06Jul22	309	2	Heathwood Homes (Huron) Limited	PDI	LAUNDRY ROOM- CABINETRY~COUNTERTOP SCHEDULED TO BE INSTALLED	146240	NoAppoint.	5	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- BACK GABLE FACING GREAT ROOM HAS MULTIPLE CHIPS NEAR GRANITE	146510	NoAppoint.	4	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND- MOLDING RIGHT SIDE OF SINK COMING OUT AS OPENING THE CABINET AND HAS VISIBLE NAIL HOLES	146511	NoAppoint.	4	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~LOWER CABINET RIGHT SIDE OF STOVE- RIGHT PANEL FACING BREAKFAST IS CHIPPED	146506	NoAppoint.	4	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER ANGLE CABINETS - THREE CHIPS ON FACE FRAME	146508	NoAppoint.	4	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER CABINET RIGHT OF FRIDGE- CHIP ON RIGHT SIDE PANEL FRONT EDGE, AND SCREW HOLE AND CHIP ON BACK PANEL ON UPPER SHELF	146509	NoAppoint.	4	
07Jul22	233	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER CABINETS - NOT DAP TO DRYWALL PROPERLY	146507	NoAppoint.	4	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~BANK OF DRAWERS- 4TH DRAWER - CHIP ON DRAWER FLOOR CLOSE TO FRONT	146604	14Jul22	1	

WO Date	Lot	Phase	Project	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	MAIN BATHROOM- CABINETRY~CABINET LEFT SIDE OF SINK HAS EXTRA GAP CABINET FLOOR AND RIGHT SIDE PANEL	146619	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~EXTRA GAP BETWEEN LAZY SUSAN CABINET DOOR PANELS	146603	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND - VISIBLE NAIL HOLES SHOWING ON MOLDINGS	146600	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND BACK PANEL FACING GREAT ROOM HAS CHIPS NEAR GRANITE COUNTERTOP	146601	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~ISLAND SIDE GABLE FACING BREAKFAST CHIPPED AT THE BOTTOM	146599	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~MULTIPLE NAIL HOLES SHOWING ON KICKPLATES	146602	14Jul22	1	
10Jul22	234	2	Heathwood Homes (Huron) Limited	Quality Control	KITCHEN- CABINETRY~UPPER CABINET LEFT SIDE OF HOOD FAN - EXTERIOR PANEL CHIPPED AT THE BOTTOM	146605	14Jul22	1	

Seasonal Deficiencies
For Frendel Kitchens Limited
For Heathwood Homes (Huron) Limited

Print Session: 2917 - Printed: 11Jul22