

Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864

MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769

OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315

NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516

GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522

PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315

HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 100

Lot 33 (Left) – Zenith Avenue

Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.

SOIL ENGINEERS LTD.

Dennis Lai, P.Eng. DL:vk



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

DATE: January 5, 2017

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive Cit of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: November 2, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE:

AS-BUILT ELEVATION:

WATER CONDITION:

DESCRIPTION OF INSPECTED SUBGRADE:

METHOD OF INSPECTION:

Visual

SUBGRADE:

GIVEN TO:

Bruno

1 kPa = 20.89 psf

The footings and foundation walls must be protected

against frost action at all times.



Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

HAMILTON PETERBOROUGH NEWMARKET **GRAVENHURST** MISSISSAUGA OSHAWA BARRIE TEL: (905) 777-7956 TEL: (705) 684-4242 TEL: (905) 440-2040 TEL: (905) 542-7605 TEL: (905) 440-2040 TEL: (905) 853-0647 TEL: (705) 721-7863 FAX: (905) 725-1315 FAX: (905) 542-2769 FAX: (416) 754-8516 FAX: (705) 684-8522 FAX: (705) 721-7864 FAX: (905) 542-2769 FAX: (905) 725-1315

Inspection No. 102

Lot 33 (Left) – Zenith Avenue

- Two 15-mm steel reinforcing bars have been placed continuously in the upper section of the foundation walls.

SOIL ENGINEERS LTD.

Dennis Lai, P.Eng. DL:vk



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

DATE: January 5, 2017

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive Cit of Vaughan

JOB DESCRIPTION:

Steel Reinforcing Bar Inspection

DATE OF INSPECTION: November 3, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE:

AS-BUILT ELEVATION:

WATER CONDITION:

DESCRIPTION OF INSPECTED SUBGRADE:

METHOD OF INSPECTION:

Visual

SUBGRADE:

GIVEN TO:

Bruno

 $1\ kPa = 20.89\ psf$ The footings and foundation walls must be protected

The footings and foundation walls must be protected against frost action at all times.