Lot 942 (MWI) 2208 BATTERS

Comments



FED 1 2000

## **Pre-Delivery Inspection Form**

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

## DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** · Windows, side lights and other glazing. Window and door screens Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room Mirrors, countertops and cabinetry · Exhaust fans (kitchen, bathrooms), if provided · Flooring (hardwood, vinyl, ceramic tiles, carpeting) · Electrical outlets and fixtures · Interior finishes and trim carpentry Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided · Hot water heater, if provided (not a rental) Heating system Exterior finishes, driveways, walkways, decks and landscaping are · Hot water heater, if provided (not a rental) complete · Air conditioning system, if provided and if conditions permit DOUGLAS TRUMBLE.

Commen		misc. I may .
Item #	Room/Location	Description
	EXTERIOR	BRADING, SOD, PARED DRUTENTY, PATINTING, MORGAR
		TOUCHUPS / BRICK TOUGHTUPS, EMPESTROUGHS,
		SOFFIT VEMS, DELK, SILLS, NOT COMPLETED.
2	IMERUR	PAINTON LEDAMICS (AS MINRILLED) (OVER SPRAY)
3	GARME	STEPS OR STEPS CHISSENG.
	LAVNORY	DOOR VERY SOUTEKY / TVB NOT STURED
	GREVAS ROOM	THERMOSTAT WERE TO BE MUED/RELOCATED
6	BASEMENT.	TO BE CLEANED
	DISMENT	INSULATION TO BE REPLACED & POLY READVACABLE
	Brown	GUTBLTO BECHANGED.
	BUSEMENT.	WINDOW PIN MT FRLY INSERTED
	Breward	WATER ON WEST SIDE OF FLOOR.
11	RYSEMENT	WAMPINES PORTS OF SMCKI
12	STAPPS TO BASE	MONT. PEICLE OF DRYWALL MISSING
13	UPSIVITY	USARLE PAINT LINES
	IM/ENT	SCREENS NOT INSTANCES.
15	INFERLOR.	TELEYBRE & CAPLE COURSMISSING
16	Browner	ENTERICOL BUX TO BE COMPLETED?
17	funnat	ANT GLER NOT INSTALLED
7	BEDDOOM XY	
	INTERIOR	SCREWINGSING IN ELETHOR COLERVISES
	FOYER	FLOOR VONT POLISH 'T FIT. IN CORMINGS
	POWER ROOM.	VENT HIS GOD TO CERMICS
22	SPEGT ROM.	COUNTERTOR DAMBED @ STOLE EDGE.  VEDER CABINET BUSIEN ASPENTE @ BASKE
23	KIPHEN	COUNTERTOR DAMAGED @ STOLE EDGE.
24	KURUEN	VEDEL CABINET BRUDEN ASPONTE & BACK
_		