

PDI Page 1 of 1 1832978 ITARION

Vendor/Builder#

Purchaser Name:

Angie Hopkin (705) 818-4772

Phone Bus: Closing Date: Inspector:

2013-07-04 Bruno Tidd

Enrollment# Legal Address:

Project: Plan #:

DLS[19] H Hansen Development Inc.

Lot / Phase #: Municiaplity:

SWD-00051 / I

Inspection Date: 25 Jun 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

· Windows, side lights and other glazing. Window and door screens

· Bathtub sinks and toilets

- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
   Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry

- Hot water heater, if provided (not rental)
  Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

Windows, interior and exterior doors including garage overhead doors, door locks

- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided

- Electrical outlets and fixtures
   Gas fireplaces, incl.circulation fans, if provided
   Heat Recovery Ventilation system, if provided

- Heating system
  Hot water heater, if provided (not rental)
  Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS			
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 8:10 TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. PURCHASER FEELS THAT WINDOW FRAMES COULD BE PAINTED BETTER.		
NEW TELEPHONE NUMBER	705-818-4772 CELL	 	
BEDROOM #2			
WINDOWS	SCREENS MISSING.	 	
MAIN BATHROOM			
TOILET	SHUT OFF VALVE CAP NOT FLUSH WITH FLOOR HOLE APPEARS LARGE TOO MUCH GROUT AROUND HOLE.	 	
FLOORING	CHIP IN CERAMIC TILE NEAR HALLWAY DOOR, CAULKING SLOPPY AT FRONT OF SINK.	 	
STAIRS			
DRYWALL	GAP BETWEEN CARPET AND WALL ON RIGHT HAND SIDE. LARGE GAP AT TOP. TOP AREA OF STAIRWELL NOT PAINTED.	 	
FOYER/HALL			
CLOSET	FRONT DOOR OF THE SLIDER IS STIFF.		<del></del>
FRONT DOORS	SMALL DENT ON INSIDE OF FRONT DOOR.	 	
LIVING ROOM			
FLOORING	HARDWOOD TRANSITION PIECES NOT INSTALLED TO HLLWAY AND KITCHEN.	 	
TRIM	DOOR PAINTED THINLY COULD USE SECOND COAT,	 	
GARDEN/PATIO DOORS			
NOTE:	no screen	 	
KITCHEN			
CABINETS	TWO HOLES IN BOTTOM OF SINK AND LARGE STAIN IN CABINET UNDER SINK.	 	
COUNTERTOPS	PUT DOOR STOP TRIM UNDER BOTH SIDES OF COUNTER TO HIDE SCREW HEADS.	 	•••
RANGEHOOD	FAN MAKES SLIGHT NOISE WHEN TURNED ON.	 	
BASEMENT			
NOTE:	TWO NAILS STICKING OUT OF CONCRETE	 <u>.</u> ,	-
EXTERIOR			
NOTE:	NO TAPS ON GARAGE OUTSIDE TAP AND BACK YARD TAP. DENTS IN EXTERIOR DOOR TO BACKYARD ON OUTSIDE. PAINT ON TOP PANEL OF GARAGE DOOR.	 	

THE COMPLETE	D PRE-DELIVERY INSPECTIO	N IS A FORMAL RECORI	OF THE HOME'S CO	NDITION	N BEFO	ORE TH	IE PURCI	<b>IASER</b>	TAKI	ES
POSSESSION IT V	WILL BE USED AS A REFEREI	NCE FOR FUTURE WARR	ANTY REQUESTS							_

Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder nuthorizing the designate to sign this form on their behalf.

Builder Representative

Designate's Signature

Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed

Purchaser

Date

31001-PDIF-01.01

