

Warranty Services
Phone: (905) 738-7010 Zancor North Inc.

Fax: (905) 738-5948

Glosing Date: Address:

Location: 07May20 Allegra Drive Wasaga Beach The Village of Trillium Forest - Phase: 3 - Lot: Block 125 Unit 4

Today's Date: Contact(s): Email: 28May21 Vito Rizzuto - Home: (416) 526-9543 dulariemangal@yahoo.com

Company: Wasaga Zancor Warranty Service

Attention: Telephone: Fax: (705) 428-6483 (705) 428-6484

DAI	Type	Issue	2333333333	Appt. Date/Time	Notes
143782	1 Year	Exterior- General- Item #7- Kitchen fan outside flaps too short keep falling (SVC to inspect	. pp. 1111 (and 1117)	02Jun21 /pm	Arrival time at 1pm
143784	1 Year	Foyer- General- Caulking short at rear patio door (was cut out) both right and left side	. PRINCE DO TO CONTROL OF THE PRINCE OF THE	02Jun21 /pm	Arrival time at 1pm

Homeowner Signature

Date Completed:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Trade &/or Service Tech

Date Completed:

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

	Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.
	will be

The Village of Trillium Forest - Phase: 3 - Lot: Block 125 Unit 4 **Outstanding Deficiencies**

13May21	13May21	13May21	13May21	13May21	3Way21	13May21	13May21	Date Reported
I Year	1 Year	l Year	1 Year	l Year	l Year	l Year	l Year	Туре
9	7	Φ	Un	4	w	2	300maf	Number
Foyer- General- Caulking short at rear patio door (was cut out) both right and left side	Exterior- General- Item #7- Kitchen fan outside flaps too short keep falling (SVC to inspect	Exterior- General- Item #6- Weeping holes under 4 pane family room window at rear have no mortar whatsoever full height of brick. One joint to the right of the bbq gas line under the vent the mortar has come out. Mortar touch ups required	Basement- General- Item #5- See picture 1 small section of apex; h.o concreted it requires more support, Dawn Inspected and confirm it is ok. Please review to confirm	Basement- General- Item #4- 5th joist from sidewall in basement split (plywood scabbing both sides)	Exterior- General- Item #3- See photos. Crack in corner of foundation has cracking. Please touch up	Exterior- General- Item #2- Crack above herringbone dummy window in mortar. touch up required	Other- General- Item #1- Multiple light switches are very stiff to turn on/off. Some are very stiff	Deficiency Description
Wasaga Zancor Warranty Service 143784	Wasaga Zancor Warranty Service 143782	<u>Uni-tri</u> 143781	Icon Plumbing & Heating 143780	Kingsview Carpentry 143779	Forming Contractors NC. 143778	<u>Uni-tri</u> 143777	Mykon Electric North Ltd 143776	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
02Jun21	<u>02Jun21</u>	02Jun21	02Jun21	02Jun21	02Jun21	02Jun21	02Jun21	Add Appointment
KA	A.	F	'			A	-	Item Completed
	X		M	****		1/3/	Z	Initial

Homeowner Signature:

https://bstapps.com/zancor/data/builderforms/ZanHSReportDeficiencyCheckList.php?&v... 2021-05-28

ì

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Zancor Service Technician: