

Outstanding Deficiencies Cookstown - Phase: 1 - Lot: 37

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>18Aug21</u>	Interval	16	Exterior- General- troughs at the dormer not installed	<u>Promark Aluminum LTD. 145568</u>	<u>Add</u>	<u>13Dec21</u>		
<u>22Feb22</u>	Interval	25	Main Hall- General- Year end drywall repairs	<u>Nelmag 146797</u>	<u>Add</u>	<u>21Mar22</u>		
<u>23Feb22</u>	Interval	26	Main Hall- General- Repair squeak in main hall above finished area in basement	<u>Kingsview Carpentry 146798</u>	<u>Add</u>	<u>09Mar22</u>	✓	GF
<u>23Feb22</u>	Interval	26	Main Hall- General- Repair squeak in main hall above finished area in basement	<u>Zancor Cookstown Service 146799</u>		<u>09Mar22</u>	✓	GF

Homeowner Signature: The Homeowner acknowledges and accepts that all
initialled work has been completed in a workman like
manner to their satisfaction.Date: March 9/22Zancor Service Technician: Forster