Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 5

<u>Date</u> <u>Reported</u>	<u>Type</u>	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
31Mar22	PDI	1	EXTERIOR- GARAGE DOORS~ GARAGE SLAB NOT INSTALLED	Toronto Concrete & Drain 147068	Add	NoAppoint.		A
31Mar22	PDI	2	EXTERIOR- PAINT~GARAGE DOORS NOT INSTALLED	Abbey Overhead Doors Inc. 147069	Add	NoAppoint.		1
31Mar22	PDI	3	EXTERIOR- PAINT~PAINTING NOT COMPLETE	Perfect Touch Painting 147070	Add	NoAppoint.	\times	
31Mar22	PDI	4	KITCHEN- COUNTERTOPS~REMOVED FILM AT COUNTERTOP LEFT OF SINK AT ISLAND	New Image Kitchens 147049	Add	NoAppoint.	_/	J
31Mar22	PDI	5	MASTER ENSUITE BATH- SHOWER ENCLOSURE~RIGHT FIXED GLASS NOT INSTALLED BY TUB	Metropolitan 147071	Add	NoAppoint.	\prec	
31Mar22	PDI	6	MASTER ENSUITE BATH- SHOWER ENCLOSURE~CHIP ON MARBLE SURROUND BY TUB INSIDE SHOWER AND SCRATCHES ON MARBLE SURROUND WHERE GLASS WAS REMOVED BASE / BELOW OPERATING DOOR / LEDGE INSIDE SHOWER	AV Classic 147050	Add	NoAppoint.	/	1
31Mar22	PDI	7	MAIN BATHROOM- MIRROR~MIRROR NOT INSTALLED	Metropolitan 147051	Add	NoAppoint.	X	

RCVD KEYS (ALSO GARAGE) RCVD A PDI BINDER

Homeowner Signature:	lana Name

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date:	APRILIHAD.
Zancor Service Technician:	