Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 5

<u>Date</u> Reported	Туре	Number	Deficiency Description	Trade Assigned	Add	Add Appointment Frade Date	Item Completed	Initial
31Mar22	Idd	ļus.	EXTERIOR- GARAGE DOORS- GARAGE SLAB NOT INSTALLED	Toronto Concrete & Drain 147068	Add	No Appoint.		1
31Mar22	Idd	2	EXTERIOR-PAINT-GARAGE DOORS NOT INSTALLED	Abbey Overhead Doors Inc. 147069	Add	NoAppoint		72-
31Mar22	PDI	ديا	EXTERIOR- PAINT-PAINTING NOT COMPLETE	Perfect Touch Painting 147070	Add	NoAppoint,	X	The state of the s
31Mar22	IQq	.4.	KITCHEN- COUNTERTOPS-REMOVED FILM AT COUNTERTOP LEFT OF SINK AT ISLAND	New Image Kitchens 147049	Add	No Appoint.	K	محوا
31Mu/22	PDI	Un.	MASTER ENSUITE BAIH- SHOWER ENCLOSURE-RIGHT FIXED GLASS NOT INSTALLED BY TUB	Metropolima 147071	Add	No.Appoint.	X	and the second
31Mar22	JOS	œ	MASTER ENSUITE BATH- SHOWER ENCLOSURE-CHIP ON MARBLE SURROUND BY TUB INSIDE SHOWER AND SCRATCHES ON MARBLE SURROUND WHERE GLASS WAS REMOVED BASE / BELOW OPERATING DOOR /	AV Classic 147050	Add	NoAppoint		4
31Mar22	PDI	7	MAIN BAITHROOM- MIRROR-MIRROR NOT INSTALLED	Metropolitan 147051	Add	No Appoint	×	1

POI BINDER & PUD A

Homeowner Signature: Jaman North

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: APRILINAD

Date:
Zancor Service Technician: