





**Zancor Homes (Cookstown) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 30Nov20  
**Address:** 40 Victoria St  
Cookstown, Ontario  
**Location:** Cookstown - Phase: 1 - Lot: 29  
**Today's Date:** 25Nov21  
**Contact(s):** Munice Wright - Home: (705) 220-1193 - (slewinwright@gmail.com)  
**Email:** slewinwright@gmail.com

**Company:** Medi Group  
**Attention:**  
**Telephone:** (416) 741-2737  
**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
146464 	1 Year	Exterior- General- Item #55- exterior wall cladding is missing income areas, water penetration at upper front of house gable		06Dec21 /am	
146465 	1 Year	Exterior- General- Item #56- weep holes along exterior walls are missing		06Dec21 /am	

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: May 5 2007

**Trade &/or Service Tech.**

Signature: 

Print Name: Grace

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.



# MEDI GROUP Service

WO Number : **W-080970**WO Date : **03-May-2022**Issued To : **ROBERT ULJASZ***GERALDO*

Builder : Zancor

ZAN08

Lot No : 29

Project : ZANCOR HOMES (COOKSTOWN) LTD.

Model : 5007 (A)

Directions : Cookstown

Intersection of Queen St (Hwy 89) and  
Dufferin St (south of Queen and west of

Address :

Contact :

Main Brick : Sierra Brown

Main Stone :

Accent Brick :

Accent Stone : Ryegrass Renaissance

INIT	Item	Work Description	PO	Builder Ref #
✓	1	EXTERIOR WALL CLADDING IS MISSING IN SOME AREAS, A WATER PENETRATION AT UPPER FRONT OF HOUSE GABLE		29NOV2521
				S-063096
✓	2	WEEP HOLES ALONG EXTERIOR WALLS ARE MISSING B		29NOV2521
				S-063096

*As per Roman weep holes are ok**could not locate water leak HO didnt know about water leak**Few broken sills at front of house HO sent WO in.*

Homeowner Signature

*MAY 4/22*  
Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED MAY 05 2022

*Jon*