



## Service Completion Status Report

**Zancor**

Date : Dec 6, 2022

Fax :

Phone :

**ZAN13 – ZANCOR-COUNTRY TRAILS-BRAM5-21**

Report To: N/A

Lot Number	Work Description	Status Status Date	Builder Ref #
11	RELOCATE HOOD VENT HIGHER FOR A CHIMNEY VENT. I HAVE OUR SERVICE DEPARTMENT GOING IN TOMORROW TO DO THE INSIDE PREP AND TO DRILL A PILOT HOLE FOR YOU GUYS. I PREFER NOT TO SMASH OUT ANY BRICKS OURSELVES NOTE: 4 BRICKS MOVED AND REPLACED. MULTIPLE PINHOLES REPOINTED	Completed 07/11/2022	11MAY2522 S-064557
5	DRYER VENT WAS MISSED AT THE TIME OF BRICK WORK NOTE: NEED ZANCOR TO DRILL HOLE FOR DRYER VENT. COULD NOT LOCATE WHERE DRYER VENT IS.	Completed 12/06/2022	11MAY2522 S-064557