

## **NEWMAR WINDOW MFG. INC.** ALPA LUMBER GROUP

WO # W164539 Pack Slin:207032

		RT ROAD, MISSISSAUGA, ON L4T 4G6 05) 672-1233 FAX (905) 672-1076			Service Date: Jan 05,				
Priority:	Normal		Status:	SCHEDU	LED			RELEASI	ED
BUILDER									
Customer:	N000531		City:	CALEDO	V	Re	ceived:	Aug 02, 20	022
Name:	ZANCOR CALEDON CLUB		Service Phone(s):			Tin	ne:		
Service Fax:			Site Phone:			Ord	der:	D380049-	-1
Site Fax:			Lot#:	8A		Ph	ase:		
RESIDENT	INFORMATION								
Home Owner	Name: CHRISTINE HUYHN		Address:	46 30	MINN	OCK			
Home Phone	e(s):		Work Pho		47-409-0	0713			
Cell Phone(s	): 647-408-1585		Email(s):	ch	nristineh	uynh13@g	amil.com	, ae_77@live	e.com
LINKED OF	RDER INFORMATION (D380	0049-1)							
Customer:	N000531 ZANCOR CALEDON	CLUB		Lot #:	8A				
Model:	30-03 GREYSTONE (BK)			Phase:					
SERVICE II	NSTRUCTIONS								
-DINING RO	OM- WINDOWS-RIGHT FIXED	GLASS SC	RATCHED AT EXTER	RIORDON	1E				
-FOYER/HAL	L- FRONT DOORS-GLASS IN	SERTS SH	OULD BE FROSTED						
PARTS RE	QUIRED								
LN Item Desc		Location	Specification	Size		Options			Qty
21 NEWMA COMPL	AR VINYL CASEMENT FIXED .ETED	DIN	GLASS ONLY - FIXED	18.75 X	54.75	CLR LOW	/E_ARG	BK	1
191 E130_S po 8071	TYLE DOORLITE	ENT	DOORLITES ONLY	20 X 80		E130_ST CLR CLR ACID_ET 3T/19/3T			2
Problem Des	cription:	******							
Warranty			П снав	GEABLES					
Material \$			Material \$	0					
Labour \$			Labour \$	120	Ò				
. 2			P.O.#;	-					
Cause:									
Solution:									
	di.					***			
Date Comp	oleted: 1/5/ z 3		Appro	oved:					
	Time:		Service Signa	ature:	Mu	Cha	She		

MIKE(RENO)



Priority:

BUILDER

# 32 minnock

Normal

#### NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L41 4G6 TEL, (905) 672-1233 FAX (905) 672-1076

Status:



SCHEDULED

NO # W164539

Pack Slip:207032

RELEASED

Service Date: Nov 02, 2022

Customer: N000531		City:	CALEDON	Receiv	red: Aug 02, 2022
Name: ZANCOR CALEDON CLUB		Service Phone(s):		Time:	
Service Fax:		Site Phone:		Order:	
Site Fax:		Lot#:	8A	Phase	•
RESIDENT INFORMATION					
Home Owner Name: CHRISTINE HUYHN		Address:			
Home Phone(s);		Work Pho	one(s): 647-4	109-0713	
Cell Phone(s): 647-408-1585 LINKED ORDER INFORMATION (D380	049-1)	Email(s):	christ	inehuynh13@gami	l.com, ae_77@live.com
Customer: N000531 ZANCOR CALEDON			Lot #:	8A	
Model: 30-03 GREYSTONE (BK)	0202		Phase:		
SERVICE INSTRUCTIONS			Thase.		
-DINING ROOM- WINDOWS-RIGHT FIXED	GLASS SC	RATCHED AT EXTE	RIOR JOY	$_{1}\rho$	
-FOYER/HALL- FRONT DOORS-GLASS IN	SERTS SHO	OULD BE FROSTED	- Eu		
PARTS REQUIRED			1		
LN Item Description	Location	Specification	Size	Options	Qty
21 NEWMAR VINYL CASEMENT FIXED	DIN	GLASS ONLY - FIXED	18.75 X 54.7	75 CLR LOWE_	ARG BK dono 1
191 E130_STYLE DOORLITE	ENT	DOORLITES	20 X 80	E130_STYLE	DOORLITE 2
		ONLY	Eu	CLR CLR ACID_ETCH_ 3T/19/3T	_LOW_E_ARG
Problem Description:					
Warranty		CHAR	GEABLES		
Material \$		Material \$		_	
Labour \$		Labour \$			
		P.O.#:			
Cause:					- iii.
Solution:					
Date Completed:	Zami Zami	Appro	oved:	"	
				1	
Time:		Service Signa	ature:	THARMA	1
				I HARIVIA	Bu



ANCOR Zancor Homes (Caledon) Ltd.
Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closina	and the last of th	21Jul22	
WITH CHILD IN	11 12 23 1 A SHIP		

Address:

Location:

Caledon Club - Phase: 1 - Lot: 8A

Today's Date:

14Jul22

Contact(s): Email:

Company:

Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

DAI	Туре	Issue		Appt. Date/Time	Notes
148827	PDI	DINING ROOM- WINDOWS~RIGHT FIXED GLASS SCRATCHED AT EXTERIOR	dian	Û	
148830	PDI	FOYER/HALL- FRONT DOORS~GLASS INSERTS SHOULD BE FROSTED	Done		

Date Completed: // 5/23

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.


## Caledon Club - Phase: 1 - Lot: 8A

148827 - 1 - WINDOWS~RIGHT FIXED GLASS SCRATCHED AT EXTERIOR



148830 - 1 - FRONT DOORS~GLASS INSERTS SHOULD BE FROSTED





Closing Date: 21Jul22

Address:

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Location: Foday's Date Contact(s): ≣mail:	e: 09Sep Christii Ali Ero	on Club - Phase: 1 - Lot: 8/ 22 ne Huyhn - Work: (647) 409 I - Cell: (647) 408-1585 - (ad nehuynh13@gamil.com	-0713 - (christinehuynh1)	3@gamil.com)			
Company: Attention: Felephone: Fax:	(905) 6	ar 672-1233 672-6350 Illowing items:		The state of the s			
DAI	Туре	Issue	Appt. Date/Time	Notes			
148827	PDI	DINING ROOM- WINDOWS~RIGHT FIXED GLASS SCRATCHED AT EXTERIOR	14Sep22 /day				
148830	PDI	FOYER/HALL- FRONT DOORS~GLASS INSERTS SHOULD BE FROSTED	14Sep22 /day				
Date Completed:			Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.				
Date Completed:			Trade &/or Service Tech.				
			Signature:				
			Print Name;				
Please so	chedule vo	ur Service Denartment to	complete work on the	above Lot Should no			

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

## Caledon Club - Phase: 1 - Lot: 8A

148827 - 1 - WINDOWS~RIGHT FIXED GLASS SCRATCHED AT EXTERIOR



148830 - 1 - FRONT DOORS~GLASS INSERTS SHOULD BE FROSTED

