

Outstanding Deficiencies

Belle Aire Shores - Phase: 3 - Lot: 82W

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>19Jan23</u>	PDI	1	LIVING ROOM- FLOORING~CHIP ON 7TH HARDWOOD PLANK FROM ENTRANCE TO LIVING FROM KITCHEN	<u>Belle Aire Shores Const. Service</u> 153933	<u>Add</u>	<u>NoAppointment.</u>	<input checked="" type="checkbox"/>	
<u>19Jan23</u>	PDI	2	KITCHEN- COUNTERTOPS~BACKSPLASH NOT INSTALLED	<u>AV Classic</u> 153934	<u>Add</u>	<u>NoAppointment.</u>	<input checked="" type="checkbox"/>	<u>VF.</u>
<u>19Jan23</u>	PDI	3	SHARED ENSUITE- VANITY CABINETS~CHIP AT BOTH BOTTOM RIGHT AND LEFT GABLE BELOW SINK	<u>New Image Kitchens</u> 153935	<u>Add</u>	<u>NoAppointment.</u> <u>1/26</u>	<input checked="" type="checkbox"/>	<u>VF</u>
<u>19Jan23</u>	PDI	4	UPPER HALL- FLOORING~DENT ON 5TH AND 6TH PLANK FROM LAUNDRY AT UPPER HALL	<u>First Canadian Hardware</u> 153936	<u>Add</u>	<u>NoAppointment.</u>	<input checked="" type="checkbox"/>	
<u>19Jan23</u>	PDI	5	BEDROOM #2- FLOORING~TOUCH UP SMALL CHIP ON HARDWOOD AT 10TH AND 14 PLAYING FROM WINDOW	<u>Belle Aire Shores Const. Service</u> 153937	<u>Add</u>	<u>NoAppointment.</u>		
<u>19Jan23</u>	PDI	6	MASTER ENSUITE BATH- VANITY CABINETS~CHIP AT BOTTOM LEFT GABLE 2) CHIP BOTTOM RIGHT GABLE RIGHT OF SINK BOTH RIGHT CABINETS	<u>New Image Kitchens</u> 153938	<u>Add</u>	<u>NoAppointment.</u> <u>1/26</u>	<input checked="" type="checkbox"/>	<u>VF.</u>

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 02/02/23.
Zancor Service Technician: _____