



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W173488
Pack Slip:225300

Service Date: Jan 31, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 611313 City: INNISFIL Received: Dec 01, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D380371-1
Site Fax: Lot#: 75W Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D380371-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 75W
Model: 36-07 ADMIRAL(COR)/WH/LOT 75W Phase: 3

SERVICE INSTRUCTIONS

G/H LOCKSIDE/ HALF JAMB
FLUSH BOLTS FOR FRONT DOOR *Complete*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
170	DCGH 2' 8" WOOD DOOR SYS lockside half jamb	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT DCGH 2' 8" WOOD DOOR SYS	1
190	5' 8" CLAD DOOR SYS flush bolts	ENT	OTHER RPLCMNT PARTS	72 X 97.75	WH 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1

Problem Description: *No one in truck to sign*

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ *NIC*
Labour \$ _____ Labour \$ _____
P.O.#: _____

Cause: _____

Solution: _____

Date Completed: *Jan 31/23* Approved: *8*

Time: *1 hr.* Service Signature: *[Signature]*
STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W173488

Pack Slip:225300

Service Date: Dec 05, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 611313
Name: ZANCOR BELLE AIRE SHORES
Service Fax:
Site Fax:

City: INNISFIL
Service Phone(s):
Site Phone:
Lot#: 75W

Received: Dec 01, 2022
Time:
Order: D380371-1
Phase: 3

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s):
Cell Phone(s):

Address:
Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (D380371-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES
Model: 36-07 ADMIRAL(COR)/WH/LOT 75W

Lot #: 75W
Phase: 3

SERVICE INSTRUCTIONS

G/H LOCKSIDE/ HALF JAMB
FLUSH BOLTS FOR FRONT DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
170	DCGH 2' 8" WOOD DOOR SYS lockside half jamb	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT DCGH 2' 8" WOOD DOOR SYS	1
190	5' 8" CLAD DOOR SYS flush bolts	ENT	OTHER RPLCMNT PARTS	72 X 97.75	WH 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1

Problem Description:

NO TIME

☐ Warranty

Material \$ _____
Labour \$ _____

☐ CHARGEABLES

Material \$ _____
Labour \$ _____
P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

ALEX



Melissa Green <mgreen@newmar.com>

Fwd: Lot 75 front door

1 message

Nathan Simas <nathan@zancorhomes.com>
To: Melissa Green <mgreen@newmar.com>

Fri, Dec 2, 2022 at 10:21 AM

Hey Melissa can we get this done too when they come to fix the jambs

Thanks,

Nathan Simas
Finishing Supervisor
Now Towns in Brooklin / Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com

From: Nathan Simas
Sent: Friday, December 2, 2022 10:18:06 AM
To: Service Department <servicedept@newmar.com>
Subject: Lot 75 front door

Fixed door pins not lining up with holes in threshold/ jamb

Thanks,

Nathan Simas
Finishing Supervisor
Now Towns in Brooklin / Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com



processed-dcfae8d7-109e-49ee-8087-efd92afc515b_j6HzKvVx.jpeg
910K