

Alexandria

Zancor Homes (Parkview) Ltd.
Warranty Services

1: 272: (905) 738-7010

Fax: (905) 738-5948

Work Order

Civic - 29/2 carnwith Drive

Now Tow 13Feb23	ns In Brooklin - Phase: 1			
Vmahzou VIP Raill (905) 669	ni@yahoo.com ngs Inc. I-9666			
` '				
Туре	Issue		Appt. Date/Time	Notes
Emergen	Stairs- General- railing came apart from newel post upper floor			
Interval	Stairs- General- cracked nosing at upper hall below pickets			
Date Completed:		Homeowner Signature: The Homeowner acknowledges and accepts all wo has been completed in a workman like manner.		
COMPLETED		Trade &/or Service Tech. Signature: Print Name:		
	Now Tow 13Feb23 Valentina Vmahzou VIP Railli (905) 669 (905) 669 (905) 669 Emergen cy Interval	Valentina Azarm Djahedi - Cell: (289 Vmahzouni@yahoo.com VIP Railings Inc. (905) 669-9666 (905) 669-9450 Plete the following items: Type Issue Emergen cy Stairs- General- railing came apart from newel post upper floor Interval Stairs- General- cracked nosing at upper hall below pickets Pleted: E-MAILED FEB 1 5 2023	Now Towns In Brooklin - Phase: 1 - Lot: Unit 13Feb23 Valentina Azarm Djahedi - Cell: (289) 387-400 Vmahzouni@yahoo.com VIP Railings Inc. (905) 669-9666 (905) 669-9450 Plete the following items: Type	Now Towns In Brooklin - Phase: 1 - Lot: Unit 53 (Block 9: 13Feb23 Valentina Azarm Djahedi - Cell: (289) 387-4001 - (Vmahzou Vmahzouni@yahoo.com VIP Railings Inc. (905) 669-9666 (905) 669-9450 Plete the following items: Type

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 53 (Block 9)

154590 - 1 - IMG_9842 - railing came apart from newel post upper floor



154595 - 1 - IMG_9848 - cracked nosing at upper hall below pickets

