

Outstanding Deficiencies
Belle Aire Shores - Phase: 3 - Lot: 40W

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
15Dec22	PDI	2	EXTERIOR- NOTE--CAULKING REQUIRED AT EXTERIOR LEFT DOOR AT BOTTOM TRIM	CJ Caulking 153206	Add	No Appointment	✓	
15Dec22	PDI	4	EXTERIOR- NOTE--CAULKING REQUIRED AT VENT ON RIGHT SIDE OF HOUSE BY DOWNSPOUT	CJ Caulking 153288	Add	No Appointment	✓	
15Dec22	PDI	5	EXTERIOR- NOTE:--TWO HOLES ON RIGHT SIDE OF HOUSE IN BETWEEN DINING WINDOWS SPRAY FORMED REQUIRED BRICK	River Valley Masonry Group LTD. 153289	Add	No Appointment	Seasonal	
15Dec22	PDI	6	EXTERIOR- NOTE--FLASHING ABOVE LIVING ROOM WINDOW AT REAR OF HOME NOT COMPLETE	Promark Aluminum LTD. 153290	Add	No Appointment	✓	
15Dec22	PDI	8	EXTERIOR- NOTE:--CAP NOT INSTALLED LEFT AT FRONT DOOR AT EAVESTROUGH ABOVE GARAGE	Promark Aluminum LTD. 153208	Add	No Appointment	✓	
15Dec22	PDI	9	EXTERIOR- SHINGLES--FLASHING ABOVE LEFT GARAGE DOOR AT BRICK MESSY	Trudel & Sons Roofing LTD. 153209	Add	No Appointment	Seasonal	
15Dec22	PDI	10	EXTERIOR- PAINT--EXTERIOR PAINTING NOT COMPLETE	Perfect Touch Painting 153210	Add	No Appointment	Seasonal	
15Dec22	PDI	12	SHARED ENSUITE- COUNTERTOPS--CHIP ON LEFT AND RIGHT SIDE SPLASH	New Image Kitchens 153212	Add	No Appointment		
15Dec22	PDI	14	SHARED ENSUITE- VANITY CABINETS--CHIP AT BOTTOM RIGHT GABLE BELOW RIGHT SINK 2) CHIP AT KICKPLATE BELOW LEFT SINK	New Image Kitchens 153214	Add	No Appointment		
15Dec22	PDI	16	MASTER ENSUITE BATH- COUNTERTOPS--CHIP AT LEFT SIDE SPLASH	New Image Kitchens 153216	Add	No Appointment		
15Dec22	PDI	18	MASTER ENSUITE BATH- NOTE--CHIP AT BOTTOM RIGHT GABLE RIGHT OF SINK 2) ADJUST DRAWER INSIDE BOTTOM RIGHT CABINET 3) SCRATCH ON SIDE CABINET GABLE	New Image Kitchens 153218	Add	No Appointment		
15Dec22	PDI	19	FOYER/HALL- FRONT DOORS--DENT ON	Zancoor Construction/Labour	Add	No Appointment		

