



Zancor Homes (Caledon) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 23Feb23

Address:

Location: Caledon Club - Phase: 1 - Lot: 141A

Today's Date: 03Feb23

Contact(s):

Email:

Company:

Newmar

Attention:

Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
154387	PDI	LIVING ROOM- WINDOWS~SCRATC H ON 2ND FIXED WINDOW RIGHT OF OPERATING		
154391	PDI	FOYER/HALL- NOTE::~AS PER HOMEOWNER INSPECT GAP AT MAN DOOR VERY LARGE		
154399	PDI	MASTER ENSUITE BATH- NOTE::~INSPECT SCREEN AT OPERATING WINDOW FOR BOW		

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W177787
Pack Slip: 214089
Service Date: Mar 17, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531

Name: ZANCOR CALEDON CLUB

Service Fax:

Site Fax:

City: CALEDON

Service Phone(s):

Site Phone:

Lot#: 141A

Received: Feb 06, 2023

Time:

Order: D383566-1

Phase:

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s):

Cell Phone(s):

Address:

Work Phone(s):

Email(s):

LINKED ORDER INFORMATION (D383566-1)

Customer: N000531 ZANCOR CALEDON CLUB

Model: 38-04 GRANVIEW (RR UPG)/LOT 141A

Lot #: 141A
Phase: 140 PETCH

SERVICE INSTRUCTIONS

LIVING ROOM- WINDOWS-SCRATCH ON 2ND FIXED WINDOW RIGHT OF OPERATING
FOYER/HALL- NOTE:-AS PER HOMEOWNER INSPECT GAP AT MAN DOOR VERY LARGE
MASTER ENSUITE BATH- NOTE:-INSPECT SCREEN AT OPERATING WINDOW FOR BOW

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
12	NEWMAR VINYL CASEMENT FIXED SCRATCH ON 2ND FIXED WINDOW RIGHT OF OPERATING	RG7/ LIV/DIN	GLASS ONLY - FIXED	18.75 X 54.75	CLR LOWE_ARG DW	2
91	NEWMAR VINYL CASEMENT SCREEN AT OPERATING WINDOW FOR BOW	ENS	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 43.125		1
120	2' 8" WOOD DOOR SYS INSPECT GAP AT MAN DOOR VERY LARGE	GAR	OTHER RPLCMNT PARTS	35.25 X 97.75	61316 FJ LEFT 2' 8" WOOD DOOR SYS	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$ 915

Labour \$ 120

P.O.#:

Cause:

NOTE: REAR PATIO DOOR SCREEN NEEDS TO BE REPLACED.

Solution:

CHANGE MAN DOOR DOOR NEEDS TO BE ADJUSTED - NOT
ABLE TO ADJUST DUE TO H.O. NEWER HARD
APPOINTMENT.

Date Completed: MARCH 17, 2023

Approved:

Signature

Time:

Service Signature:

Signature