## Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 163

	16Feb23	30Jan23	23Jan23	23Jan23	23Jan23	23Jan23	23Jan23	23Jan23	<u>Reported</u>
	Interval	Interval	PDI	PDI	PDI	PDI	PDI	PDI	Туре
	ω	1	7	6	y,	4	ω	2	Number
	Master Ensuite- General- Toilet not flushing properly. Not enough water flow	Dining Room- General- REPLACE SCREEN	Laundry Room- General- install base and upper cabinets	Kitchen- General- require sliding door screen	Kitchen- General- chips at hood fan and dap above at brown (other tups marked w/ tape)	Kitchen- General- gouge at bottom p&p's drawer at facing	Kitchen- General- replace drawer at bank of drawers (2nd from top)	Kitchen- General- filler short to wall left of wine fridge opening and right of pantry	Deficiency Description
	Nota Plumbing & Heating Inc. 154629	<u>Newmar</u> 154210	New Image Kitchens 153959	<u>Newmar</u> 153958	New Image Kitchens 153957	New Image Kitchens 153956	New Image Kitchens 153955	New Image Kitchens 153954	Trade Assigned
	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
	<u>24Feb23</u>	NoAppoint.	27Mar23	NoAppoint.	27Mar23	27Mar23	27Mar23	27Mar23	Add Appointment
THE WAY	SA SA		<b>%</b>	<	X	$\times$	×	×	Item Completed
(			De la companya de la	MON					Initial

POTRAILER-

Hom	
leowne	
r Sign	
ature:	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date:

Zancor Service Technician:

MSTRENS-SILLONI FRUACE GLOBE IN KITCHEN AUNDRY - NISTAN FRUET & THE STEEL SILLIANE SINK. TO FROSTED GLASS