Inspector: Gisella Flore

Page 1 of 2

Inspector: Gisella Flore

Page 1 of 2

Inspector Date: March 21, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items selected under, the Agreement of Purchase and Sales (APS), Please initial all changes and deletions. As a minimum, check the following: Enrollment: Purchaser Name: Phone Res: Phone Bus: Closing Date: : (416) 315-2779 : June 02, 2022 Irina Pollova Sergiy Fedorenko ANCOR HOMES Vendor / Builder: Project: Lot / Phase: Plan: Address: Zancor Homes (Wasaga) Ltd 170 / 1

- DAMAGED, INCOMPLETE OR MISSING

  Windows, side lights and other glazing. Window and door screen:
  Bathtub sinks and toilets
  Bathroom accessories if provided
  Mirrors, counter tops and cabinetry
  Flooring (hardwood, vinyl, ceramic tiles, carpeting)
  Interior finished and tim carpentry

- Furnace
  Hot water heater, if provided (not rental)
  Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

  Windows, Interior and exterior doors. Door locks
  Faucets: Kitchen, bathroom, laundry room
  Exhaust fans (kitchen, bathrooms) if provided
  Electrical outlets and fixtures
  Gas freplaces, incl.circulation fans, if provided
  Heat Recovery Ventilation system, if provided

- Heating system

  Hot water heater, if provided (not rental)

  Air conditioning system, if provided and if co

MASTER ENSUITE BATH	47	
MIRROR	FROSTED GLASS DOOR REQUIRED AT PER EXTRAS 2) CONFIRM FROSTED GLASS PANE AT	
VANITY CABINETS	SWALL CHIP INSIDE BOTTOM RIGHT CABINET BELOW SINK AT GABLE	200
LIVING ROOM		14510
NOTE:	ADJUST RIGHT OPERATING WINDOW	
KITCHEN		
CABINETS	UPPER RIGHT CABINET NOT INSTALLED ABOVE FRIDGE 2) SCRATCH INSIDE CABINET ON UPPER SHELF LEFT OF HOODFAN CHIPPED 3) SCRATCH ON BACK PANEL AT UPPER CABINET	
	SINK LEAKING UNDER CABINET LEFT SIDE AT DRAIN.	> KK D
WINDOWS	ADJUST WINDOW IN KITCHEN AREA LEFT OF SLIDING DOOR 2) SCREEN DOOR NOT INSTALLED AT SLIDING DOOR 3) INSPECT SCRATCHES ON SLIDING DOOR AND ADJUST SLIDING	\
EXTERIOR		
GARAGE DOORS	WEATHERSTRIPPING NOT INSTALLED ON GARAGE DOORS. 2)ADJUST LEFT GARAGE DOOR NOT CLOSING.	
NOTE:	MOVE LIGHT FIXTURE LEFT SIDE OF GARAGE OVER CLOSER TO GARAGE TRIM RIGHT	
FOYER/HALL		
STAIRS 7	LARGE GAP BETWEEN STRINGER AND HISER AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR AT	
ţ	HARDWOOD AT STAIRS TO MAIN FLOOR NOT DONE.	
	F	

riomeowner Signature:

PRONE

The Homeowner acknowledges and accepta that all initialed work has been completed in a workman like manner to their satisfaction:

ADVISE TRADES TO BOOK FOR ARRID.

FOYER & BOUT NOSING REQUIRES VARNISH.



The above items were received on this b day of ARIL. 2023	N/A_ Other	_N/A Recycling and Green Bins	Homeowner Manual (given at PDI)	—✓— House and Garage Door Keys	Lot # /70 Site/Phase: Shoreline Point	The items listed below were released to the homeowner(s) of
(b)						

Purchaser

Purchaser