Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 154

Date Reported	<u>Type</u>	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
10Mar23	PDI	1	EXTERIOR- NOTE:~HOUSE NUMBER NOT INSTALLED AT HOUSE	Assign				X
10Mar23	PDI	2	EXTERIOR-PAINT-PAINT NOT COMPLETE AT EXTERIOR GARAGE DOOR -SEASONAL-	Perfect Touch Painting 155080	Add	NoAppoint.		×
10Mar23	PDI	3	EXTERIOR-GARAGE DOOR NOT INSTALLED COWING WED MARCH 15	Abbey Overhead Doors Inc. 155081	Add	NoAppoint.		X
10Mar23	PDI	4	UPPER HALL- FLOORING~INSPECT HARDWOOD HUMP LEFT OF UPPER RAILING INFRONT LINEN CLOSET	First Canadian Hardwood 155082	Add	NoAppoint.		\times
10Mar23	PDI	5	FOYER/HALL- STAIRS~FILL GAP BETWEEN NOISING AT HARDWOOD AT 2ND FLOOR	VIP Railings Inc. 155083	Add	NoAppoint.		\times
10Mar23	PDI		FOYER/HALL- STAIRS~FILL GAP AT RISER AND TREAD BELOW NOSING AT 2ND FLOOR AND STAIRS FROM LANDING TOP 2ND FLOOR ALL TREADS	<u>Stairfab</u> 155084	Add	NoAppoint.		X
10Mar23	PDI		MASTER ENSUITE BATH- VANITY CABINETS~CHIPS AT KICKPLATE BELOW VANITY 2) SCRATCH ON BOTTOM RIGHT AND LEFT CABINET BELOW RIGHT SINK	New Image Kitchens 155085	Add	NoAppoint.		X
10Mar23	PDI	8	KITCHEN- CABINETS~SEAM AT CROWN MOULDING TO BE JOINT OR PAINTED BETTER ABOVE HOOD FAN RIGHT SIDE 2) SEAM LEFT OF HOODFAN AT CROWN MOULDING YELLOW- TO BE RE PAINTED 3) CHIP AT TOP DRAWER RIGHT OF STOVE	New Image Kitchens 155086	Add	NoAppoint.		×
10Mar23	PDI	9	KITCHEN- NOTE:~INSTALL SOAP DISPENSER SEE PHOTO THURS WARCH VO	Redstone Marble 155087	Add	NoAppoint.		X

FILLER ABOVE FRONT DOORS	
ADD ADJUST GIMD FEEL DRAFT - PETER. — LEAVE SOME BROWN REGISTERS AS A	^ - <i>b</i>
- LEAVE SOME BROWN REGISTERS AS A	COURTESY
LEAVE SOME BROWN REGISTERS AS A BOUNT BOOK-COMP PATCH & PAINT.	
LEATH BATH-HAN ROUST	_
LPANTRY-INSTALL BLANK PLATE GARAGE.	MAMES

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: MAR 14 23

Zancor Service Technician: