

REPRINT 1

BUILDER:

Zancor Homes

JOB SITE:

Caledon Club

Customer Code:

Job Number:

18338

Board Area:8

COMPLAINT DATE: 11/17/22

LOT:

57A

INSTALLER:

GERRY

SCHEDULED DATE: 02/24/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

E-MAIL

REPAIRMAN:

BUILDER PO#:

Gerry Cody

BUILDER WO#

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#: 704755

REPAIR DESC:

BEDROOM #4- FLOORING~BUBBLE IN CARPET IN CLOSEST RIGHT SIDE

BEDROOM 2 ENSUITE FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO BATH

MASTER BEDROOM FLOORING~TUCK CARPET HUMP IN FLOOR NOT TIGHT

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE

DATE:

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT























INSTALLER SIGNATURE

DATE



INSTALLER	

CUTTING SHEET COPY

							IIIOIALL	
BUILDER Zancor Homes			PROJECT/JOB SITE	ub		JOBID 193	ВЗ8 pb210232	
ADDRESS/MAJOR INTERSECTION:			LOT/LOCATION:	ub		CUST:	:	
Caledon			57A			ZAI	NC20	
CONTACT:			MODEL/OPTIONS: 30-5-A,B,C					
BOOKED DATE INSTALL DATE 12-Oct-22 SUPPLIER: P.O. NUMBER								
		P.O. NUMBER			P.O. DUE (P.O. DUE DATE		
BOARD: 8 - GTA		work type: Residential			ORDER REF: SALES PERSON:			
RÒOM	UNDERPAD	Carpet [COLOUR]		SIZE	NOTES			
Bed 2	PK:30790 PLUS	PK:22284 Opening Night/TXP140 [21]						
Bed 3	PK:30790 PLUS	PK:22284 Opening Night/TXP140 [21]						
Bed 4	PK:30790 PLUS	PK:22284 Opening Night/TXP140 [21]						
Master Bed	PK:30790 PK:22284 Opening		Night/TXP14	0 [21]				
Carpet Accessories		PK:5845 Transition LS40D - 0" -3/8" 4ft L box 20' 5 pieces [LS40D]				4		
							-	
INSTALLER NOTES SKETCH ATTACHED		BASE	LABOUR	TOTAL	YARDS			
			MOULDINGS		C.O.D.	C.O.D.		

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT





















INSTALLER SIGNATURE

DATE


HEAD PROTECTION CLASS A CLASS B Flammable and combustible material

CLASS C Oxidizing material

CLASS D
Materials causing Bio hazardous immediate and serious toxic effects Infectious Material serious toxic effects Infectious Material serious toxic effects Infectious Material serious toxic effects Infectious Material

CLASS E Corrosive Material

CLASS F Dangerously Reactive Material





REPRINT 1

BUILDER:

Zancor Homes

JOB SITE:

Caledon Club

Customer Code:

Job Number:

18338

Board Area:8

COMPLAINT DATE: 11/17/22

LOT:

INSTALLER:

GERRY

57A

SCHEDULED DATE: 02/24/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

E-MAIL

REPAIRMAN:

Gerry Cody

BUILDER WO#

NO

BUILDER PO#:

PO Required:

NO

Inspection Reqd:

ORIGINAL WO#:

704755

REPAIR DESC:

BEDROOM #4- FLOORING~BUBBLE IN CARPET IN CLOSEST RIGHT SIDE

BEDROOM 2 ENSUITE FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO BATH

MASTER BEDROOM FLOORING~TUCK CARPET HUMP IN FLOOR NOT TIGHT

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE:

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

















INSTALLER SIGNATURE